

**App. B:**  
**Petrie Decl., Ex. 2**  
**Part I**

Confidential

ID	Model	RAMAC	Cal./Ga.	DOM	OBS	C	D/O	D/C	ALLEGED	CAUSE	RE#	P	Resolution	
7470	600	n/a				Y	S	8-Mar-12	29-Dec-12	Fired on Safe Release	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
7473	700	84371	308 WIN	25-Jan-10	N	S	9-Mar-12	9-Mar-12	Fired on Safe Release	Could Not Duplicate Concern	261242	F	Per Ilion, to restore confidence in the rifle will replace, check over and test at no charge	
7474	700	n/a	270 WIN	1-Nov-71	N	S	9-Mar-12	9-Mar-12	Fired on Bolt Closing	Improper Maintenance	261183	F	Per Ilion, replace TPA, clean and test under BLSM program price	
7475	700	27255	300 WSM	20-Jun-06	N	S	9-Mar-12	9-Mar-12	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	261173	F	Per Ilion, replace TPA, clean, test at 1/2 normal cost	
7476	700	25859	3006 SPRG	1-Nov-95	N	S	9-Mar-12	9-Mar-12	Safety not working properly	Could Not Duplicate Concern	261126	F	Per Ilion, offer to replace TPA, clean, test at 1/2 normal cost	
7477	700	n/a	243 WIN	1-Apr-69	N	S	9-Mar-12	9-Mar-12	Fired on Bolt Closing	Could Not Duplicate Concern	261003	F	Per Ilion, offer to replace TPA, clean and test fire at BLSM program price	
7478	700	85370	223 REM	13-Jul-09	N	S	12-Mar-12	12-Mar-12	Fired on Safe Release	Could Not Duplicate Concern	261360	F	Per Ilion - Replace TA, clean & test fire - warranty	
7480	700	26035	3006 SPRG	15-May-97	N	S	13-Mar-12	13-Mar-12	Fired on Safe Release	Could Not Duplicate Concern	261547	F	Per Ilion, can offer to replace TPA, clean, test fire at 1/2 normal cost	
7481	700	n/a	243 WIN	1-Mar-67	N	S	13-Mar-12	13-Mar-12	Fired on Safe Release	Altered Adjustments or Components	261535	F	Per Ilion, replace TPA, clean and test under BLSM program price	
7482	700	n/a	270 WIN	1-Jun-74	N	S	13-Mar-12	13-Mar-12	Fired on Safe Release	Altered Adjustments or Components	261544	F	Per Ilion, replace TPA, clean, test at BLSM program price	
7483	710	27408	270 WIN	14-Feb-05	Y	S	13-Mar-12	13-Mar-12	Safety not working properly	Could Not Duplicate Concern	261474	F	Return as received.	
7487	710	27412	7MM REM MA	9-Jun-06	Y	S	15-Mar-12	15-Mar-12	Fired With Safe ON	Could Not Duplicate Concern	261290	F	Per Ilion - Replace w/85635 - M/770, 7MM REM MAG @ n/c	
7488	700	n/a	300 RUM	1-Mar-99	N	S	15-Mar-12	15-Mar-12	Fired on Bolt Closing	Altered Adjustments or Components	261747	F	Per Ilion - Quote to repair	
7489	700	25777	7MM MAG		N	S	15-Mar-12	29-Dec-12	Fired on Bolt Closing	Other - Unexamined	n/a	F	Gun not returned to Ilion for exam	
7490	700	n/a	243 WIN	26-May-77	N	S	15-Mar-12	19-Jun-13	Fired on Safe Release	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam	
7492	700	n/a	270 WIN	1-Oct-76	N	S	16-Mar-12	16-Mar-12	Fired on Safe Release	Improper Maintenance	261422	F	Per Ilion - Quote to repair under BLM	
7494		n/a	223 REM		N	S	16-Mar-12	29-Dec-12	Fired on Bolt Closing	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam	
7495	600	n/a	308 WIN	21-Apr-77	N	S	19-Mar-12	19-Mar-12	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	261375	F	Per Ilion - Repair @ n/c - recall	
7496	700	n/a	7MM STW	1-Apr-99	N	S	19-Mar-12	19-Mar-12	Fired on Bolt Opening	Altered Adjustments or Components	262249	F	Per Ilion - Quote to repair	
7497	700	27488	7MM08 REM	9-Jan-97	N	S	19-Mar-12	19-Mar-12	Fired on Safe Release	Improper Maintenance	262262	F	Per Ilion - Quote to repair	
7500	1100	n/a	12 GA		N	S	19-Mar-12	19-Mar-12	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	262095	F	Per Ilion - Quote to repair	
7501	700	n/a	3006 SPRG	1-Feb-70	N	S	19-Mar-12	19-Mar-12	Fired on Bolt Closing	Could Not Duplicate Concern	261932	F	Per Ilion - Quote to repair under BLM	

RAC001129

## Confidential

7502	700	n/a	7MM REM MA	1-Jul-70	N	S	19-Mar-12	19-Mar-12	Safety not working properly	Could Not Duplicate Concern	261937	F	Per Ilion - Quote to repair @ a discount
7507	700	29708	270 WIN	27-Aug-92	N	S	20-Mar-12	12-Apr-12	Fired on Safe Release	Could Not Duplicate Concern	264605	F	Per Ilion - Quote to repair
7510	700	85351	223 REM	16-Aug-07	N	S	21-Mar-12	21-Mar-12	Fired on Safe Release	Altered Adjustments or Components	262443	F	Per Ilion - Quote to repair
7512	552	25594	22 RF	11-Nov-09	N	S	21-Mar-12	24-Apr-12	Blowback in Face	Case Separation	262451	F	Refunding for rifle
7513	700	n/a	222 REM	1-Apr-72	N	S	21-Mar-12	21-Mar-12	Fired on Bolt Closing	Altered Adjustments or Components	262452	F	Per Ilion, replace TPA, clean, test at BLSM program price
7515	700	n/a	308 WIN	1-Feb-74	N	S	22-Mar-12	22-Mar-12	Fired on Bolt Closing	Altered Adjustments or Components	262074	F	Per Ilion, replace TPA, clean and test fire at BLSM program price
7516	SPT 78	26160	308 WIN	1-Dec-84	Y	S	22-Mar-12	22-Mar-12	Delayed Firing - Firearms	Improper Maintenance	262688	F	Per Ilion, replace TPA, clean, test fire at 1/2 normal cost
7518	700	n/a	35 WHELEN	1-Jan-99	N	S	22-Mar-12	22-Mar-12	Fired on Safe Release	Improper Maintenance	262621	F	Per Ilion, replaced fire control, mag parts, tested at no charge
7523	700	n/a	3006 SPRG	12-Jun-78	N	S	26-Mar-12	26-Mar-12	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	262844	F	Replace TPA, clean, test at BLSM
7524	700	29694	300 WIN MA	22-Jun-95	N	S	26-Mar-12	26-Mar-12	Fired on Bolt Closing	Could Not Duplicate Concern	262955	F	Per Ilion, can offer to replace TPA, clean, test at 1/2 normal cost
7528	770	85651	243 WIN	27-Oct-10	N	S	27-Mar-12	27-Mar-12	Jar-Off - No Mention of Safety Position	Could Not Duplicate Concern	262767	F	Per Ilion, can replace TPA, clean, test fire to restore confidence at no charge
7529	700	n/a	7MM REM MA	1-Aug-85	N	S	27-Mar-12	12-Apr-12	Fired on Safe Release	Could Not Duplicate Concern	264941	F	Per Watkins, replace TPA no charge
7530	700	n/a	222 REM	1-Sep-62	N	PD/S	27-Mar-12	17-Apr-12	Fired on Safe Release	Could Not Duplicate Concern	264457	F	Quote to repair under BLM
7532	700	n/a	22-250 REM	1-Jan-66	N	S	27-Mar-12	11-Apr-12	Fired on Safe Release	Altered Adjustments or Components	264455	F	Per Ilion - Quote to repair under BLM
7538	700	27315	7MM RUM	13-Jul-11	N	S	29-Mar-12	29-Mar-12	Jar-Off - No Mention of Safety Position	Altered Adjustments or Components	262957	F	Per Ilion - Replace TA @ n/c - warranty
7539	700	27319	3006 SPRG	19-Jun-03	N	S	29-Mar-12	29-Mar-12	Fired on Safe Release	Improper Maintenance	263023	F	Per Ilion - Quote to repair
7540	700	n/a	308 WIN	14-May-80	N	S	29-Mar-12	29-Mar-12	Fired on Safe Release	Altered Adjustments or Components	263376	F	Per Ilion - Quote to repair under BLM
7541	770	85634	308 WIN	6-Apr-10	N	S	29-Mar-12	29-Dec-12	Fired on Safe Release	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
7542	700	n/a	6MM REM	1-Dec-71	N	PD/S	29-Mar-12	17-Apr-12	Fired on Safe Release	Could Not Duplicate Concern	264311	F	Replace TA @ n/c - goodwill gesture
7544	870	25077	12 GA	28-Oct-11	N	S	29-Mar-12	12-Apr-12	Defective Parts	Could Not Duplicate Concern	264594	F	Per Ilion - Check over completely, repair as needed, test @ n/c - warranty
7545	700	n/a	3006 SPRG	13-Sep-80	N	S	30-Mar-12	30-Mar-12	Improper Safety Design	Improper Maintenance	263222	F	Per Ilion, replace TPA, clean, test fire at BLSM program price
7549	700	27496	308 WIN	21-Jan-97	N	S	2-Apr-12	2-Apr-12	Unexplained Discharge Safe OFF	Could Not Duplicate Concern	263592	F	Per Ilion - Quote to repair
7550	700	n/a	308 WIN	8-Jul-75	N	S	2-Apr-12	2-Apr-12	Fired on Safe Release	Could Not Duplicate Concern	263520	F	Per Ilion - Quote to repair under BLM
7553	721	n/a	3006 SPRG	1-Oct-56	Y	S	2-Apr-12	20-Apr-12	Fired on Safe Release	Improper Maintenance	265253	F	Per Ilion - Quote to repair under BLM

RAC001130

## Confidential

7556	887	82500	12 GA	8-Dec-09	N	S	3-Apr-12	3-Apr-12	Safety not working properly	Could Not Duplicate Concern	263688	F	Per Ilion, check over completely, repair no charge as goodwill	
7558	700	n/a	270 WIN	29-Sep-76	N	S	4-Apr-12	4-Apr-12	Fired on Safe Release	Could Not Duplicate Concern	263751	F	Per Ilion - Quote to repair under BLM	
7561	700	n/a	7MM REM	MA	7-Nov-75	N	S	5-Apr-12	5-Apr-12	Fired on Safe Release	Could Not Duplicate Concern	263874	F	Per Ilion - Quote to repair under BLM
7571		20000	22 LR		N	Pl/S	9-Apr-12	22-Jun-12	Excessive Report	Other - Unspecified or Undetermined - Ammunition	n/a	A	Lonoke refunded for ammo Gun not returned to Ilion for exam	
7572	597	26536	22LR	23-May-03	N	S	9-Apr-12	29-Dec-12	My Gun Blew Up	Not Examined by Product Service	n/a	F	Per Ilion - Quote to repair under BLM	
7563	700	25709	308 WIN	19-Dec-05	N	S	10-Apr-12	10-Apr-12	Fired on Safe Release	Could Not Duplicate Concern	264237	F	Per Ilion - Repair @ n/c under BLM	
7564	600	n/a	308 WIN	1-Mar-64	Y	S	10-Apr-12	10-Apr-12	Fired on Safe Release	Could Not Duplicate Concern	264222	F	Per Ilion - Repair @ n/c under recall	
7565	700	n/a	3006 SPRG	1-Feb-75	N	S	10-Apr-12	25-Apr-12	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	265527	F	Per Ilion, replace TPA, clean, test at BLSM price	
7576	700	n/a	3006 SPRG	13-May-80	N	S	11-Apr-12	19-Jun-13	Fired on Safe Release	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam	
7578	887	82500	12 GA	26-Aug-09	N	S	12-Apr-12	12-Apr-12	Fired Out of Battery	Could Not Duplicate Concern	264534	F	Per Ilion, adjust as needed at no charge under warranty	
7579	700	n/a	7MM REM	MA	1-Mar-68	N	S	12-Apr-12	12-Apr-12	Fired on Safe Release	Altered Adjustments or Components	264582	F	Replace TPA, clean, test at BLSM program price
7583	700	n/a			N	PD/S	13-Apr-12	13-Apr-12	Fired on Safe Release	Other - Unexamined	n/a	O	Customer sold the rifle - no name or address of new owner	
7584	700	n/a	2506 REM	1-Mar-67	N	S	16-Apr-12	16-Apr-12	Fired on Safe Release	Improper Maintenance	264815	F	Per Ilion - Quote to repair under BLM	
7585	700	25616	7MM/08 REM	13-Aug-90	N	S	16-Apr-12	16-Apr-12	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	264774	F	Per Ilion - Quote to repair under BLM	
7587	700	25634	30-06 SPRG	22-Apr-86	N	S	16-Apr-12	1-May-12	Fired on Safe Release	Could Not Duplicate Concern	266119	F	Per Ilion, replace TPA, clean, test at no charge	
7588	700	85434	22-250 REM	10-Aug-10	N	S	17-Apr-12	17-Apr-12	Blowback in Face	Could Not Duplicate Concern	264922	F	Per Ilion, repair as needed at no charge	
7590	700	25815	7MM REM MA	7-Sep-04	N	S	18-Apr-12	18-Apr-12	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	265040	F	Per Ilion - Quote to repair under BLM	
7591	700	n/a	3006 SPRG	1-Apr-66	N	S	18-Apr-12	18-Apr-12	Fired on Safe Release	Could Not Duplicate Concern	265014	F	Per Ilion - Quote to repair under BLM	
7593	700	27502	7MM STW	8-Jan-98	N	S	19-Apr-12	19-Apr-12	Fired on Safe Release	Could Not Duplicate Concern	265144	F	Per Ilion - Quote to repair under BLM	
7594	700	n/a	3006 SPRG	1-Feb-74	N	S	19-Apr-12	19-Apr-12	Fired on Safe Release	Improper Maintenance	265100	F	Per Ilion - Quote to repair under BLM	
7596	700	n/a	22-250 REM	1-Dec-82	N	S	19-Apr-12	18-May-12	Fired on Safe Release	Altered Adjustments or Components	267783	F	Per D. Evans, adjust as needed at no charge	
7601	742	n/a	308 WIN	1-Apr-75	Y	S	19-Apr-12	31-May-12	Fired With Safe ON	Could Not Duplicate Concern	268042	F	Clean & test fire @ n/c	
7602	700	n/a	270 WIN	1-Jul-74	N	S	19-Apr-12	8-May-12	Fired on Bolt Closing	Could Not Duplicate Concern	266695	F	Repair @ n/c - goodwill	
7599	700	25773	3006 SPRG	19-May-89	N	S	20-Apr-12	20-Apr-12	Fired With Safe ON	Improper Maintenance	265180	F	Per Ilion - Quote to repair under BLM	
7604	7	24782	243 WIN	1-Dec-82	N	S	23-Apr-12	23-Apr-12	Fired on Safe Release	Could Not Duplicate Concern	265324	F	Can offer to replace TPA, clean, test at 1/2 normal cost	

RAC001131

## Confidential

7607	700	n/a	270 WIN	1-Jun-73	N	S	23-Apr-12	23-Apr-12	Fired on Safe Release	Improper Maintenance	265420	F	Per Ilion, replace TPA, clean, test at BLSM price
7610	700ML	27574	50 CAL	11-Sep-98	Y	S	24-Apr-12	4-May-12	Fired on Bolt Closing	Improper Maintenance	266504	F	Per Ilion - Quote to repair @ a discount
7613	700	20000	243 WIN	23-Oct-80	N	S	25-Apr-12	25-Apr-12	Fired on Safe Release	Could Not Duplicate Concern	265279	F	Replace TPA, clean, test at BLSM program price
7614	700	25715	308 WIN	16-Jan-98	N	S	25-Apr-12	25-Apr-12	Fired on Safe Release	Altered Adjustments or Components	265456	F	Replace TPA, clean, test at 1/2 normal cost
7617	700	n/a	3006 SPRG	1-Aug-71	N	S	25-Apr-12	11-May-12	Fired on Bolt Closing	Could Not Duplicate Concern	267155	F	Can offer to repair TPA, clean and test at BLSM price
7618	660	n/a	243 WIN	1-May-69	Y	S	26-Apr-12	26-Apr-12	Fired on Safe Release	Altered Adjustments or Components	265705	F	Replace TPA, clean, test at no charge under recall
7619	700	n/a	270 WIN	1-Jan-80	N	S	26-Apr-12	26-Apr-12	Delayed Firing - Firearms	Improper Maintenance	265787	F	Replace TPA, clean, test at BLSM price
7620	700	n/a	22-250 REM	21-May-76	N	PD/S	26-Apr-12	18-May-12	Fired on Bolt Opening	Improper Maintenance	266418	F	Repair and clean no charge as goodwill gesture.
7630	597	26556	22 LR	18-Dec-98	N	S	2-May-12	2-May-12	Fired on Bolt Closing	Other - Unspecified or Undetermined - Firearms	266190	F	Per Ilion - Repair @ n/c
7631	870	25561	20 GA	7-Apr-98	N	PI/S	2-May-12	14-Jun-12	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	n/a	F	Could not duplicate - gun returned to customer
7633	700	n/a	7 MM REM U		N	S	2-May-12	29-Dec-12	Delayed Firing - Firearms	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
7637	700	n/a	7MM RE MAG	19-Dec-88	N	S	3-May-12	3-May-12	Fired on Safe Release	Improper Maintenance	264981	F	Returned as Received - CSR spoke to dealer
7639	700	n/a	3006 SPRG	1-Jul-70	N	S	4-May-12	4-May-12	Delayed Firing - Firearms	Improper Maintenance	266358	F	Per Ilion - Quote to repair under BLM
7640	700	n/a	3006 SPRG	1-Jul-76	N	S	7-May-12	7-May-12	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	266525	F	Per Ilion - Quote to repair under BLM
7643	721	n/a	280 REM	1-Jan-54	Y	S	8-May-12	8-May-12	Fired on Bolt Closing	Could Not Duplicate Concern	266735	F	Per Ilion, replace TPA, clean and check over under BLSM price
7644	700	26283	7MM RUM	1-Feb-01	N	S	8-May-12	8-May-12	Fired on Bolt Closing	Could Not Duplicate Concern	266685	F	Can offer to replace TPA, clean, test at 1/2 normal cost
7649	722	n/a	300 SAVAGE		N	S	8-May-12	29-Dec-12	Fired on Safe Release	Other - Unexamined	n/a	F	Gun not returned to Ilion for exam
7650	700	n/a	270 WIN	10-Jan-03	N	S	8-May-12	29-May-12	Fired on Safe Release	Altered Adjustments or Components	268913	F	Per Ilion, replace TPA, clean, test at 1/2 normal cost
7651	700	27140	300 RUM	22-Jan-10	N	S	9-May-12	9-May-12	Fired on Bolt Closing	Altered Adjustments or Components	266897	F	Per Ilion, as a good-will gesture, will repair as needed at no charge
7654	581	n/a	22 RF	6-Feb-81	N	S	10-May-12	10-May-12	Fired on Safe Release	Improper Maintenance	266904	F	Per Ilion, clean and test at 1/2 normal cost
7655	700	n/a	243 WIN	1-Apr-71	N	S	10-May-12	10-May-12	Unexplained Discharge Safe ON	Could Not Duplicate Concern	266937	F	Per Ilion, replace TPA, clean, test at BLSM price
7657	721	n/a	3006 SPRG	1-Jun-61	Y	S	10-May-12	10-May-12	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	267023	F	Per Ilion, replace TPA, clean, test at BLSM price
7668	700	27475	243 WIN	6-Aug-09	N	S	10-May-12	24-Oct-12	Unexplained Discharge - No Mention of Safety Position	Other - Unexamined	n/a	F	Case turned over to Sr Paralegal

RAC001132

## Confidential

7659	700	n/a	270 WIN	1-Feb-71	N	S	14-May-12	14-May-12	Fired on Bolt Opening	Improper Maintenance	267200	F	Replace TPA, clean, test at BLSM program price.
7661	597	26536	17 HMR	18-Mar-03	N	S	14-May-12	24-May-12	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	268829/282170	F	Replacing with #70712
7664	700	n/a			N	S	15-May-12	31-May-13	Fired on Bolt Closing	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
7669	870	25568	12 GA	25-Oct-11	N	S	16-May-12	16-May-12	Fired on Bolt Closing	Could Not Duplicate Concern	267417	F	Per Ilion - Repair under warranty
7671	700	29663	308 WIN	28-Jul-09	N	S	16-May-12	16-May-12	Fired on Bolt Closing	Could Not Duplicate Concern	267429	F	Per Ilion - Repair at no charge
7672	700	n/a	308 WIN	1-Jul-67	N	S	16-May-12	16-May-12	Fired on Safe Release	Could Not Duplicate Concern	267623	F	Per Ilion - Quote to repair under BLM
7673	XP 100	n/a	221 FIREBA	1-Jun-86	Y	S	17-May-12	17-May-12	Fired on Bolt Closing	Could Not Duplicate Concern	267742	F	Per Ilion, repair as needed at no charge under recall
7674	721	n/a	3006 SPRG	1-Jun-49	Y	S	17-May-12	17-May-12	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	267705	F	Per Ilion, replace TPA, clean, test at BLSM program price
7675	SPT 78	26172	223 REM	16-Mar-89	Y	S	17-May-12	17-May-12	Fired on Safe Release	Could Not Duplicate Concern	267714	F	Per Ilion - Quote to repair @ a discount
7679	BACR	90704	5.56 NATO	31-Aug-10	N	S	23-May-12	23-May-12	Fired Out of Battery	Could Not Duplicate Concern	268173	F	Per Ilion - Repair as needed at n/c
7683	700	n/a	3006 SPRG	1-Jun-71	N	S	24-May-12	24-May-12	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	268868	F	Per Ilion - Quote to repair under BLM
7685	700	27478	3006 SPRG	21-Jun-95	N	S	29-May-12	26-May-12	Fired on Safe Release	Could Not Duplicate Concern	269199	F	Per Ilion - Quote to repair @ a discount
7687	700	n/a	7MM REM MA	1-Apr-74	N	S	29-May-12	29-May-12	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	269299	F	Per Ilion - Quote to repair under BLM
7691	700	n/a	7MM REM EX	1-Apr-79	N	S	30-May-12	30-May-12	Fired on Bolt Opening	Could Not Duplicate Concern	269502	F	Rifle returned unprepared - customer demand
7693	700	n/a	3006 SPRG	18-Feb-82	N	S	30-May-12	30-May-12	Fired on Safe Release	Could Not Duplicate Concern	269585	F	Per Ilion - Quote to repair under BLM
7694	660	n/a	243 WIN	1-Sep-68	Y	S	30-May-12	30-May-12	Safety not working properly	Altered Adjustments or Components	269496	F	Per Ilion - Repair @ n/c - recall
7696	600	n/a			Y	S	30-May-12	*	Defective Parts	Not Examined by Product Service		F	Gun not returned to Ilion for exam
7698	721	n/a	3006 SPRG	1-Aug-49	Y	S	31-May-12	31-May-12	Safety not working properly	Improper Maintenance	269619	F	Per Ilion - Quote to repair under BLM
7700	700	n/a	3006 SPR	27-Feb-76	N	S	31-May-12	28-Jun-12	Fired on Safe Release	Altered Adjustments or Components	273233	F	Per Ilion, replace TPA, clean, test at BLSM price
7701	700	n/a	3006 SPRG	9-Feb-77	N	S	1-Jun-12	1-Jun-12	Fired on Bolt Opening	Improper Maintenance	269905	F	Per Ilion - Quote to repair under BLM
7703	700	n/a	3006 SPRG	7-Apr-82	N	S	4-Jun-12	4-Jun-12	Fired on Safe Release	Improper Maintenance	270043	F	Per Ilion - Quote to repair @ a discount
7704	870	25098	12 GA	15-Sep-06	N	S	4-Jun-12	16-Jul-12	Fired Out of Battery	Fired from Contact with Foreign Object	274391	F	Per Ilion - Repair @ n/c
7706	870	25568	12 GA	24-Mar-11	N	S	5-Jun-12	5-Jun-12	Fired on Bolt Closing	Other - Unspecified or Undetermined - Firearms	270191	F	Per Ilion, repair as needed, replace TPA, test fire at no charge under warranty
7721	700	27094	270 WIN	22-May-06	N	S	5-Jun-12	22-Jun-12	Ammunition Exploded	Over Pressured Factory Load	272627	A	Per Ilion - Repair @ n/c
7710	700	27503	6.8 REM SP	1-Mar-06	N	S	6-Jun-12	6-Jun-12	Fired on Safe Release	Altered Adjustments or Components	270538	F	Per Ilion, replace TPA, check over, test fire no charge as goodwill

RAC001133

## Confidential

7724	700	27015	7MM-08 REM	19-Jul-04	N	S	6-Jun-12	20-Jun-12	Fired on Safe Release	Altered Adjustments or Components	272491	F	Per Ilion - Quote to repair @ a discount
7712	600	n/a	308 WIN	1-Feb-64	Y	S	7-Jun-12	7-Jun-12	Fired on Bolt Closing	As received Follows Down	270553	F	Per Ilion, replace TPA, clean, test under recall at no charge
7715	700	n/a	2506 REM	1-May-70	N	S	8-Jun-12	8-Jun-12	Fired on Bolt Closing	Altered Adjustments or Components	270763	F	Per Ilion, replace TPA, clean, test at BLSM price
7716	721	n/a	3006 SPRG	1-Nov-48	Y	S	8-Jun-12	8-Jun-12	Fired on Bolt Closing	Improper Maintenance	270794	F	Per Ilion, replace TPA, clean and test under BLSM
7718	700	n/a	270 WIN	1-Sep-71	N	S	11-Jun-12	11-Jun-12	Fired on Safe Release	Improper Maintenance	270889	F	Per Ilion - Quote to repair under BLM
									Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	270940	F	Per Ilion - Quote to repair under BLM
7719	700	n/a	270 WIN	1-Oct-66	N	S	11-Jun-12	11-Jun-12		Not Examined by Product Service	n/a	A	Gun not returned to Ilion for exam
7722	1100	n/a	12 GA		N	PI/S	11-Jun-12	23-Apr-15	Blowback in Face	Other - Unspecified or Undetermined - Firearms	273242	F	Replacing with #70723
7728	597	26536	17 HMR	29-May-03	N	S	13-Jun-12	29-Jun-12	Fired Out of Battery	Could Not Duplicate Concern	274072	F	Per Ilion, replace TPA, clean, test at 1/2 normal cost
7732	700	27453	7MM-08 REM	8-May-02	N	S	15-Jun-12	16-Jul-12	Fired on Safe Release	Other - Unspecified or Undetermined - Ammunition	n/a	A	Lonoke resolved with customer
7733	Wildcat	n/a	22 LR		N	PI/S	15-Jun-12	15-Aug-12	Blowback in Face	Could Not Duplicate Concern	272113	F	Repair @ n/c - goodwill gesture
7734	700	n/a	3006 SPRG	1-Sep-79	N	PI/S	18-Jun-12	22-Jun-12	Fired on Safe Release	Could Not Duplicate Concern	272204	F	Per Ilion - Replace TA @ n/c - goodwill gesture
7739	700	85543	308 WIN	17-Nov-11	N	S	19-Jun-12	19-Jun-12	Fired on Safe Release	Improper Maintenance	272360	F	Per Ilion, replace TPA, clean, test at BLSM price
7740	700	n/a	3006 SPRG	1-Jan-73	N	S	19-Jun-12	19-Jun-12	Fired on Bolt Closing	Improper Maintenance	272387	F	Per Ilion - Repair @ n/c
7743	700	n/a	223 REM	21-Dec-77	N	S	20-Jun-12	20-Jun-12	Fired on Bolt Opening	Broken or Missing Parts	272348	F	Per Ilion - Quote to repair under BLM
7744	700	n/a	300 WIN	1-Oct-78	N	S	20-Jun-12	20-Jun-12	Fired on Bolt Closing	Altered Adjustments or Components	272384	F	Per Ilion - Quote to repair under BLM
7745	581	29848	22 RF	13-Nov-95	Y	S	20-Jun-12	20-Jun-12	Fired on Bolt Closing	Altered Adjustments or Components	272391	F	Per Ilion - Quote to repair at a discount
7746	597	26513	22 LR	5-Oct-11	N	S	20-Jun-12	25-Jun-12	Defective Parts	Other - Unspecified or Undetermined - Firearms	272387	F	Replace no charge under warranty
7767	788	n/a	n/a	2-Sep-81	Y	S	25-Jun-12	28-Jun-12	Fired on Safe Release	Other - Unexamined	n/a	F	Owner found his use of improper lubricants was the cause
7759	H&R Handi-Rifle	72500	223 REM	14-May-03	N	S	26-Jun-12	26-Jun-12	Fired on Bolt Closing	Could Not Duplicate Concern	272964	F	Per Ilion, check over completely, repair as needed at no charge
7760	700	25855	7MM08 REM	8-Aug-02	N	S	26-Jun-12	26-Jun-12	Fired With Safe ON	Could Not Duplicate Concern	273001	F	Per Ilion- Quote to repair @ a discount
									Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	273070	F	Per Ilion, offer to replace TPA, clean, test at 1/2 normal cost
7763	700	25791	270 WIN	1-May-84	N	S	27-Jun-12	27-Jun-12		Improper Maintenance	273106	F	Per Ilion - Quote to repair under BLM
7765	700	n/a	270 WIN	17-Jan-79	N	S	28-Jun-12	28-Jun-12	Fired on Safe Release	Improper Maintenance	274576	F	Per Ilion - Repair as needed @ n/c

RAC001134

## Confidential

7770	770	85633	3006 SPRG	4-Aug-11	N	S	9-Jul-12	2-Aug-12	Unexplained Discharge Safe OFF	Could Not Duplicate Concern	276637	F	As goodwill, will replace TPA, check over and test at no charge	
7774	597	80914	22 LR	20-Mar-12	N	S	10-Jul-12	23-Aug-12	Fired Out of Battery	Other - Unspecified or Undetermined - Firearms	279595	F	Per Ilion - Repair under warranty	
7775	700	25709	308 WIN	5-Jun-01	N	S	11-Jul-12	4-Jun-13	Fired on Bolt Closing	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam	
7776	700	25771	270 WIN	1-Jul-85	N	S	16-Jul-12	16-Jul-12	Fired on Safe Release	Could Not Duplicate Concern	273752	F	Per Ilion - Quote to repair @ a discount	
7778	700	20000	270 WIN	1-Nov-74	N	S	16-Jul-12	16-Jul-12	Fired on Safe Release	Improper Maintenance	274347	F	Per Ilion, replace TPA, clean, test at BLSM price	
7779	700	n/a	270 WIN	27-Jun-80	N	S	16-Jul-12	16-Jul-12	Fired on Safe Release	Could Not Duplicate Concern	274363	F	Per Ilion, replace TPA, clean, test at BLSM program price	
7784	600	n/a	222 REM	18-May-77	Y	S	16-Jul-12	16-Jul-12	Fired on Bolt Closing	Could Not Duplicate Concern	273541	F	Per Ilion - Repair @ n/c	
7785	700	25787	243 WIN	1-Dec-06	N	S	16-Jul-12	16-Jul-12	Fired on Bolt Closing	Could Not Duplicate Concern	274406	F	Per Ilion, offer to replace TPA, test at 1/2 normal cost	
7786	600	20000	308 WIN	1-Jul-66	Y	S	16-Jul-12	16-Jul-12	Fired on Bolt Closing	Altered Adjustments or Components	273743	F	Per Ilion, replace TPA and test under recall at no charge	
7788	722	n/a	222 REM	1-Dec-51	Y	S	16-Jul-12	16-Jul-12	Fired on Safe Release	Could Not Duplicate Concern	273511	F	Per Ilion, replace TPA, clean, test at BLSM program price	
7789	R25	60032	308 WIN	5-Sep-08	N	S	16-Jul-12	17-Aug-12	Jamming/Feeding issues	Could Not Duplicate Concern	273863	F	Replaced bolt, carrier assm no charge	
7790	SEVEN	85950	17 REM FB	28-Apr-08	N	PI/S	16-Jul-12	23-Aug-12	Blowback in Face	Over pressured shell - not returned	276278	F	Per Release - Replace w/85952 - M7 Predator & \$286 for medical	
7791	700	25807	300 WIN	MA	10-May-90	N	S	16-Jul-12	27-Jul-12	Fired on Bolt Closing	Improper Maintenance	275978	F	Per Ilion - Quote to repair at a discount
7798	700	n/a	3006 SPRG	1-Jan-72	N	S	16-Jul-12	27-Jul-12	Fired on Safe Release	Altered Adjustments or Components	276013	F	Per Ilion - Quote to repair under BLM	
7787	788	n/a	222	31-Jan-78	Y	S	16-Jul-12	29-Dec-13	Fired on Bolt Closing	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam	
7793	700	25795	308 WIN	27-Mar-90	N	S	17-Jul-12	17-Jul-12	Delayed Firing - Firearms	Improper Maintenance	273619	F	Per Ilion, offer to replace TPA, clean, test at 1/2 normal cost	
7800	600	n/a	243 WIN	1-May-74	Y	S	20-Jul-12	20-Jul-12	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	274929	F	Replace TPA, clean, test under recall at no charge	
7803	700	27476	270 WIN	17-Jun-97	N	S	23-Jul-12	23-Jul-12	Fired on Safe Release	Improper Maintenance	274883	F	Offer to replace TPA, clean, test fire at 1/2 normal cost	
7804	700	25771	270 WIN	1-Jul-85	N	S	23-Jul-12	23-Jul-12	Fired on Bolt Closing	Could Not Duplicate Concern	274986	F	Per Ilion, offer to replace TPA, clean, test fire at 1/2 normal cost	
7805	597	26550	22 LR	15-Oct-97	N	S	23-Jul-12	23-Jul-12	Jamming/Feeding issues	Other - Unspecified or Undetermined - Firearms	275042	F	Per Ilion, check completely and repair as needed no charge	
7811	597	26513	22 LR	27-Aug-11	N	S	24-Jul-12	24-Jul-12	Fired on Bolt Closing	Broken or Missing Parts	275381	F	Per Ilion, check over completely, repair as needed at no charge under warranty	
7813	1187	83700	12 GA	7-Sep-11	N	S	26-Jul-12	26-Jul-12	Fired on Bolt Closing	Could Not Duplicate Concern	275793	F	Per Ilion - Repair under warranty	

RAC001135

## Confidential

7816	700	84364	308 WIN	16-Mar-12	N	PD/S	27-Jul-12	23-Aug-12	Unexplained Discharge Safe OFF	Could Not Duplicate Concern	277626	F	Replace TA @ n/c - goodwill gesture
7819	700	85375	7MM REM MA	30-Nov-07	N	S	31-Jul-12	31-Jul-12	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	276168	F	Per Ilion, check over, reset trigger pull to specs, test fire at no charge as goodwill
7822	700	26189	22-250 REM	9-Jul-07	N	S	1-Aug-12	1-Aug-12	Fired on Bolt Closing	Altered Adjustments or Components	276382	F	Per Ilion, replace TPA, clean, test at 1/2 normal cost
7828	722	n/a	ROBERT 257	1-Jan-51	Y	S	1-Aug-12	28-Aug-12	Fired on Bolt Closing	Altered Adjustments or Components	280160	F	Per Ilion - Quote to repair under BLM
7829	660	n/a	308 WIN	1-Apr-68	Y	S	2-Aug-12	21-Aug-12	Fired on Safe Release	Altered Adjustments or Components	278342	F	Per Ilion - Repair under recall
7831	700	25793	3006 SPR	22-Oct-08	N	S	6-Aug-12	22-Aug-12	Fired on Bolt Closing	Could Not Duplicate Concern	279244/279232	F	Replace TPA, check, test at no charge to restore confidence
7835	SR 22	n/a	22 LR		N	PI/S	6-Aug-12	29-Oct-12	Ammunition Exploded	Not Examined by Product Service	n/a	A	Product not returned for exam
7911	7	24751	260 REM	3-Feb-99	N	S	6-Aug-12	6-Aug-12	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	280934	F	Can offer to replace TPA, clean, test fire at 1/2 normal cost to restore confidence in rifle
7836		N/A	N/A		N	PI/S	8-Aug-12	30-Oct-12	Ammunition Exploded	Not Examined by Product Service	n/a	A	Product not returned for exam
7837	Mark II	n/a	22 LR		N	PI/S	9-Aug-12	*	Ammunition Exploded	Other - Unspecified or Undetermined - Ammunition	n/a	A	
7841	S&W 617	n/a	22 LR		N	PI/S	13-Aug-12	26-Oct-12	Ammunition Exploded	Other - Unspecified or Undetermined - Ammunition	n/a	A	Lonoke reached resolution w/cusotmer
7843	R15	60102	450 Bush	10-Dec-09	N	S	14-Aug-12	30-Aug-12	Fired on Bolt Closing	Could Not Duplicate Concern	280415	F	Per Ilion, check completely, test fire at no charge
7849	700	25711	308 WIN	29-Oct-02	N	S	20-Aug-12	20-Aug-12	Fired on Bolt Closing	Altered Adjustments or Components	278600	F	Replace TPA, clean and test fire at 1/2 normal cost
7851	700	n/a	270 WIN	1-Oct-76	N	S	20-Aug-12	20-Aug-12	Fired on Safe Release	Altered Adjustments or Components	278737	F	Per Ilion, replace TPA, clean and test fire at BLSM price
7852	700	n/a	3006 SPRG	1-Aug-66	N	S	20-Aug-12	20-Aug-12	Fired on Safe Release	Improper Maintenance	277692	F	Per Ilion, replace TPA, clean and test fire at BLSM price
7853	700	n/a	7MM REM MA	1-Oct-79	N	S	20-Aug-12	20-Aug-12	Fired on Bolt Closing	Could Not Duplicate Concern	278735	F	Per Ilion, replace TPA, clean and test fire at BLSM program price
7859	BACR	90704	5.56 NATO	25-Aug-10	N	S	20-Aug-12	20-Aug-12	Went Automatic	Other - Unspecified or Undetermined - Firearms	277627	F	Per Ilion, check over completely. Repair as needed at no charge
7862	700	27313	300 WIN MA	13-Dec-11	N	S	20-Aug-12	26-Sep-12	Fired on Bolt Closing	Could Not Duplicate Concern	278194/282317	F	Per Ilion, to restore confidence, we will replace TPA, check and test at no charge
7863	700	26933	7MM REM MA	13-Jan-95	N	S	20-Aug-12	20-Aug-12	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	277790	F	Per Ilion - Quote to repair @ a discount
7865	700	n/a	270 WIN	26-Jan-79	N	S	20-Aug-12	20-Aug-12	Fired on Safe Release	Improper Maintenance	277737	F	Per Ilion - Quote to repair under BLM
7864	597	26516	17 HMR	16-Oct-03	N	S	20-Aug-12	16-Jan-13	My Gun Blew Up	Not Examined by Product Service	280513	F	Replace with a Marlin

RAC001136

## Confidential

7866	700	25803	7MM REM MA	1-Aug-85	N	S	21-Aug-12	21-Aug-12	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	278679	F	Per Ilion - Quote to repair @ a discount
7867	700	n/a	3006 SPRG	27-Feb-76	N	S	21-Aug-12	21-Aug-12	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	277701	F	Per Ilion - Quote to repair under BLM
7869	700	25635	308 WIN	2-Nov-11	N	S	21-Aug-12	21-Aug-12	Fired on Bolt Closing	Could Not Duplicate Concern	278624	F	Per Ilion - Repair under warranty
7875	700	26287	3006 SPRG	29-Nov-04	N	S	21-Aug-12	5-Sep-12	Fired on Safe Release	Could Not Duplicate Concern	280910	F	Per Ilion - Quote to repair @ a discount
7876	700	n/a	3006 SPRG	1-Apr-72	N	S	22-Aug-12	22-Aug-12	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	279447	F	Replace TPA, clean, test at BLSM price
7877	700	n/a	3006 SPRG	1-Jun-76	N	S	22-Aug-12	22-Aug-12	Fired on Safe Release	Improper Maintenance	278087	F	Per Ilion, replace TPA, clean, test at BLSM price
7878	870	25077	12 GA.	2-Mar-12	N	S	22-Aug-12	6-Sep-12	Defective Parts	Improper Assembly by Factory	278168	F	Per Ilion, repair no charge
7880	700	84178	30-06 SPG	3-Dec-10	N	S	22-Aug-12	22-Aug-12	Fired on Safe Release	Could Not Duplicate Concern	279293	F	Per Ilion, replace TPA, check over, test fire to restore confidence in rifle at no charge
7881	700	n/a	270 WIN	21-May-81	N	S	22-Aug-12	22-Aug-12	Fired With Safe ON	Improper Maintenance	279213	F	Replace TPA, clean, test at BLSM program price
7883	700	n/a	3006 SPRG	18-Oct-79	N	S	22-Aug-12	22-Aug-12	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	279470	F	Replace TPA, clean, test fire at BLSM program price
7884	700	n/a	3006 SPRG	1-Oct-71	N	S	22-Aug-12	22-Aug-12	Fired on Bolt Opening	Could Not Duplicate Concern	279273	F	Replace TPA, clean, test at BLSM program price
7887	700	85336	3006 SPRG	18-Jun-12	N	S	24-Aug-12	24-Aug-12	Fired on Bolt Closing	Could Not Duplicate Concern	279687	F	To restore confidence in rifle, will replace TPA, check over and test at no charge
7888	597	80866	22 LR	4-May-11	N	S	24-Aug-12	24-Aug-12	Fired on Bolt Closing	Could Not Duplicate Concern	279231	F	Check over completely, repair as needed at no charge
7893	700	n/a	3006 SPRG		N	S	28-Aug-12	28-Aug-12	Fired on Safe Release	Could Not Duplicate Concern	280100	F	Replace TPA, clean and test under BLSM program price, repair as needed
7895	1187	29882	12 GA	1-Feb-90	N	S	29-Aug-12	29-Aug-12	Went Automatic	Altered Adjustments or Components	280127	F	Check over completely, repair as needed at 1/2 normal cost
7897	700	25771	270 WIN	28-Feb-90	N	S	30-Aug-12	30-Aug-12	Fired With Safe ON	Could Not Duplicate Concern	280159	F	Per Ilion, offer to replace TPA, clean, test at 1/2 normal cost
7900	700	25801	17 REM	22-Apr-90	N	S	31-Aug-12	31-Aug-12	Fired on Bolt Closing	Altered Adjustments or Components	280583	F	Per Ilion, replace TPA, clean, test at 1/2 normal cost
7906	660	n/a	308 WIN	1-Sep-69	Y	S	4-Sep-12	20-Sep-12	Fired on Bolt Closing	Altered Adjustments or Components	282763	F	Per Ilion, replace TPA, clean, test under recall at no charge
7908	700	n/a	222 REM MA	1-Jul-63	N	S	5-Sep-12	5-Sep-12	Fired With Safe ON	Altered Adjustments or Components	280875	F	Replace TPA, clean, test at BLSM program price
7909	700	26023	222 REM	28-Oct-97	N	S	5-Sep-12	5-Sep-12	Fired on Safe Release	Altered Adjustments or Components	280829	F	Per Ilion, offer to replace TPA, clean, test fire at 1/2 normal cost

RAC001137

## Confidential

7913	700	84207	308 WIN	10-Jun-09	N	S	7-Sep-12	7-Sep-12	Fired on Bolt Closing	Could Not Duplicate Concern	280643	F	To restore confidence in rifle, will replace TPA, check over, and test fire at no charge
7927	700	n/a	3006 SPRG	1-Mar-84	N	S	11-Sep-12	21-Sep-12	Fired on Bolt Closing	Improper Maintenance	282932	F	Per Ilion - Quote to repair
7922	700	85471	308 WIN	11-Jun-10	N	S	12-Sep-12	12-Sep-12	Fired on Bolt Closing	Could Not Duplicate Concern	281653	F	To restore confidence in rifle, will replace TPA, check over, test at no charge
7923	700	25793	3006 SPRG	1-Oct-84	N	S	12-Sep-12	12-Sep-12	Safety not working properly	Improper Maintenance	281814	F	Can offer to replace TPA, clean, test at 1/2 normal cost
7924	R-25	60032	308 WIN	28-Apr-09	N	S	12-Sep-12	12-Sep-12	Fired on Bolt Closing	Could Not Duplicate Concern	281742	F	Check over completely at no charge under warranty
7925	Handi-Rifle	72532	44 REM MAG	26-Aug-11	N	PD/S	12-Sep-12	19-Sep-12	Light Trigger Pull	Broken or Missing Parts	282564	F	Per Ilion - Repair @ n/c - warranty
7926	600	n/a	308 WIN	1-Apr-77	Y	S	12-Sep-12	3-Oct-12	Fired on Safe Release	Altered Adjustments or Components	284053	F	Per Ilion, can offer to replace TPA at 1/2 normal cost.
7928	597	26550	22 LR	7-Apr-99	N	PD/S	12-Sep-12	2-Nov-12	Fired Out of Battery	Other - Unspecified or Undetermined - Firearms	286201	F	Replace with #26550
7929	700	n/a	3006 SPRG	1-Sep-70	N	S	13-Sep-12	13-Sep-12	Fired on Bolt Closing	Improper Maintenance	281823	F	Replace TPA, clean and test at BLSM program price
7930	700	n/a	270 WIN	1-Mar-84	N	S	13-Sep-12	13-Sep-12	Fired on Safe Release	Could Not Duplicate Concern	281976	F	Per Ilion, replace TPA, clean, test at no charge
7931	597	26550	22 LR	28-Apr-11	N	S	13-Sep-12	13-Sep-12	Delayed Firing - Firearms	Altered Adjustments or Components	281948	F	Replace TPA, check over and test at no charge
7932	597	26513	22 LR	1-Jun-09	N	S	13-Sep-12	13-Sep-12	Fired Out of Battery	Other - Unspecified or Undetermined - Firearms	281826	F	Per Ilion, check over completely, repair as needed
7944	700	27476	270 WIN	20-Jul-99	N	S	17-Sep-12	17-Sep-12	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	282314	F	Per Ilion - Quote to repair
7946	700	n/a	308 WIN	1-Apr-67	N	S	17-Sep-12	27-Sep-12	Fired on Bolt Closing	Improper Maintenance	283581	F	Replace TPA, clean, test fire at BLSM program price
7948	700	n/a	308 WIN	1-Sep-69	N	S	18-Sep-12	4-Oct-12	Fired on Safe Release	Could Not Duplicate Concern	284229	F	Can offer to replace TPA, clean, test at BLSM price
7951	700	27482	300 WIN MA	29-Jul-01	N	S	20-Sep-12	20-Sep-12	Fired on Bolt Closing	Improper Maintenance	282516	F	Per Ilion, replace TPA, clean and test fire at 1/2 cost
7952	700	25787	243 WIN	29-Aug-87	N	S	20-Sep-12	20-Sep-12	Other - Firearms	Needs Updated Parts	282504	F	Per Ilion, replace TPA, check over and test fire under sear cam recall at no charge
7954	700	n/a	243 WIN	1-Nov-71	N	S	20-Sep-12	3-Oct-12	Fired on Safe Release	Could Not Duplicate Concern	284078	F	Per Ilion - Quote to repair under BLM
7955	597	26550	22 LR	29-Jan-01	N	S	21-Sep-12	21-Sep-12	Fail to Fire	Could Not Duplicate Concern	282930	F	Per Ilion - Repair @ n/c
7956	700	n/a	3006 SPRG 7MM REM	1-May-83	N	S	21-Sep-12	21-Sep-12	Improper Safety Design	Improper Maintenance	282931	F	Replace TPA, clean and test at 1/2 cost
7959	700	n/a	MA	9-May-77	N	S	21-Sep-12	4-Oct-12	Fired on Bolt Closing	Improper Maintenance	284269	F	Per Ilion - Quote to repair under BLM
7957	700	26939	338 WIN MA	13-Apr-95	N	S	21-Sep-12	29-Dec-13	Fired on Safe Release	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
7963	700	25777	7MM MAG	12-Dec-89	N	S	24-Sep-12	23-May-13	Fired on Safe Release	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam

RAC001138

Confidential

7966	40-XB	27225	308 WIN	13-Apr-09	N	S	25-Sep-12	26-Oct-12	Fired on Bolt Closing	Could Not Duplicate Concern	287031	F	Per Illion - Repair @ n/c Can offer to replace TPA, clean, test at BLSM program price	
7972	700	n/a	7MM REM MA	22-Mar-80	N	S	26-Sep-12	26-Sep-12	Fired on Safe Release	Could Not Duplicate Concern	283421	F	Per Consumer Service Dept. - Replace TA @ n/c - goodwill Per Illion - Quote to repair under BLM	
7973	700	27485	7MM-08 REM	19-Jun-01	N	S	26-Sep-12	27-Sep-12	Fired on Bolt Closing	Could Not Duplicate Concern	283538	F	Per Consumer Service Dept. - Replace TA @ n/c - goodwill Per Illion - Quote to repair under BLM	
7975	700	n/a	7MM REM EX	23-Jul-79	N	S	26-Sep-12	27-Sep-12	Fired on Safe Release	Improper Maintenance	283543	F	Per Illion - Quote to repair under BLM	
7976	700	n/a	7MM REM MA	1-Oct-71	N	S	26-Sep-12	26-Sep-12	Fired on Bolt Closing	Altered Adjustments or Components	283221	F	Per Illion - Quote to repair under BLM	
7977	1187	n/a	12 GA	22-May-12	N	PD/S	26-Sep-12	30-Nov-12	Unexplained Discharge Safe ON	Could Not Duplicate Concern	286125	F	Replace TPA no charge as goodwill to restore confidence	
7980		n/a	270 WIN			N	PI/S	26-Sep-12	12-Nov-12	Ammunition Exploded	Other - Unspecified or Undetermined - Ammunition	n/a	A	Lonoke replaced ammo
7978	700	n/a	270 WIN	1-Mar-84	N	S	27-Sep-12	27-Sep-12	Fired on Safe Release	Altered Adjustments or Components	283401	F	Replace TPA, clean and test fire at 1/2 normal cost	
7990	700	84370	223 REM	28-Jan-09	N	S	27-Sep-12	15-Oct-12	Fired on Safe Release	Could Not Duplicate Concern	285297	F	Per Illion - Replace TA @ n/c	
7984	700	27572	50 CAL	25-Oct-97	Y	S	1-Oct-12	1-Oct-12	Fired on Safe Release	As received Follows Down	283678	F	Per Illion, replace TPA, check over, clean at no charge	
7985	Para GI45	n/a	45 ACP			N	PI/S	1-Oct-12	18-Oct-12	Safety not working properly	As received Follows Down	n/a	F	Per Release - repair firearm @ n/c. Refund for vet bills \$3,479.77
7987	700	n/a	243 WIN	1-May-67	N	S	2-Oct-12	2-Oct-12	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	283967	F	Replace TPA, clean and test at BLSM program price	
7992	700	25777	7MM REM MA	18-Jan-96	N	S	3-Oct-12	3-Oct-12	Fired on Safe Release	Altered Adjustments or Components	284011	F	Per Illion - Quote to repair @ a discount	
7994	700	29696	338 WIN MA	3-Mar-97	N	S	3-Oct-12	3-Oct-12	Fired on Bolt Closing	Improper Maintenance	284097	F	Repaired @ n/c - Consumer Serv. Dept. removed charges	
7995	700	25793	270 WIN	14-Jan-02	N	S	3-Oct-12	3-Oct-12	Fired on Bolt Closing	Could Not Duplicate Concern	284140	F	Per Illion - Quote to repair @ a discount	
7999	700	n/a	300 H&H MA	1-May-83	N	S	4-Oct-12	4-Oct-12	Delayed Firing - Firearms	Could Not Duplicate Concern	284294	F	Per Illion - Quote to repair @ a discount	
8001	700	84467	308 WIN	2-Jun-10	N	S	4-Oct-12	4-Oct-12	Fired on Safe Release	Could Not Duplicate Concern	284361	F	Per Illion - Replace TA & test - warranty	
8004	Ruger .22	n/a	22		N	S	4-Oct-12	4-Oct-12	Blowback in Face	Other - Unexamined	n/a	A	Lonoke resolved	
8006	700	n/a	243 WIN	1-Apr-69	N	S	5-Oct-12	5-Oct-12	Delayed Firing - Firearms	Altered Adjustments or Components	284292	F	Per Illion - Repair under BLM	
8007	7	24741	7MM-08 REM	5-May-98	N	S	5-Oct-12	5-Oct-12	Fired on Safe Release	Altered Adjustments or Components	284515	F	Per Illion - Quote to repair @ a discount	
8008	700	27478	3006 SPRG	22-Mar-96	N	S	5-Oct-12	5-Oct-12	Fired on Safe Release	Altered Adjustments or Components	284517	F	Per Illion, replace TPA, clean, test at 1/2 normal cost	
8020	700	29692	7MM REM MA	20-Mar-96	N	S	10-Oct-12	10-Oct-12	Fired on Bolt Closing	Improper Maintenance	284646	F	Per Illion, replace TPA, clean, test fire at 1/2 normal cost	
8021	700	25793	3006 SPRG	1-Jun-84	N	S	10-Oct-12	10-Oct-12	Fired on Bolt Closing	Altered Adjustments or Components	284997	F	Per Illion, replace TPA, clean, test at 1/2 normal cost	
8023	700	n/a	270 WIN	28-Apr-76	N	S	10-Oct-12	10-Oct-12	Unexplained Discharge Safe ON	Altered Adjustments or Components	284897	F	Per Illion, replace TPA, clean, test at BLSM program price	

RAC001139

## Confidential

8024	700	n/a	3006 SPRG	2-Feb-81	N	PD/S	10-Oct-12	10-Oct-12	Fired on Bolt Closing	Could Not Duplicate Concern	284940	F	Replace TPA, clean, test at no charge as goodwill
8026	700	n/a	3006 SPRG	1-Jun-79	N	S	10-Oct-12	17-Oct-12	Fired on Safe Release	Altered Adjustments or Components	285828	F	Per Ilion, replace TPA, clean, test at BLSM program price
8030	700ML	27580	50 CAL	8-Aug-97	Y	S	11-Oct-12	25-Oct-12	Fired on Safe Release	Broken or Missing Parts	286761	F	Per Ilion, connector broken, Repair in exchange at no charge
8052	700	n/a	270 WIN		N	PD/S	12-Oct-12	24-Jun-13	Unexplained Discharge - No Mention of Safety Position	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
8035	700	n/a	243 WIN	10-Apr-79	N	S	15-Oct-12	15-Oct-12	Fired on Bolt Closing	Altered Adjustments or Components	284998	F	Per Ilion - Quote to repair under BLM
8037	887	82503	12 GA	29-Jun-10	N	S	15-Oct-12	15-Oct-12	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	285001	F	Per Ilion - Replace TA & test @ n/c
8038	700	n/a	7MM REM MA	1-Sep-65	N	S	15-Oct-12	26-Oct-12	Fired on Safe Release	Could Not Duplicate Concern	286987	F	Per Ilion, replace TPA, clean, test at BLSM program price
8040	700	27476	270 WIN	18-Mar-97	N	S	15-Oct-12	23-Oct-12	Fired on Safe Release	Could Not Duplicate Concern	286498	F	Per Ilion, replace TPA, clean, test at 1/2 normal cost
8041	Llama pistol	n/a	22 LR		N	S	15-Oct-12	6-Mar-13	Ammunition Exploded	Other - Unexamined	n/a	A	Lonoke resolved
8042	1100	25260	20 GA	9-Jul-76	N	S	16-Oct-12	16-Oct-12	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	285444	F	Per Ilion, check over, test fire at 1/2 normal cost
8043	700	27586	50 CAL	5-Sep-97	Y	PI/S	16-Oct-12	16-Oct-12	Fired on Safe Release	Defective Trigger Assembly	285595	F	Per Ilion - Replace TA & clean @ n/c
8044	770	85633	3006 SPRG	17-Feb-10	N	S	16-Oct-12	16-Oct-12	Fired on Safe Release	Could Not Duplicate Concern	285527	F	Per Ilion - Replace TA & test @ n/c
8045	710	27410	3006 SPRG	25-May-06	Y	S	16-Oct-12	16-Oct-12	Fired on Bolt Closing	Improper Maintenance	285585	F	Per Ilion - Quote to repair at a discount
8046	700	n/a	3006 SPRG	1-Aug-69	N	S	17-Oct-12	17-Oct-12	Fired on Bolt Closing	Improper Maintenance	285279	F	Per Ilion - Quote to repair under BLM
8047	700	25773	3006 SPRG	13-Nov-93	N	S	17-Oct-12	17-Oct-12	Fired on Safe Release	Worn parts or components	285282	F	Per Ilion - Quote to repair @ a discount
8048	700	27094	270 WIN	10-May-10	N	S	17-Oct-12	17-Oct-12	Fired on Safe Release	Could Not Duplicate Concern	285608	F	Per Ilion, replace TPA, check over and test fire at no charge under warranty
8057	700	27140	300 RUM	14-Apr-08	N	S	18-Oct-12	18-Oct-12	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	285839	F	Per Ilion, offer to replace TPA, clean, test fire at 1/2 normal cost
8058	700	84463	338 LAPUA	30-Mar-12	N	S	18-Oct-12	18-Oct-12	Fired on Bolt Closing	Could Not Duplicate Concern	285885	F	Per Ilion: Repair at no charge
8059	700	25739	308 WIN	28-Mar-07	N	S	18-Oct-12	18-Oct-12	Fired on Safe Release	Could Not Duplicate Concern	285931	F	Per Ilion, will replace TPA, check over and test at no charge
8061	700	n/a	7MM REM MA	3-Jul-75	N	S	18-Oct-12	18-Oct-12	Unexplained Discharge Safe ON	Improper Maintenance	285970	F	Per Ilion, replace TPA, clean, test at BLSM program price
8067	700	n/a	7MM REM MA	5-Dec-80	N	S	19-Oct-12	19-Oct-12	Fired on Bolt Closing	Altered Adjustments or Components	286029	F	Per Ilion, replace TPA, clean, test at BLSM program price
8075	700	n/a	3006 SPRG	1-Feb-71	N	S	22-Oct-12	5-Nov-12	Fired on Bolt Closing	Could Not Duplicate Concern	288116	F	Per Ilion - Quote to repair under BLM

RAC001140

## Confidential

8072	700	26989	3006 SPRG	15-May-98	N	S	23-Oct-12	23-Oct-12	Fired on Safe Release	Could Not Duplicate Concern	286019	F	Per Ilion, offer to replace TPA at 1/2 normal cost
8077	700	25711	308 WIN	8-Jan-07	N	S	24-Oct-12	24-Oct-12	Fired on Bolt Closing	Could Not Duplicate Concern	286297	F	Per Ilion, offer to replace TPA, clean and test fire at 1/2 normal cost
8080	700	84176	243 WIN	25-Mar-10	N	S	25-Oct-12	25-Oct-12	Fired on Safe Release	Could Not Duplicate Concern	286796	F	To restore confidence in rifle will replace TPA, check over and test
8081	700	n/a	308 WIN	1-Aug-73	N	S	25-Oct-12	25-Oct-12	Fired on Safe Release	Could Not Duplicate Concern	286783	F	Per Ilion - Quote to repair under BLM
8082	700	n/a	270 WIN	1-May-75	N	S	25-Oct-12	25-Oct-12	Fired on Safe Release	Altered Adjustments or Components	286826	F	Per Ilion - Quote to repair under BLM
8086	770	85637	243 WIN	13-Aug-08	N	S	26-Oct-12	16-Nov-12	Unexplained Discharge Safe ON	Other - Unspecified or Undetermined - Firearms	286984	F	Refunding for rifle
8087	600	n/a	222 REM	1-Mar-74	Y	S	26-Oct-12	26-Oct-12	Fired on Safe Release	Could Not Duplicate Concern	286957	F	Per Ilion, replace TPA, clean, test at BLSM program price
8088	770	85656	3006 SPRG	31-Jul-09	N	S	26-Oct-12	8-Nov-12	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	286965	F	Replace TPA to restore confidence, clean, test no charge
8089	770	85633	3006 SPRG	18-Oct-11	N	S	26-Oct-12	26-Oct-12	Delayed Firing - Ammunition	Could Not Duplicate Concern	286967	F	Per Ilion, to restore confidence in rifle will replace TPA, clean and test at no charge
8091	700	26196	204 RUGER	20-Mar-06	N	S	26-Oct-12	27-Nov-12	Fired on Safe Release	Altered Adjustments or Components	289893	F	Per Ilion - Quote to repair @ a discount
8093	700	25771	270 WIN	19-Sep-89	N	S	29-Oct-12	29-Oct-12	Fired on Safe Release	Altered Adjustments or Components	287197	F	Per Ilion, can offer to replace TPA, clean and test at 1/2 normal cost
8095	700	n/a	3006 SPRG	20-Aug-76	N	S	29-Oct-12	29-Oct-12	Fired on Safe Release	Altered Adjustments or Components	287111	F	Per Ilion, replace TPA, clean, test at BLSM program price
8096	700	27582	54 CAL	4-Jun-96	Y	S	29-Oct-12	29-Oct-12	Fired on Safe Release	Broken or Missing Parts	287196	F	Per Ilion, check over and repair TPA at no charge.
8054	700	n/a	3006 SPRG	1-Nov-72	N	S	30-Oct-12	30-Oct-12	Fired on Bolt Opening	Could Not Duplicate Concern	287490	F	Per Ilion - Quote to repair under BLM
8102	7	24786	REM	9-Jan-98	N	S	31-Oct-12	31-Oct-12	Fired on Bolt Closing	Could Not Duplicate Concern	287645	F	Per Ilion, to restore confidence in rifle, offer to replace TPA, clean, test at 1/2 normal cost
8107	522	29792	22 LR	25-Oct-95	Y	S	1-Nov-12	9-Nov-12	Went Automatic	Broken or Missing Parts	287712	F	Return as received
8110	Benelli	n/a	12 GA				1-Nov-12	6-Mar-13	Case Separation	Other - Unexamined	n/a	A	Per Ilion - Lonoce resolved
8111	700	n/a	270 WIN	1-Feb-71	N	S	2-Nov-12	2-Nov-12	Fired on Bolt Closing	Could Not Duplicate Concern	287526	F	Per Ilion, offer to replace TPA, clean, test at BLSM program price
8114	700	27580	50 CAL	7-Apr-97	Y	S	2-Nov-12	2-Nov-12	Fired on Safe Release	Could Not Duplicate Concern	287717	F	Per Ilion, can offer to replace TPA, clean, check over at 1/2 normal cost
8116	700	20000	6MM REM	1-Apr-72	N	S	5-Nov-12	5-Nov-12	Fired on Safe Release	Altered Adjustments or Components	288079	F	Per Ilion, replace TPA, clean, test at BLSM program price
8118	700	84177	270 WIN	23-Jul-12	N	S	5-Nov-12	26-Nov-12	Fired on Safe Release	Could Not Duplicate Concern	290108	F	Per Ilion - Replace TA & test @ n/c - warranty
8120	597	n/a	17 HMR	24-Mar-03	N	S	5-Nov-12	3-Dec-12	Ammunition Exploded	Other - Unexamined	290054	F	Convert to .22 WMR
8124	700	n/a	30-06 SPRG	1-Jul-70	N	S	6-Nov-12	28-Nov-12	Fired on Safe Release	Could Not Duplicate Concern	290248	F	Per Ilion, replace TPA, clean, test at BLSM program price

RAC001141

## Confidential

8123	870	25568	12 GA	30-Jan-02	N	PI/S	6-Nov-12	*	Fired With Safe ON	Other - Unexamined		F	Gun not returned to Ilion for exam
8127	700	n/a	3006 SPRG		N	PD/S	7-Nov-12	13-Dec-12	Fired on Bolt Closing	Altered Adjustments or Components	290673	F	Replace TA, remove bolt lock & test @ n/c - goodwill gesture
8125	770	85654	7MM REM MA	15-Sep-11	N	PI/S	7-Nov-12	7-Jan-13	Defective Parts	Sent in for Evaluation	292398	F	Per Release - Replace w/84187 in exchange
8128	700	n/a	6MM REM	1-Jun-70	N	S	8-Nov-12	8-Nov-12	Fired on Bolt Closing	Altered Adjustments or Components	288463/461/465/460	F	Per Ilion - Quote to repair under BLM
8129	Versa Max	81048	12 GA	28-Feb-12	N	S	8-Nov-12	8-Nov-12	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	288443	F	Per Ilion - Repair as needed & test @ n/c
8130	700	n/a	3006 SPRG	1-Apr-73	N	S	8-Nov-12	8-Nov-12	Fired on Safe Release	Altered Adjustments or Components	288471	F	Per Ilion - Quote to repair under BLM
8132	700	n/a	270 WIN		N	S	8-Nov-12	8-Nov-12	Fired on Safe Release	Could Not Duplicate Concern	287200	F	Per Ilion, replace TPA, clean and test at BLSM program price
8133	770	85633	3006 SPR	5-Mar-12	N	PI/S	8-Nov-12	10-Dec-12	Fired on Safe Release	Could Not Duplicate Concern	290494	F	Replace TPA, test no charge to restore confidence
8136	700	27474	243 WIN	12-Aug-98	N	S	9-Nov-12	9-Nov-12	Fired on Safe Release	Improper Maintenance	288683	F	Per Ilion - Quote to repair @ a discount
8143	600	n/a	222 REM	1-Apr-64	Y	S	12-Nov-12	30-Nov-12	Defective Parts	Altered Adjustments or Components	290773	F	Replace TA under recall @ n/c
8149	Excel Auto	72350	12 GA	2-Jun-10	N	S	12-Nov-12	7-Dec-12	Unexplained Discharge - No Mention of Safety Position	Sent in for Evaluation	290511	F	Refunding \$339.19 for firearms
8146	700	n/a	243 WIN		N	S	12-Nov-12	21-May-13	Fired on Safe Release	Other - Unexamined	n/a	F	No product sent for inspection
8151	700	84370	223 REM	23-Mar-09	N	S	13-Nov-12	13-Nov-12	Fired on Bolt Closing	Could Not Duplicate Concern	288901	F	Per Ilion - Replace TA & test @ n/c
8152	742	n/a	3006 SPRG	1-Jul-70	Y	S	13-Nov-12	13-Nov-12	Fired With Safe ON	Could Not Duplicate Concern	289033	F	Per Ilion - Quote to check over & test at 1/2 normal cost
8161	600	n/a	243 WIN	1-Jun-67	Y	S	13-Nov-12	11-Dec-12	Defective Parts	Sent in for Evaluation	291919	F	Per Ilion - Replace TA, clean & test under recall
8165	PARDNER	72096	12 GA	7-Feb-11	N	S	15-Nov-12	15-Nov-12	Unexplained Discharge - No Mention of Safety Position	Sent in for Evaluation	289269	F	Per Ilion, check over completely. Repair as needed at no charge under warranty
8166	541	29824	22 RF	2-Mar-90	Y	S	15-Nov-12	15-Nov-12	Fired on Safe Release	Altered Adjustments or Components	289334	F	Per Ilion - Quote to repair @ 1/2 normal cost
8169	7	20000	308 WIN		N	S	15-Nov-12	5-Jun-13	Fired on Safe Release	Not Examined by Product Service		F	Gun not returned to Ilion for exam
8170	600	n/a	243 WIN	1-Jul-74	Y	S	16-Nov-12	16-Nov-12	Fired on Safe Release	Could Not Duplicate Concern	289051	F	Per Ilion - Replace TA under recall @ n/c
8171	700	25791	270 WIN	7-Nov-89	N	S	16-Nov-12	16-Nov-12	Delayed Firing - Firearms	Improper Maintenance	289516	F	Ilion repaired at no charge
8177	700	85435	308 WIN	19-Apr-12	N	PI/PD/S	19-Nov-12	27-Dec-12	Fired With Safe ON	Could Not Duplicate Concern	292419	F	To restore confidence - replace TA, clean & test Repair @ n/c - goodwill
8179	7600	n/a	270 WIN	1-Mar-82	N	PD/S	19-Nov-12	14-Dec-12	Fired on Bolt Closing	Altered Adjustments or Components	291209	F	Repair @ n/c - goodwill gesture
8184	700	n/a	308 WIN	1-Aug-71	N	S	21-Nov-12	9-Jan-13	Fired on Safe Release	Could Not Duplicate Concern	295446	F	Per Ilion - Quote to repair under BLM
8187	660	n/a	222 REM	1-Jun-68	Y	S	26-Nov-12	26-Nov-12	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	289964	F	Per Ilion, replace TPA, clean, test at no charge under recall
8188	700	n/a	7MM REM MA	23-Mar-79	N	S	26-Nov-12	26-Nov-12	Fired on Bolt Closing	Could Not Duplicate Concern	289653	F	Per Ilion, replace TPA, clean, test at BLSM price

RAC001142

## Confidential

8189	700	85435	308 WIN	18-Jul-12	N	S	26-Nov-12	26-Nov-12	Fired on Bolt Closing	Could Not Duplicate Concern	289945	F	Per Ilion, replace TPA, check over and test at no charge
8190	700	n/a	243 WIN	1-Sep-71	N	S	26-Nov-12	26-Nov-12	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	290142	F	Per Ilion, replace TPA, clean, test at BLSM program price
8191	710	27416	243 WIN	3-Mar-06	N	S	26-Nov-12	26-Nov-12	Jar-Off Safe OFF	Could Not Duplicate Concern	290112	F	Per Ilion, can offer replace TPA, clean and test fire with slave mag at 1/2 normal cost
8192	700	n/a	25-06		N	S	26-Nov-12	26-Nov-12	Fired on Safe Release	Not Examined by Product Service	n/a	F	Customer had local gunsmith change the trigger
8196	870	81221	20 GA	21-Aug-09	N	S	27-Nov-12	27-Nov-12	Fired With Safe ON	Could Not Duplicate Concern	289274	F	Per Ilion: Repair at no charge
8197	700	n/a	3006 SPRG	1-Jul-68	N	S	27-Nov-12	27-Nov-12	Fired on Bolt Closing	Could Not Duplicate Concern	289855	F	Per Ilion, replace TPA, clean, test at BLSM program price
8199	600	n/a	6MM REM	20-Jun-75	Y	S	27-Nov-12	27-Nov-12	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	289966	F	Per Ilion, replace TPA, clean, test at no charge under recall
8200	700	27173	270 WSM	21-Jun-07	N	S	27-Nov-12	27-Nov-12	Fired on Safe Release	Could Not Duplicate Concern	289617	F	Per Ilion, to restore confidence will replace TPA, clean and test fire no charge
8202	SPT 78	26164	3006 SPRG	1-Jul-84	N	S	27-Nov-12	27-Nov-12	Fired on Safe Release	Altered Adjustments or Components	290036	F	Per Ilion - Quote to repair @ 1/2 normal cost
8211	7	86052	308 WIN	2-Aug-07	N	S	27-Nov-12	27-Nov-12	Fired on Safe Release	Could Not Duplicate Concern	290255	F	Per Ilion, will replace TPA, check over and test at no charge as goodwill
8219	700	n/a	308 WIN	1-May-78	N	PI/S	27-Nov-12	28-Dec-12	Fired on Bolt Closing	Improper Maintenance	293160	F	Perform BLM @ n/c - goodwill gesture
8203	870	n/a	12 GA	1-Jan-00	N	S	27-Nov-12	22-May-13	Jamming/Feeding issues	Other - Unexamined	n/a	F	No product sent for inspection
8205	700	n/a	25-06 REM		N	S	27-Nov-12	21-May-13	Fired With Safe ON	Other - Unexamined	n/a	F	Product not sent for inspection
8208	Mossberg 590 Flex	n/a	12 GA		N	S	27-Nov-12	29-Dec-13	Case Separation	Other - Unexamined	n/a	F	No Additional Info. From Lonoke
8231	700	n/a	3006 SPRG	25-Mar-76	N	S	27-Nov-12	16-Jan-13	Fired on Safe Release	Altered Adjustments or Components	296691	F	Per Ilion - Quote to repair under BLM
8270	870	81282	12 GA	23-Aug-12	N	S	27-Nov-12	23-Jan-13	Warning Inadequate - Firearm	Defective Parts	n/a	F	Replacing scopes with 2 Simmons ProHunter scopes
8210	105	90689	12 GA	16-Mar-09	N	S	28-Nov-12	28-Nov-12	Fired on Bolt Closing	Could Not Duplicate Concern	289207	F	Per Ilion, repair as needed and test at no charge
8212	710	27410	3006 SPRG	2-Jun-04	N	S	28-Nov-12	28-Nov-12	Unexplained Discharge - No Mention of Safety Position	Sent in for Evaluation	290249	F	Per Ilion, check over completely, repair as needed at no charge
8213	700	n/a	7MM REM MA	7-Dec-81	N	S	28-Nov-12	28-Nov-12	Improper Safety Design	Could Not Duplicate Concern	290218	F	Per Ilion, replace TPA, clean, test at BLSM program price
8215	710	27408	270 WIN	3-Dec-01	Y	S	28-Nov-12	13-Dec-12	Unexplained Discharge - No Mention of Safety Position	As received Follows Down	290386	F	Replacing with 770
8216	700	25791	270 WIN	26-Feb-02	N	PD/S	28-Nov-12	7-Jun-13	Fired on Safe Release	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam

RAC001143

## Confidential

8221	700	n/a	n/a		N	S	28-Nov-12	23-May-13	Fired on Bolt Opening	Other - Unexamined	n/a	F	No product sent for inspection
8235	710	27410	3006 SPRG	1-Dec-05	Y	S	28-Nov-12	7-Jan-13	Fired on Bolt Closing	Could Not Duplicate Concern	294933	F	Per Illion - Quote to repair @ 1/2 normal cost
8222	700	n/a	3006 SPRG	1-Jun-74	N	S	29-Nov-12	29-Nov-12	Fired on Safe Release	Improper Maintenance	290646	F	Per Illion - Quote to repair under BLM
8223	700	n/a	7MM REM MA	1-Oct-77	N	S	29-Nov-12	29-Nov-12	Delayed Firing - Firearms	Improper Maintenance	290468	F	Per Illion - Quote under BLM
8224	700	n/a	308 WIN	1-Oct-72	N	S	29-Nov-12	29-Nov-12	Safety not working properly	Altered Adjustments or Components	290485	F	Per Illion - Quote to repair under BLM
8227	Excel Auto	72350	12 GA	5-Jun-10	N	S	29-Nov-12	29-Nov-12	Fired on Bolt Closing	Could Not Duplicate Concern	290489	F	Per Illion - Check over & repair @ n/c
8239	700	n/a	3006 SPRG	27-Aug-76	N	S	30-Nov-12	30-Nov-12	Safety not working properly	Altered Adjustments or Components	290583	F	Per Illion, repair TPA, clean, test at no charge per M. Johnson
8240	700	27167	3006 SPRG	5-Oct-06	N	S	30-Nov-12	30-Nov-12	Fired on Safe Release	Could Not Duplicate Concern	290648	F	Per Illion, replace TPA, check, test to restore confidence in rifle at no charge as goodwill
8242	760	n/a	280 REM	1-Feb-64	Y	S	30-Nov-12	14-Dec-12	Fired on Bolt Closing	Altered Adjustments or Components	290653	F	Upgrade to Model 7600 at special price
8243	700	27580	50 CAL	7-Oct-96	Y	S	30-Nov-12	30-Nov-12	Fired on Safe Release	Broken or Missing Parts	290738	F	Per Illion, replace TPA, check over, clean at no charge
8244	SPT 78	26164	3006 SPRG	14-Jun-86	Y	S	30-Nov-12	30-Nov-12	Fired on Safe Release	Altered Adjustments or Components	290645	F	Per Illion, replace TPA, clean, test at 1/2 normal cost
8250	700	27573	50 CAL	25-Jul-02	N	S	3-Dec-12	3-Dec-12	Fired on Safe Release	Could Not Duplicate Concern	290887	F	Per Illion - Quote to repair at 1/2 normal cost
8251	7	24788	308 WIN	1-Sep-84	N	S	3-Dec-12	3-Dec-12	Fired on Safe Release	Improper Maintenance	290895	F	Per Illion - Quote to repair @ 1/2 normal cost
8252	600	n/a	243 WIN	1-Apr-74	Y	S	3-Dec-12	3-Dec-12	Fired on Safe Release	Broken or Missing Parts	290937	F	Per Illion - Replace TA, clean & test under recall
8253	CARBON 15	90689	223 REM	20-Jan-12	N	S	3-Dec-12	3-Dec-12	Went Automatic	Broken or Missing Parts	291033	F	Per Illion, repair as needed at no charge
8255	700	25773	3006 SPRG	6-Jun-96	N	S	3-Dec-12	3-Dec-12	Fired on Safe Release	Improper Maintenance	290963	F	Per Illion - Quote to repair @ 1/2 normal cost
8256	700	27476	270 WIN	31-Mar-03	N	S	3-Dec-12	3-Dec-12	Fired on Safe Release	Could Not Duplicate Concern	291014	F	Per Illion, replace TPA, clean and test at 1/2 normal cost
8257	700	20000	243 WIN	1-Apr-68	N	S	3-Dec-12	3-Dec-12	Fired on Bolt Closing	Altered Adjustments or Components	291072	F	Per Illion, replace TPA, clean and test at BLSM program price
8259	700	25803	7MM REM MA	1-Aug-85	N	S	3-Dec-12	3-Dec-12	Fired on Bolt Closing	Altered Adjustments or Components	291092	F	Per Illion, replace TPA, clean, test at 1/2 normal cost
8260	1100	25328	12 GA	1-Mar-75	N	PD/S	3-Dec-12	10-Jan-13	Barrel Burst/Split (Other than Chamber)	Fired While Obstructed	292656	A	Repair @ n/c
8261	700	n/a	3006 SPRG	25-May-79	N	PD/S	3-Dec-12	21-Jan-13	Fired on Safe Release	Could Not Duplicate Concern	296677	F	Bolt Lock Modification at n/c goodwill gesture
8207	710	27412	7MM REM MA	28-Nov-06	N	S	4-Dec-12	4-Dec-12	Fired on Bolt Closing	Broken or Missing Parts	291130	F	Per Illion, replace TPA, check over and test at no charge
8266	700	n/a	7MM REM EX	27-Apr-79	N	S	4-Dec-12	4-Dec-12	Fired on Safe Release	Altered Adjustments or Components	291206	F	Per Illion, replace TPA, clean, test at BLSM program price
8267	788	n/a	222 REM	1-May-74	Y	S	4-Dec-12	4-Dec-12	Fired on Safe Release	Improper Maintenance	291241	F	Per Illion, offer to remove, tear down and clean TPA and test firearm at 1/2 normal cost.

RAC001144

## Confidential

8268	660	n/a	243 WIN	1-Apr-68	Y	S	4-Dec-12	4-Dec-12	Fired on Safe Release	As received Follows Down	291253	F	Per Ilion, replace TPA, clean and test at no charge under recall
8269	742	n/a	3006 SPRG	1-Aug-72	Y	PD/S	4-Dec-12	18-Jan-13	Fired on Bolt Closing	Sent in for Evaluation	292652	F	Per Release - replace w/27061 at n/c
8273	660	n/a	308 WIN	1-Aug-69	N	S	5-Dec-12	5-Dec-12	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	289613	F	Replace TPA, clean and test under recall at no charge
8274	597	26562	22 LR	22-Jul-02	N	S	5-Dec-12	5-Dec-12	Jamming/Feeding issues	Could Not Duplicate Concern	291320	F	Per Ilion, check over completely, repair as needed at no charge
8275	700	20000	308 WIN	1-Jan-72	N	S	5-Dec-12	5-Dec-12	Fired on Bolt Closing	Could Not Duplicate Concern	291311	F	Per Ilion, replace TPA, clean, test at BLSM program price
8276	700	84078	7MM REM MA	13-May-11	N	S	5-Dec-12	5-Dec-12	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	291342	F	Check over completely and safety check and test fire at no charge as goodwill
8279	700	n/a	3006 SPRG	1-Apr-72	N	S	5-Dec-12	5-Dec-12	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	291485	F	Per Ilion, replace TPA, clean, test at BLSM program price
8280	700	n/a	243 WIN	1-Oct-77	N	S	5-Dec-12	5-Dec-12	Fired on Safe Release	Altered Adjustments or Components	291459	F	Replace TPA, clean, test at BLSM program price
8281	700	n/a	270 WIN	22-Aug-77	N	S	5-Dec-12	5-Dec-12	Fired on Safe Release	Altered Adjustments or Components	291484	F	Per Ilion, replace TPA, clean, test at 1/2 normal cost
8282	700	n/a	6MM REM	10-Nov-76	N	S	5-Dec-12	5-Dec-12	Fired on Safe Release	Altered Adjustments or Components	291487	F	Per Ilion, replace TPA, clean, test at BLSM program price
8288		n/a	38 SPC		N	S	6-Dec-12	6-Mar-13	Bullet Lodged in Barrel	Other - Unexamined	n/a	A	Lonoke resolved
8291	700	25771	270 WIN	24-Jul-86	N	S	7-Dec-12	7-Dec-12	Safety not working properly	Could Not Duplicate Concern	290933	F	Per Ilion, replace TPA, clean, test at 1/2 normal cost
8292	700	n/a	308 WIN	1-Jul-73	N	S	7-Dec-12	7-Dec-12	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	290913	F	Replace TPA, clean and test at BLSM program price
8293	700	25807	300 WIN MA	23-May-06	N	S	7-Dec-12	7-Dec-12	Fired on Bolt Closing	Could Not Duplicate Concern	290922	F	Can offer to replace TPA, clean, test fire at 1/2 normal cost
8294	700	n/a	3006 SPRG	1-Jul-74	N	S	7-Dec-12	7-Dec-12	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	291800	F	Per Ilion, replace TPA, clean and test fire at BLSM program price
8299	700	27357	7MM08 REM	18-Mar-09	N	S	10-Dec-12	10-Dec-12	Fired on Safe Release	Could Not Duplicate Concern	292050	F	To restore confidence in rifle, will replace TPA, clean and test at no charge
8300	700	n/a	35 WHELEN	26-Jul-88	N	S	10-Dec-12	10-Dec-12	Fired on Safe Release	Could Not Duplicate Concern	292016	F	Per Ilion, can offer to replace TPA, clean, test at 1/2 normal cost
8301	700	27478	3006 SPRG	27-Aug-98	N	S	10-Dec-12	10-Dec-12	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	291936	F	Per Ilion, replace TPA, clean and test at 1/2 normal cost
8303	700	n/a	8MM REM MA	31-Mar-77	N	S	10-Dec-12	10-Dec-12	Fired on Bolt Opening	Could Not Duplicate Concern	291930	F	Per Ilion, replace TPA, clean, test at BLSM program price

RAC001145

## Confidential

8304	700	27013	280 REM	18-Aug-04	N	S	10-Dec-12	10-Dec-12	Fired on Bolt Closing	Altered Adjustments or Components	291953	F	Per Ilion, replace TPA, clean, test at 1/2 normal cost
8305	770	85630	243 WIN	12-Jan-12	N	S	10-Dec-12	10-Dec-12	Defective Parts	Broken or Missing Parts	291846	F	Per Ilion, repair as needed at no charge
8306	770	85635	7MM REM MA	3-Feb-09	N	S	10-Dec-12	10-Dec-12	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	291892	F	Per Ilion, as a gesture of goodwill, replace TPA, check over and test at no charge
8309	700	25793	3006 SPRG	3-Jun-96	N	S	10-Dec-12	4-Feb-13	Fired on Safe Release	Could Not Duplicate Concern	299070	F	Replace TPA, clean and test at 1/2 normal cost
8312	597	26550	22 LR	26-Oct-00	N	PD/S	10-Dec-12	9-Jan-13	Ammunition Exploded	Other - Unspecified or Undetermined - Firearms	294697	A	Replace rifle w/26550 in exchange
8314	700	n/a	270 WIN		N	PD/S	10-Dec-12	7-Jun-13	Fired on Safe Release	Not Examined by Product Service		F	Gun not returned to Ilion for exam
8315	700	25632	280 REM	21-Mar-86	N	S	11-Dec-12	11-Dec-12	Fired on Safe Release	Altered Adjustments or Components	292145	F	Per Ilion - Quote to repair @ 1/2 normal cost
8316	700	n/a	243 WIN	1-Dec-74	N	S	11-Dec-12	11-Dec-12	Fired on Safe Release	Altered Adjustments or Components	292079	F	Per Ilion - Quote to repair under BLM
8317	700	n/a	22-250 REM	12-Dec-77	N	S	11-Dec-12	11-Dec-12	Fired on Safe Release	Altered Adjustments or Components	291992	F	Per Ilion - Quote to repair under BLM
8318	700	n/a	270 WIN	8-Jan-80	N	S	11-Dec-12	11-Dec-12	Fired on Bolt Closing	Could Not Duplicate Concern	292047	F	Per Ilion - Quote to repair under BLM
8319	700	n/a	308 WIN	1-Jul-74	N	S	11-Dec-12	11-Dec-12	Fired on Bolt Closing	Could Not Duplicate Concern	291886	F	Per Ilion - Quote to repair under BLM
8320	7	24786	7MM08 WIN	1-Jul-84	N	S	11-Dec-12	11-Dec-12	Fired on Safe Release	Could Not Duplicate Concern	291922	F	Per Ilion, offer to replace TPA, clean, test at 1/2 normal cost
8321	700	n/a	7MM REM MA	1-Sep-77	N	S	11-Dec-12	11-Dec-12	Fired on Safe Release	Altered Adjustments or Components	291956	F	Per Ilion - Quote to repair under BLM
8322	700	n/a	243 WIN	1-Apr-64	N	S	11-Dec-12	11-Dec-12	Fired on Safe Release	Improper Maintenance	292094	F	Per Ilion - Quote to repair under BLM
8323	700ML	27572	50 CAL	15-Sep-97	Y	S	11-Dec-12	11-Dec-12	Fired on Safe Release	Broken or Missing Parts	292133	F	Per Ilion - Repair at n/c
8325	700	29712	3006 SPRG	14-Jul-92	N	S	11-Dec-12	11-Dec-12	Fired on Bolt Closing	Improper Maintenance	292144	F	Per Ilion - Quote to repair @ 1/2 normal cost
8326	721	n/a	270 WIN	1-Apr-52	Y	S	11-Dec-12	11-Dec-12	Fired on Bolt Closing	Altered Adjustments or Components	292135	F	Per Ilion - Quote to repair under BLM
8327	600	n/a	308 WIN	1-Mar-73	Y	S	11-Dec-12	11-Dec-12	Fired on Bolt Closing	Altered Adjustments or Components	292148	F	Per Ilion - Repair under recall @ n/c
8328	600	n/a	308 WIN	1-Oct-73	Y	S	11-Dec-12	11-Dec-12	Fired on Bolt Closing	Improper Maintenance	292187	F	Per Ilion - Repair under recall @ n/c
8329	700	n/a	7MM REM MA	1-Feb-72	N	S	11-Dec-12	11-Dec-12	Fired on Safe Release	Could Not Duplicate Concern	292178	F	Per Ilion - Quote to repair under BLM
8332	600	n/a	222 REM	1-Apr-65	Y	S	11-Dec-12	11-Dec-12	Fired on Safe Release	Improper Maintenance	292217	F	Per Ilion - Repair under recall @ n/c
8336	1187	25339	12 GA	20-Apr-00	N	S	11-Dec-12	28-Dec-12	Fired Out of Battery	Could Not Duplicate Concern	293814	F	Replace w/83620 in exchange
8333	700	n/a	243 WIN		N	PD/S	11-Dec-12	8-Jan-13	Fired on Safe Release	Altered Adjustments or Components	293967	F	Replace TA, clean & test @ n/c - goodwill gesture
8334	700	85361	3006 SPRG	8-Nov-07	N	PD/S	11-Dec-12	11-Jan-13	Fired With Safe ON	Could Not Duplicate Concern	294889	F	To restore confidence - replace TA, clean & test at n/c
8337	700	n/a	7MM REM MA	1-Jun-75	N	S	12-Dec-12	12-Dec-12	Fired on Safe Release	Could Not Duplicate Concern	292301	F	Per Ilion, replace TPA, clean and test at BLSM program price
8339	700	27572	50 CAL	1-Nov-96	Y	S	12-Dec-12	12-Dec-12	Fired on Safe Release	Broken or Missing Parts	292327	F	Replace TPA, clean and check over at no charge
8340	700	25777	7MM REM MA	8-Apr-96	N	S	12-Dec-12	12-Dec-12	Fired on Safe Release	Could Not Duplicate Concern	292337	F	Per Ilion, replace TPA, clean and test at 1/2 normal cost

RAC001146

## Confidential

8341	597	26550	22 LR	4-May-98	N	S	12-Dec-12	12-Dec-12	Fired Out of Battery	Other - Unspecified or Undetermined - Firearms	292409	F	Per Ilion, check over completely, repair as needed at no charge
8342	660	n/a	6.5MM REM	1-Feb-68	Y	S	12-Dec-12	12-Dec-12	Fired on Bolt Closing	Could Not Duplicate Concern	292420	F	Per Ilion, replace TPA, clean and test under recall at no charge.
8343	600	n/a	243 WIN	1-Jun-67	Y	S	12-Dec-12	12-Dec-12	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	292422	F	Per Ilion, replace TPA, clean and test at no charge under recall
8345	700	29709	270 WIN	19-Aug-96	N	S	12-Dec-12	12-Dec-12	Delayed Firing - Firearms	Improper Maintenance	292423	F	Per Ilion, can offer to replace TPA, clean and test at 1/2 normal cost
8347	Mohawk 600	n/a	243 WIN	10-Jan-78	Y	S	12-Dec-12	11-Feb-13	Fired on Safe Release	Could Not Duplicate Concern	300135	F	Replace TPA, clean, test at BLSM program price
8349	700	n/a	243 WIN	1-Aug-74	N	S	13-Dec-12	13-Dec-12	Fired on Bolt Closing	Improper Maintenance	292572	F	Per Ilion, replace TPA, clean and test at BLSM program price
8350	700ML	27580	50 CAL	11-Apr-97	Y	S	13-Dec-12	13-Dec-12	Fired on Safe Release	Broken or Missing Parts	292597	F	Per Ilion - Repair @ n/c
8352	700	25807	300 WIN MA	1-Mar-85	N	S	13-Dec-12	13-Dec-12	Fired on Safe Release	Altered Adjustments or Components	292527	F	Per Ilion - Quote to repair @ 1/2 normal cost
8353	700	n/a	3006 SPRG	1-Aug-71	N	S	13-Dec-12	13-Dec-12	Fired on Safe Release	Altered Adjustments or Components	292619	F	Per Ilion - Quote to repair under BLM
8348	700	n/a	3006 SPRG	22-Jun-78	N	PD/S	13-Dec-12	6-Jan-13	Fired on Bolt Opening	Could Not Duplicate Concern	292660	F	Replace TA, clean & test fire @ n/c - goodwill gesture
8355	700	n/a	3006 SPRG	1-May-06	N	S	13-Dec-12	9-Jan-13	Fired on Safe Release	Altered Adjustments or Components	295454	F	Per Ilion - Quote to repair @ 1/2 normal cost
8356	700	n/a	3006 SPRG	1-Dec-74	N	S	14-Dec-12	14-Dec-12	Fired on Safe Release	Could Not Duplicate Concern	292748	F	Per Ilion - Quote to repair under BLM
8357	597	26513	22 LR	11-Sep-12	N	S	14-Dec-12	14-Dec-12	Unexplained Discharge - No Mention of Safety Position	Broken or Missing Parts	292733	F	Per Ilion - Check over completely, repair as needed under warranty
8362	700	n/a	243 WIN	1-May-73	N	S	17-Dec-12	17-Dec-12	Fired on Bolt Closing	Altered Adjustments or Components	292958	F	Per Ilion, replace TPA, clean and test fire at BLSM program price
8363	770	85632	270 WIN	25-May-11	N	S	17-Dec-12	17-Dec-12	Fired on Bolt Closing	Could Not Duplicate Concern	292384	F	Per Ilion - check over & repair - warranty
8365	700	84016	7MM REM MA	3-Apr-12	N	S	17-Dec-12	17-Dec-12	Fired on Safe Release	Could Not Duplicate Concern	292261	F	Per Ilion - Replace TA to restore confidence @ n/c
8366	700	26263	7MM REM MA	26-Feb-98	N	S	17-Dec-12	17-Dec-12	Fired on Safe Release	Could Not Duplicate Concern	292403	F	Per Ilion, can offer to replace TPA, clean, test at 1/2 charge to restore confidence
8367	700	84207	308 WIN	29-Jun-12	N	S	17-Dec-12	17-Dec-12	Fired on Safe Release	Could Not Duplicate Concern	292947	F	Per Ilion, will replace TPA, check over and test at no charge
8368	700	25773	3006 SPRG	16-Oct-87	N	S	17-Dec-12	17-Dec-12	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	292922	F	Per Ilion, can offer to replace TPA, clean and test at 1/2 charge to restore confidence
8369	600	n/a	243 WIN	1-Aug-74	Y	S	17-Dec-12	17-Dec-12	Fired on Safe Release	Altered Adjustments or Components	292924	F	Per Ilion, replace TPA, clean and test under recall at no charge
8370	700	84170	243 WIN	24-Jan-07	N	S	17-Dec-12	17-Dec-12	Safety not working properly	Altered Adjustments or Components	292979	O	Per Ilion, replace TPA, clean and test at 1/2 normal cost

RAC001147

## Confidential

8371	700	25773	3006 SPRG	16-Nov-89	N	S	17-Dec-12	17-Dec-12	Fired on Safe Release	Could Not Duplicate Concern	292992	F	Per Iliion, offer to replace TPA, clean, test at 1/2 charge
8372	700	n/a	3006 SPRG	25-Jan-78	N	S	17-Dec-12	17-Dec-12	Fired on Safe Release	Could Not Duplicate Concern	293067	F	Per Iliion, replace TPA, clean and test at BLSM program price
8373	700	27476	270 WIN	24-Jan-00	N	S	18-Dec-12	18-Dec-12	Delayed Firing - Firearms	Improper Maintenance	292508	F	Per Iliion - Quote to repair @ 1/2 normal charge
8375	700	25777	7MM REM MA	19-May-89	N	S	18-Dec-12	18-Dec-12	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	293178	F	Per Iliion, offer to replace TPA, clean and test at 1/2 normal charge
8376	700	n/a	308 WIN	1-Jul-68	N	S	18-Dec-12	18-Dec-12	Fired on Safe Release	Improper Maintenance	293229	F	Per Iliion - Quote to repair under BLM
8377	700	25771	270 WIN	21-Oct-96	N	S	18-Dec-12	18-Dec-12	Fired on Safe Release	Could Not Duplicate Concern	293346	F	Per Iliion - Quote to repair @ 1/2 normal cost
8382	770	85637	243 WIN	14-Aug-09	N	S	19-Dec-12	19-Dec-12	Fired on Safe Release	Could Not Duplicate Concern	293417	F	Per Iliion - Repair @ n/c - goodwill gesture
8383	7	24743	308 WIN	14-Oct-96	N	S	19-Dec-12	19-Dec-12	Fired on Safe Release	Improper Maintenance	293495	F	Per Iliion - Quote to repair @ 1/2 normal cost
8384	700	26434	7MM SAUM	10-Jul-02	N	S	19-Dec-12	19-Dec-12	Fired on Safe Release	Altered Adjustments or Components	293381	F	Per Iliion - Quote to repair @ 1/2 normal cost
8385	700	27580	50 CAL	4-Apr-97	N	S	19-Dec-12	19-Dec-12	Fired on Bolt Closing	Worn parts or components	293457	F	Per Iliion - Repair at n/c
8389	700	26259	3006 SPRG	24-Oct-01	N	S	20-Dec-12	20-Dec-12	Fired on Safe Release	Could Not Duplicate Concern	293611	F	Per Iliion - Quote to repair @ 1/2 normal cost
8391	700	25713	308 WIN	18-Feb-99	N	S	20-Dec-12	20-Dec-12	Fired on Safe Release	Altered Adjustments or Components	293664	F	Return as received
8392	597	26516	17 HMR	20-Mar-03	N	S	20-Dec-12	2-May-13	Other - Firearms	Other - Unspecified or Undetermined - Firearms	295181	F	Quote for 60001
8394	700	n/a	270 WIN	1-Aug-74	N	S	21-Dec-12	21-Dec-12	Fired on Safe Release	Could Not Duplicate Concern	293695	F	Per Iliion, replace TPA, clean and test at BLSM program price
8395	700	n/a	270 WIN	22-Jul-79	N	S	21-Dec-12	21-Dec-12	Fired on Safe Release	Altered Adjustments or Components	293754	F	Per Iliion, replace TPA, clean and test at BLSM program price
8396	700	n/a	3006 SPRG	23-Sep-75	N	S	21-Dec-12	21-Dec-12	Fired on Safe Release	Could Not Duplicate Concern	293798	F	Per Iliion, replace TPA, clean and test at BLSM program price
8397	700	25771	270 WIN	1-Jan-89	N	S	21-Dec-12	21-Dec-12	Fired on Safe Release	Improper Maintenance	293785	F	Return as received
8398	788	29813	243 WIN	1-Jun-82	Y	S	21-Dec-12	21-Dec-12	Fired on Safe Release	Improper Maintenance	293806	F	Per Iliion, offer to remove, disassemble and clean TPA and test at 1/2 charges
7127	New England Single Shot	n/a	12 GA		N	S	21-Dec-12	*	Delayed Firing - Ammunition	Other - Unexamined		A	
8406	700	n/a	270 WIN	1-Mar-70	N	S	2-Jan-13	2-Jan-13	Fired on Bolt Closing	Improper Maintenance	293577	F	Per Iliion, replace TPA, clean and test fire at BLSM program price.
8407	600	n/a	308 WIN	1-Apr-67	N	S	2-Jan-13	2-Jan-13	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	294045	F	Per Iliion, replace TPA, clean and test under recall
8409	700	27518	243 WIN	3-May-02	N	S	2-Jan-13	2-Jan-13	Fired on Safe Release	Could Not Duplicate Concern	293956	F	Per Iliion, offer to replace TPA, clean, test at 1/2 normal cost
8410	700	n/a	7MM REM MA	1-Oct-71	N	S	2-Jan-13	2-Jan-13	Fired on Safe Release	Improper Maintenance	293891	F	Per Iliion - Quote to repair

RAC001148

## Confidential

8411	7600	25153	3006 SPRG	23-Jan-03	N	PD/S	2-Jan-13	30-Jan-13	Fired With Safe ON	Altered Adjustments or Components	293971	F	Repair @ n/c - goodwill gesture
8412	700	n/a	7MM REM MA	1-May-77	N	S	2-Jan-13	2-Jan-13	Fired on Safe Release	Improper Maintenance	293946	F	Replace TPA, clean, test at BLSM program price
8413	700	n/a	243 WIN	1-Dec-71	N	S	2-Jan-13	2-Jan-13	Fired on Safe Release	Could Not Duplicate Concern	294124	F	Per Ilion, replace TPA, clean and test at BLSM program price
8414	700	n/a	7MM REM MA	1-Oct-68	N	S	2-Jan-13	2-Jan-13	Fired on Safe Release	Altered Adjustments or Components	294132	F	Per Ilion, replace TPA, clean and test at BLSM program price
8417	742	n/a	3006 SPRG	27-Jun-79	Y	PD/S	2-Jan-13	9-Jan-13	Fired on Bolt Closing	Sent in for Evaluation	294342	F	Return as received
8421	700	n/a	2506 REM	1-Jul-84	N	PD/S	3-Jan-13	3-Jan-13	Fired on Bolt Closing	Altered Adjustments or Components	294739	F	Per Ilion, offer to replace TPA, clean, test at 1/2 normal cost
8422	700	25771	270 WIN	2-Aug-88	N	S	3-Jan-13	3-Jan-13	Fired on Safe Release	Improper Maintenance	294743	F	Per Ilion - Quote to repair @ 1/2 normal cost
8423	700	n/a	270 WIN	1-Aug-67	N	S	3-Jan-13	3-Jan-13	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	294253	F	Per Ilion - Quote to repair under BLM
8424	700	n/a	270 WIN	28-Apr-76	N	S	3-Jan-13	3-Jan-13	Fired on Safe Release	Improper Maintenance	294368	F	Per Ilion - Quote to repair under BLM
8425	700	26099	300 RUM	25-Jul-99	N	S	3-Jan-13	3-Jan-13	Fired on Safe Release	Could Not Duplicate Concern	294575	F	Per Ilion - Quote to repair @ 1/2 normal cost
8426	700	n/a	3006 SPRG	30-Mar-76	N	S	3-Jan-13	3-Jan-13	Fired on Safe Release	Altered Adjustments or Components	294585	F	Per Ilion - Quote to repair under BLM
8427	597	26516	17 HMR	24-Oct-04	N	S	3-Jan-13	22-Jan-13	Other - Firearms	Other - Unspecified or Undetermined - Firearms	296803	F	Replace with #70724
8432	700	n/a	3006 SPRG	1-Sep-71	N	S	4-Jan-13	4-Jan-13	Fired on Safe Release	Could Not Duplicate Concern	294785	F	Per Ilion - Quote to repair under BLM
8434	700	n/a	3006 SPRG	19-Sep-78	N	S	4-Jan-13	4-Jan-13	Fired on Safe Release	Could Not Duplicate Concern	294791	F	Per Ilion - Quote to repair under BLM
8436	660	n/a	243 WIN	1-Feb-68	Y	S	4-Jan-13	21-Jan-13	Other - Does not trust firearm	Returned due to Recall	297128	F	Per Ilion - Replace TA @ n/c - recall
8438	700	n/a	270 WIN	6-Oct-75	N	S	7-Jan-13	7-Jan-13	Fired on Bolt Closing	Altered Adjustments or Components	294509	F	Per Ilion, replace TPA, clean and test firm at BLSM program price
8439	700	n/a	7MM REM MA	3-May-77	N	S	7-Jan-13	7-Jan-13	Fired on Safe Release	Could Not Duplicate Concern	294952	F	Per Ilion - Quote to repair under BLM
8440	700	25797	280 REM	4-Nov-91	N	S	7-Jan-13	7-Jan-13	Fired on Bolt Closing	Altered Adjustments or Components	295098	F	Per Ilion, can offer to replace TPA, clean and test at 1/2 normal cost
8441	700	n/a	270 WIN	1-Apr-77	N	S	7-Jan-13	22-Jan-13	Delayed Firing - Firearms	Improper Maintenance	297520	F	Per Ilion, replace TPA, clean, test at BLSM program price
8445	700	n/a	270 WIN	1-Jul-74	N	S	8-Jan-13	8-Jan-13	Fired on Safe Release	Could Not Duplicate Concern	294552	F	Replace TPA, clean and test fire at BLSM program price
8446	700	84600	223 REM	27-Feb-12	N	S	8-Jan-13	15-Jan-13	Fired on Safe Release	Could Not Duplicate Concern	295180	F	Replace TPA, clean, test at no charge to restore confidence in rifle
8448	700	26096	300 RUM	23-Oct-00	N	S	8-Jan-13	8-Jan-13	Fired on Safe Release	Improper Maintenance	295225	F	Per Ilion - Quote to repair @ 1/2 normal cost
8452	700	n/a	2506 REM	9-Apr-76	N	S	9-Jan-13	9-Jan-13	Fired on Safe Release	Altered Adjustments or Components	295455	F	Per Ilion, replace TPA, clean, test at BLSM program price
8453	700	25739	308 WIN	21-Mar-12	N	S	10-Jan-13	10-Jan-13	Fired on Bolt Closing	Improper Maintenance	295573	F	Per Ilion - Replace TA @ n/c - goodwill gesture

RAC001149

## Confidential

8454	788	n/a	6MM REM 338 WIN	1-Nov-70	Y	S	10-Jan-13	10-Jan-13	Fired on Bolt Closing	Could Not Duplicate Concern	295502	F	Per Ilion, can offer to remove TPA, disasm and clean and remove bolt lock at 1/2 cost
8456	700	26973	MA	4-May-95	N	S	10-Jan-13	10-Jan-13	Fired on Bolt Closing	Altered Adjustments or Components	295578	F	Replace TPA, clean and test at 1/2 normal cost
8460	600	n/a	308 WIN 7MM/08 REM	1-Jan-66	Y	PD/S	10-Jan-13	12-Feb-13	Fired on Safe Release	Could Not Duplicate Concern	298058	F	Bolt lock modification - no charge
8465	R25	60031		25-Nov-09	N	S	11-Jan-13	28-Jan-13	Fired on Bolt Closing	Could Not Duplicate Concern	295350	F	RGA issued for the rifle
8466	CARBON 15	90689	223-5.56 N	13-Jun-12	N	S	11-Jan-13	21-Jan-13	Fired on Bolt Closing	Could Not Duplicate Concern	295804	F	Repair no charge under warranty
8467	600	n/a	243 WIN	14-Nov-77	Y	S	11-Jan-13	11-Jan-13	Fired on Bolt Closing	Could Not Duplicate Concern	295908	F	Per Ilion, replace TPA, clean, test fire at BLSM program price
8468	700	26107	300 RUM	25-Jan-01	N	S	11-Jan-13	29-Jan-13	Fired on Safe Release	Could Not Duplicate Concern	298263	F	Per Ilion - Quote to repair @ 1/2 normal cost
8471	700	n/a	270 WIN	1-Aug-72	N	S	14-Jan-13	14-Jan-13	Fired on Safe Release	Could Not Duplicate Concern	296328	F	Per Ilion - Quote to repair under BLM
8472	700	n/a	3006 SPRG	1-Apr-72	N	S	14-Jan-13	14-Jan-13	Fired on Safe Release	Altered Adjustments or Components	296173	F	Per Ilion - Quote to repair under BLM
8474	700	n/a	22-250 REM	1-May-68	N	S	14-Jan-13	14-Jan-13	Fired on Bolt Closing	Altered Adjustments or Components	296348	F	Per Ilion, replace TPA, clean, test at BLSM program price
8476	700	n/a	270 WIN	5-Jan-81	N	S	14-Jan-13	14-Jan-13	Fired on Safe Release	Could Not Duplicate Concern	296345	F	Per Ilion, replace TPA, clean, test at BLSM program price
8477	700	85407	308 WIN	29-May-12	N	S	14-Jan-13	14-Jan-13	Fired on Safe Release	Could Not Duplicate Concern	296325	F	Per Ilion, will replace TPA, check over and test at no charge as goodwill
8478	700	25709	308 WIN	1-Oct-08	N	S	14-Jan-13	14-Jan-13	Fired on Bolt Closing	Could Not Duplicate Concern	296162	F	Per Ilion, can offer to replace TPA, clean, test at 1/2 normal cost
8479	600	n/a	243 WIN	1-May-72	Y	S	15-Jan-13	15-Jan-13	Fired on Bolt Closing	Altered Adjustments or Components	296425	F	Per Ilion, replace TPA, clean, test at no charge under recall
8482	700	25793	3006 SPRG	18-Dec-86	N	S	16-Jan-13	16-Jan-13	Delayed Firing - Firearms	Improper Maintenance	295927	F	Per Ilion, can offer to replace TPA, clean, test fire at 1/2 normal cost
8494	870	27040	12 GA	24-Sep-12	N	S	18-Jan-13	18-Jan-13	Fired on Safe Release	Could Not Duplicate Concern	296953	F	Per D. Sykes, #26929 as replacement under warranty
8496	700	84272	2506 REM	24-Oct-12	N	S	18-Jan-13	18-Jan-13	Fired on Bolt Closing	Other - Unspecified or Undetermined - Firearms	296810	F	Per Ilion, will replace TPA, check over and test fire at no charge
8499	597	26560	22 WMR	21-Sep-11	N	S	21-Jan-13	24-Jan-13	Blowback in Face	Other - Unspecified or Undetermined - Firearms	297358	F	Replace w/70855 in exchange
8500	700	25793	3006 SPRG	1-Nov-83	N	S	21-Jan-13	21-Jan-13	Delayed Firing - Firearms	Improper Maintenance	297149	F	Per Ilion, can offer to replace TPA, clean, test at 1/2 normal cost
8501	700	29717	3006 SPRG	26-Oct-95	N	S	21-Jan-13	21-Jan-13	Fired on Safe Release	Altered Adjustments or Components	297410	F	Per Ilion - Quote to repair at 1/2 normal cost
8502	700	27572	50 CAL	15-Sep-97	N	S	21-Jan-13	21-Jan-13	Fired on Bolt Closing	Improper Maintenance	297380	F	Per Ilion - Quote to repair at 1/2 normal cost
8503	700	n/a	243 WIN	14-Nov-75	N	S	21-Jan-13	21-Jan-13	Fired on Safe Release	Altered Adjustments or Components	297400	F	Per Ilion - Quote to repair under BLM
8506	1911	96328	45 ACP	1-Dec-11	N	S	21-Jan-13	21-Jan-13	Fired With Safe ON	Sent in for Evaluation	297025	F	Per Ilion - Check over, repair as needed @ n/c

RAC001150

## Confidential

8507	700	85490	308 WIN	21-Oct-11	N	S	21-Jan-13	21-Jan-13	Fired on Safe Release	Could Not Duplicate Concern	297101	F	Per Ilion - Replace TA @ n/c to restore confidence - goodwill
8508	700	n/a	3006 SPRG	1-Sep-71	N	S	21-Jan-13	21-Jan-13	Fired on Safe Release	Altered Adjustments or Components	297268	F	Per Ilion - Quote to repair under BLM
8509	700	25632	280 REM	9-May-91	N	S	21-Jan-13	21-Jan-13	Fired on Bolt Closing	Altered Adjustments or Components	297271	F	Per Ilion - Quote to repair @ 1/2 normal cost
8510	700	25771	270 WIN	20-Aug-91	N	S	21-Jan-13	21-Jan-13	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	297203	F	Per Ilion, offer replace TPA, clean, test at 1/2 normal cost
8515	887	82502	12 GA	18-Jun-10	N	S	22-Jan-13	22-Jan-13	Fired on Bolt Closing	Could Not Duplicate Concern	297550	F	Check over completely, repair as needed and test fire at no charge as goodwill
8519	700	27131	204 RUGER	5-Sep-08	N	S	23-Jan-13	23-Jan-13	Fired on Safe Release	Altered Adjustments or Components	297652	F	Per Ilion, can offer to replace TPA, clean and test at 1/2 normal cost
8520	700	25803	7MM REM MA	10-Jul-95	N	S	23-Jan-13	23-Jan-13	Delayed Firing - Firearms	Improper Maintenance	297617	F	Per Ilion - Quote to repair @ 1/2 normal cost
8522	700	25767	243 WIN	13-Sep-93	N	S	24-Jan-13	24-Jan-13	Defective Parts	Leaking Primers	296992	F	Per Ilion, repair 1/2 normal cost as a good will gesture
8523	700	n/a	243 WIN	1-Dec-71	N	S	24-Jan-13	24-Jan-13	Fired on Bolt Opening	Altered Adjustments or Components	297857	F	Per Ilion, replace TPA, clean and test at BLSM program price
8525	600	n/a	222 REM	25-Feb-76	Y	S	24-Jan-13	24-Jan-13	Fired on Bolt Closing	Could Not Duplicate Concern	297906	F	Per Ilion, replace TPA, clean, test under recall at no charge
8527	710	27408	270 WIN	16-May-02	N	PI/PD/S	24-Jan-13	20-Feb-13	Fired on Safe Release	Altered Adjustments or Components	300092	F	Replace with #85632, 770 .270
8528	700	25609	35 WHELEN	5-Oct-89	Y	PI/S	28-Jan-13	26-Feb-13	Fired on Bolt Closing	Altered Adjustments or Components	301645/301709	F	Replace TPA no charge as goodwill
8532	710	27410	3006 SPRG	7-Jan-01	N	S	28-Jan-13	19-Feb-13	Fired on Bolt Closing	Altered Adjustments or Components	298241	F	85633, 770 30-06 as replacement no chg
8534	1187	29895	12 GA	11-May-10	N	S	29-Jan-13	29-Jan-13	Fired With Safe ON	Could Not Duplicate Concern	297973	F	To restore confidence, will replace TPA, check over completely and test as goodwill
8535	700	84401	2506 REM	8-Jul-09	N	S	29-Jan-13	29-Jan-13	Fired on Safe Release	Altered Adjustments or Components	298215	F	Per Ilion, offer to replace TPA, check over and test at 1/2 normal cost
8536	597	26560	22 WMR	1-Aug-11	N	S	29-Jan-13	18-Feb-13	Jamming/Feeding issues	Sent in for Evaluation	298132	F	Ordered #25594 as replacement
8539	700	n/a	3006 SPRG	23-Sep-79	N	S	29-Jan-13	29-Jan-13	Fired on Bolt Opening	Improper Maintenance	298271	F	Per Ilion, replace TPA, clean and test at BLSM program price
8543	700	25771	270 WIN	1-Oct-83	N	S	30-Jan-13	30-Jan-13	Fired on Safe Release	Improper Maintenance	298376	F	Per Ilion, offer to replace TPA, clean and test at 1/2 normal cost
8544	700	n/a	270 WIN	20-May-81	N	S	30-Jan-13	30-Jan-13	Fired on Safe Release	Altered Adjustments or Components	298379	F	Per Ilion, replace TPA, clean and test at BLSM program price
8547	700	n/a	308 WIN	16-Jul-79	N	S	30-Jan-13	30-Jan-13	Defective Parts	Altered Adjustments or Components	298400	F	Replace TPA, clean and test at BLSM program price
8548	700	n/a	6MM REM	1-May-69	N	S	30-Jan-13	30-Jan-13	Fired on Safe Release	Altered Adjustments or Components	298537	F	Replace TPA, clean and test at BLSM program price

RAC001151

## Confidential

8551	700	27009	2506 REM 22-250 REM	21-Jan-10	N	S	31-Jan-13	31-Jan-13	Fired on Bolt Closing	Could Not Duplicate Concern	298782	F	To restore confidence, will replace TPA, recrown muzzle, check over and test no charge	
8552	700	n/a	7MM REM MA	1-Mar-69	N	S	31-Jan-13	31-Jan-13	Fired on Safe Release	Could Not Duplicate Concern	298815	F	Per Ilion - Quote to repair under BLM	
8553	700	n/a	7MM REM MA	1-Oct-01	N	S	31-Jan-13	31-Jan-13	Delayed Firing - Firearms	Improper Maintenance	298775	F	Per Ilion - Quote to repair at 1/2 normal cost	
8554	700	27094	270 WIN	17-Jul-12	N	S	31-Jan-13	31-Jan-13	Fired on Bolt Closing	Could Not Duplicate Concern	298738	F	Per Ilion - Replace TA @ n/c - goodwill	
8558	597	26562	22 LR	25-Mar-11	N	S	1-Feb-13	1-Feb-13	Unexplained Discharge Safe OFF	Could Not Duplicate Concern	298985	F	Per Ilion - Check over & repair under warranty	
8559	700	n/a	7MM REM MA	1-Sep-71	N	S	1-Feb-13	1-Feb-13	Fired on Safe Release	Altered Adjustments or Components	298948	F	Per Ilion, replace TPA, clean and test at BLSM program price	
8560	700	n/a	243 WIN	12-Oct-77	N	S	1-Feb-13	1-Feb-13	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	298856	F	Replace TPA, clean and test at BLSM program price	
8562	700	27476	270 WIN	1-Jan-96	N	S	4-Feb-13	4-Feb-13	Fired on Safe Release	Improper Maintenance	299028	F	Offer to replace TPA, clean and test at 1/2 normal cost	
8563	700	27017	3006 SPRG	24-Aug-09	N	S	4-Feb-13	4-Feb-13	Fired on Safe Release	Could Not Duplicate Concern	299026	F	To restore confidence in rifle we will replace TPA, clean and test at no charge	
8564	700	25783	22-250 REM	6-Jan-03	N	S	4-Feb-13	4-Feb-13	Fired on Safe Release	Improper Maintenance	299055	F	Replace TPA, clean and test at 1/2 normal cost	
8565	700	27478	3006 SPRG	12-Mar-99	N	S	4-Feb-13	4-Feb-13	Fired on Bolt Closing	Could Not Duplicate Concern	299029	F	Per Ilion - Quote to repair at 1/2 normal cost	
8567	CARBON 15	90689	223 REM	29-Oct-10	N	S	4-Feb-13	4-Feb-13	Fired With Safe ON	Could Not Duplicate Concern	299228	F	Per Ilion, offer to update to the new style trig assm at 1/2 normal cost	
8568	700	n/a	3006 SPRG	1-Aug-87	N	S	4-Feb-13	4-Feb-13	Fired on Safe Release	Improper Maintenance	299030	F	Per Ilion - Quote to repair @ 1/2 normal cost	
8569	870	25568	12 GA	18-May-12	N	S	4-Feb-13	4-Feb-13	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	299248	F	Check over completely. Repair as needed at no charge	
8571	700	84644	3006 SPRG	10-Aug-12	N	S	5-Feb-13	5-Feb-13	Fired on Safe Release	Could Not Duplicate Concern	298477	F	Per Ilion, will replace TPA, check over and test fire at no charge under warranty	
8572	700	25789	2506 REM	28-Jun-96	N	S	5-Feb-13	5-Feb-13	Fired on Safe Release	Altered Adjustments or Components	299304	F	Replace TPA, clean and test at 1/2 normal cost	
8573	700	n/a	243 WIN	1-Apr-69	N	PD/S	5-Feb-13	5-Feb-13	Fired With Safe ON	Altered Adjustments or Components	299267	F	Per Ilion, replace TPA and test at BLSM program price	
8574	600	n/a	308 WIN	1-Jul-65	Y	S	5-Feb-13	5-Feb-13	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	299305	F	Replace TPA, clean and test under recall at no charge	
8575	700	84543	2506 REM	2-Apr-12	N	S	5-Feb-13	5-Feb-13	Fired on Bolt Closing	Could Not Duplicate Concern	298482	F	Per Ilion, replace TPA, check over and test at no charge	
8577	700	27255	300 WSM	21-Aug-09	N	S	5-Feb-13	6-Mar-13	Fired on Safe Release	Could Not Duplicate Concern	303330	F	Per Ilion - Replace TA @ n/c - goodwill	

RAC001152

## Confidential

8582	597	26515	22 LR	6-Sep-12	N	S	7-Feb-13	7-Feb-13	Went Automatic	Could Not Duplicate Concern	298883	F	Per Ilion, check over completely, repair as needed at no charge under warranty
8583	700	n/a	7MM REM MA	10-Jul-80	N	S	7-Feb-13	7-Feb-13	Safety not working properly	Altered Adjustments or Components	299656	F	Per Ilion, replace TPA, clean and test at BLSM program price
8584	887	82502	12 GA	8-Oct-10	N	S	7-Feb-13	21-Feb-13	Fired Out of Battery	Sent in for Evaluation	299630	F	Replace w/82502 in exchange @ n/c
8585	770	85633	3006 SPRG	28-Dec-09	N	S	7-Feb-13	7-Feb-13	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	299626	F	Per Ilion, offer to replace TPA, clean and test at no charge
8586	700	n/a	270 WIN	1-Mar-70	N	S	7-Feb-13	7-Feb-13	Fired on Bolt Closing	Improper Maintenance	299658	F	Per Ilion, replace TPA, clean, test at BLSM program price
8587	700	84206	223 REM	8-May-09	N	S	7-Feb-13	7-Feb-13	Fired on Bolt Closing	Could Not Duplicate Concern	299659	F	Per Ilion, could not duplicate concern
8589	700	25709	308 WIN	27-Apr-09	N	S	8-Feb-13	8-Feb-13	Fired on Bolt Closing	Could Not Duplicate Concern	299018	F	Per Ilion, will replace TPA, check over and test at no charge as goodwill
8591	700	n/a	3006 SPRG	1-Sep-71	N	S	8-Feb-13	8-Feb-13	Fired on Safe Release	Improper Maintenance	299808	F	Replace TPA, clean and test at BLSM program price
8592	887	82500	12 GA	22-Jul-09	N	S	8-Feb-13	8-Feb-13	Fired on Bolt Closing	Sent in for Evaluation	299790	F	Per Ilion, check over completely, replace bolt assm, clean and test at no charge
8593	7	24788	308 WIN	21-Jun-96	N	S	8-Feb-13	8-Feb-13	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	299770	F	Per Ilion - Quote to repair @ 1/2 normal cost
8594	700	n/a	308 WIN	1-Nov-77	N	S	8-Feb-13	8-Feb-13	Fired on Safe Release	Altered Adjustments or Components	299837	F	Per Ilion - Quote to repair
8595	BACR	90704	5.56 NATO	30-Jul-10	N	S	8-Feb-13	8-Feb-13	Went Automatic	Sent in for Evaluation	299849	F	Per Ilion - Repair @ n/c
8596	700	26285	7MM08 REM	17-Sep-09	N	S	8-Feb-13	8-Feb-13	Fired on Safe Release	Could Not Duplicate Concern	299832	F	Per Ilion - Replace TA, check over, test @ n/c - goodwill
8599	870	25100	12 GA	25-Jan-12	N	S	11-Feb-13	11-Feb-13	Fired Out of Battery	Sent in for Evaluation	299169	F	Per Ilion - Repair @ n/c - warranty
8601	700	n/a	7MM REM MA	23-Sep-77	N	PD/S	11-Feb-13	22-Feb-13	Fired on Safe Release	Could Not Duplicate Concern	300101	F	Quoted 1/2 normal price for stock and BLSM program price for trigger
8602	700	84207	308 WIN	10-Jun-09	N	S	11-Feb-13	11-Feb-13	Fired on Safe Release	Could Not Duplicate Concern	299947	F	Per Ilion, will replace TPA, clean and test as goodwill gesture
8603	700	27533	M	19-May-98	N	S	11-Feb-13	11-Feb-13	Fired on Bolt Closing	Improper Maintenance	299952	F	Can offer to replace TPA, clean and test at 1/2 normal cost
8604	700	27489	22-250 REM	23-Feb-00	N	S	11-Feb-13	11-Feb-13	Fired on Safe Release	Altered Adjustments or Components	299999	F	Replace TPA, clean and test at 1/2 normal cost
8607	7	85953	22-250 REM	15-Apr-08	N	S	12-Feb-13	12-Feb-13	Fired on Safe Release	Altered Adjustments or Components	300196	F	Per Ilion - Reset TA & test @ n/c - goodwill gesture
8608	770	85654	7MM REM MA	13-Jul-11	N	S	12-Feb-13	12-Feb-13	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	300190	F	Per Ilion - Repair @ n/c - goodwill gesture
8609	600	n/a	350 REM MA	1-Mar-65	Y	S	12-Feb-13	12-Feb-13	Fired on Safe Release	Could Not Duplicate Concern	300256	F	Per Ilion - Replace TA under recall
8610	1911	96323	45 ACP	19-Jan-12	N	S	12-Feb-13	12-Feb-13	Safety not working properly	Sent in for Evaluation	300287	F	Per Ilion - Replace in exchange @ n/c

RAC001153

## Confidential

8614	770	85653	3006 SPRG	23-Mar-11	N	S	14-Feb-13	14-Feb-13	Fired on Safe Release	Could Not Duplicate Concern	299884	F	Per Ilion - Repair @ n/c
8615	700	n/a	7MM REM MA	1-Jul-74	N	S	14-Feb-13	14-Feb-13	Delayed Firing - Firearms	Improper Maintenance	299863	F	Per Ilion - Quote to repair under BLM
8620	700	26933	7 MM REM M	9-Jan-95	N	S	18-Feb-13	18-Feb-13	Fired on Safe Release	Could Not Duplicate Concern	300780	F	Per Ilion - Quote to repair @ 1/2 normal cost
8626	710	27412	7 MM REM M	15-Feb-06	N	S	19-Feb-13	19-Feb-13	Fired With Safe ON	Could Not Duplicate Concern	300316	F	Can offer to replace TPA, clean and test fire at 1/2 normal cost
8628	700	n/a	223 REM	31-Dec-75	N	S	19-Feb-13	19-Feb-13	Fired on Safe Release	Altered Adjustments or Components	300941	F	Replace TPA, clean and test at BLSM program price
8630	700	27017	3006 SPRG	10-Mar-05	N	S	20-Feb-13	25-Feb-13	Fired on Safe Release	Could Not Duplicate Concern	301122	F	Replace TA, clean & test @ n/c - goodwill gesture
8632	700	n/a	7 MM REM A	13-Jun-80	N	S	20-Feb-13	20-Feb-13	Fired on Safe Release	Could Not Duplicate Concern	301212	F	Per Ilion - Quote to repair under BLM
8633	721	n/a	270 WIN	1-Dec-52	Y	S	20-Feb-13	20-Feb-13	Fired on Bolt Closing	AFT MKT STOCK ASSM	301243	F	Per Ilion - Quote to repair under BLM
8638	XIM15-E25	90641	223 - 5.56	16-Aug-11	N	S	21-Feb-13	21-Feb-13	Went Automatic	Sent in for Evaluation	301327	F	Per Ilion, check over completely, repair as needed
8642	600	n/a	243 WIN	4-Dec-77	Y	S	21-Feb-13	12-Apr-13	Fired on Safe Release	Altered Adjustments or Components	307383	F	Repair @ n/c - goodwill gesture
8643	700	n/a	3006 SPRG	1-Mar-75	N	S	22-Feb-13	22-Feb-13	Fired on Bolt Closing	Improper Maintenance	301531	F	Per Ilion - Quote to repair under BLM
8644	1911 R1	96324	45 ACP	21-Jan-13	N	S	22-Feb-13	22-Feb-13	Fired Out of Battery	Could Not Duplicate Concern	301474	F	Per Ilion, check over completely, repair/adjust as needed, test fire at no charge
8646	SB2 ULTRA	72744	22-250 REM	9-Mar-06	N	S	25-Feb-13	25-Feb-13	Action Opened on Firing	MIN LOCK UP ON BBL CATCH	301811	F	Per Ilion - Repair as needed at n/c
8647	700	25869	300 SAVAGE	3-Apr-03	N	S	25-Feb-13	25-Feb-13	Fired on Safe Release	Improper Maintenance	301084	F	Per Ilion, offer to replace TPA, clean and test fire at 1/2 normal cost
8648	700	n/a	7MM REM MA	1-Dec-74	N	S	25-Feb-13	25-Feb-13	Fired on Safe Release	Improper Maintenance	301078	F	Per customer request - returned as received
8649	522	29792	22 LR	23-Jul-96	Y	PD/S	25-Feb-13	25-Feb-13	Went Automatic	Could Not Duplicate Concern	301706	F	Replacing with a 597 .22LR #26550 as a gesture of goodwill
8650	700	25739	308 WIN	19-Dec-12	N	S	25-Feb-13	25-Feb-13	Fired on Bolt Closing	As received Follows Down	301809	F	Replace TPA, check over and test fire at no charge
8651	700	84207	308 WIN	14-Feb-12	N	S	25-Feb-13	25-Feb-13	Fired on Bolt Closing	Altered Adjustments or Components	301642	F	Per Ilion - Repair @ n/c - goodwill
8652	700	26107	300 RUM	31-Jan-00	N	S	25-Feb-13	25-Feb-13	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	301658	F	Return as received
8653	700	n/a	3006 SPRG	1-Oct-69	N	S	25-Feb-13	25-Feb-13	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	301671	F	Per Ilion, replace TPA, clean and test at BLSM program price
8656	597	26516	17 HMR	21-Jul-05	N	S	26-Feb-13	1-Mar-13	Fired Out of Battery	Other - Unspecified or Undetermined - Firearms	301973	F	Replace with #70721
8657	700	n/a	6MM REM	1-May-70	N	S	26-Feb-13	26-Feb-13	Fired on Safe Release	Altered Adjustments or Components	301855	F	Replace TPA, clean and test at BLSM program price
8660	700	n/a	7MM REM MA	1-Apr-83	N	S	27-Feb-13	27-Feb-13	Fired on Safe Release	Altered Adjustments or Components	301577	F	Per Ilion, replace TPA, clean and test fire at BLSM program price

RAC001154

## Confidential

8661	700	27363	3006 SPRG	9-Mar-11	N	S	27-Feb-13	27-Feb-13	Fired on Bolt Closing	Could Not Duplicate Concern	302049	F	Per Ilion, will replace TPA, check over and test at no charge
8663	700	n/a	6MM REM	8-Dec-75	N	S	28-Feb-13	28-Feb-13	Delayed Firing - Firearms	Altered Adjustments or Components	302176	F	Per Ilion, replace TPA, clean and test at BLSM program price
8664	770	85633	3006 SPRG	29-Aug-12	N	S	28-Feb-13	28-Feb-13	Delayed Firing - Firearms	Improper Maintenance	302186	F	Per Ilion, replace TPA, clean and test at no charge
8665	887	82502	12 GA	28-Jan-10	N	S	28-Feb-13	28-Feb-13	Fired With Safe ON	Could Not Duplicate Concern	302181	F	Per Ilion, check over completely, replace TPA, repair, test no charge
8666	700	n/a	270 WIN	9-Oct-75	N	S	28-Feb-13	28-Feb-13	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	302279	F	Replace TPA, clean and test at BLSM price
8668	1187	83609	12GA	5-May-11	N	S	1-Mar-13	1-Mar-13	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	301791	F	Per Ilion, check over completely, replace TPA and test fire at no charge
8669	887	82500	12 GA	22-Jun-12	N	S	1-Mar-13	1-Mar-13	Fired With Safe ON	Could Not Duplicate Concern	302519	F	Replace TPA, check over completely and test fire at no charge
8670	700	n/a	7MM REM MA	1-Oct-71	N	S	1-Mar-13	1-Mar-13	Fired on Bolt Opening	Could Not Duplicate Concern	302537	F	Per Ilion - Quote to repair under BLM
8743	700	n/a	270 WIN	1-May-72	N	S	1-Mar-13	27-Mar-13	Fired on Safe Release	Altered Adjustments or Components	305981	F	Per Ilion, replace TPA, clean and test at BLSM program price
8673	700	n/a	22-250 REM	1-Feb-71	N	S	4-Mar-13	4-Mar-13	Fired on Bolt Closing	Improper Maintenance	302131	F	Per Ilion, replace TPA, clean and test at BLSM program price
8674	700	27271	7MM REM MA	27-Aug-12	N	S	4-Mar-13	4-Mar-13	Fired on Bolt Closing	Could Not Duplicate Concern	302715	F	Per Ilion, replace TPA, check over and test at no charge as goodwill
8677	600	n/a	308 WIN	1-May-71	Y	S	5-Mar-13	5-Mar-13	Fired on Bolt Closing	Improper Maintenance	302076	F	Per Ilion, replace TPA, clean, test at no charge
8682	N/A	N/A			N	S	7-Mar-13	22-May-13	Ammunition Exploded	Other - Unexamined	n/a	A	No product returned for inspection
8683	700	n/a	270 WIN	19-Sep-75	N	S	8-Mar-13	8-Mar-13	Fired on Bolt Opening	Could Not Duplicate Concern	302723	F	Replace TPA, clean, test at BLSM program price
8684	700	85623	300 WIN MA	2-Aug-12	N	S	8-Mar-13	8-Mar-13	Fired on Safe Release	Could Not Duplicate Concern	303851	F	Per Ilion - Replace TA at n/c As a gesture of goodwill, replace TPA, clean and test at no charge
8685	770	85632	270 WIN	17-Nov-08	N	S	8-Mar-13	8-Mar-13	Delayed Firing - Firearms	Could Not Duplicate Concern	303887	F	Per Ilion, replace TPA, check over, test fire at no charge as a gesture of goodwill.
8687	XM15E25	n/a	223-5.56 N	14-Jan-09	N	S	8-Mar-13	8-Mar-13	Went Automatic	Broken or Missing Parts	303908	F	Per Ilion - Repair as needed and test fire
8688	710	27408	270 WIN	26-Apr-02	N	S	8-Mar-13	27-Mar-13	Fired on Bolt Closing	Could Not Duplicate Concern	305661	F	Check over, repair, adjust, clean and test as needed at no charge
8689	700	27097	7MM REM MA	12-Apr-12	N	S	11-Mar-13	11-Mar-13	Fired on Bolt Closing	Could Not Duplicate Concern	303290	F	Per Ilion, replace TPA, check over, test fire at no charge as a gesture of goodwill.
8690	700	27317	270 WIN	13-Jun-03	N	S	11-Mar-13	11-Mar-13	Fired on Safe Release	Could Not Duplicate Concern	304047	F	Per Ilion, offer to replace TPA, clean and test fire at \$20 + shipping
8693	887	82502	12 GA	6-Aug-12	N	S	12-Mar-13	12-Mar-13	Fired on Safe Release	Could Not Duplicate Concern	304183	F	Per Ilion - Repair at n/c
8694	700	n/a	3006 SPRG	15-Feb-77	N	S	12-Mar-13	12-Mar-13	Delayed Firing - Firearms	Improper Maintenance	304143	F	Per Ilion - Quote to repair under BLM

RAC001155

## Confidential

8695	700	n/a	3006 SPRG	7-Feb-77	N	S	12-Mar-13	12-Mar-13	Fired on Safe Release	Improper Maintenance	304144	F	Per Ilion - Quote to repair under BLM
			7MM08 REM	31-Jan-90	N	S	12-Mar-13	12-Mar-13	Unexplained Discharge - No Mention of Safety Position				
8696	700	25799	300 H&H MA	1-Apr-60	Y	S	13-Mar-13	13-Mar-13	Fired on Safe Release	Improper Maintenance	304152	F	Per Ilion - Quote to repair @ 1/2 normal cost
8698	721	n/a	3006 SPRG	1-Jul-76	N	S	13-Mar-13	13-Mar-13	Fired on Bolt Opening	Could Not Duplicate Concern	304241	F	Per Ilion - Quote to repair under BLM
8699	700	n/a	3006 SPRG	1-Jul-76	N	S	13-Mar-13	13-Mar-13	Fired on Safe Release	Could Not Duplicate Concern	304307	F	Per Ilion - Quote to repair under BLM
8701	722	n/a	n/a		Y	S	14-Mar-13	14-Mar-13	Fired on Safe Release	Altered Adjustments or Components	304374	F	Per Ilion - Quote to repair @ 1/2 normal cost
8702	660	n/a	6MM REM	1-May-69	Y	S	14-Mar-13	14-Mar-13	Fired on Safe Release	Improper Maintenance	304443	F	Per Ilion - Replace TA, clean & test under recall at n/c
6170	700	n/a	3006 SPRG	1-Sep-74	N	S	15-Mar-13	15-Mar-13	Fired on Safe Release	Improper Maintenance	304601	F	Per Ilion - Quote to repair under BLM
8704	710	27412	7MM REM MA	13-Jun-05	Y	S	15-Mar-13	15-Mar-13	Fired on Safe Release	Broken or Missing Parts	304251	F	Per Ilion - Repair @ n/c
8705	XM15-E2S	90629	223 - 5.56	27-Sep-11	N	S	15-Mar-13	15-Mar-13	Defective Parts	Could Not Duplicate Concern	304615	F	Per Ilion - Repair @ n/c
8706	700	25791	270 WIN	31-Oct-91	N	S	15-Mar-13	15-Mar-13	Delayed Firing - Firearms	Improper Maintenance	304621	F	Per Ilion - Quote to repair @ 1/2 normal cost
8707	700	25793	3006 SPRG	19-Apr-89	N	S	15-Mar-13	15-Mar-13	Fired on Bolt Closing	Could Not Duplicate Concern	304568	F	Per Ilion - Quote to repair @ 1/2 normal cost
8708	700	n/a	222 REM	1-Dec-71	N	S	15-Mar-13	15-Mar-13	Fired on Bolt Closing	Altered Adjustments or Components	304566	F	Per Ilion - Quote to repair under BLM
8711	700	27094	270 WIN	19-Jun-12	N	S	18-Mar-13	18-Mar-13	Fired on Safe Release	Could Not Duplicate Concern	304577	F	Per Ilion - Replace TA @ n/c - goodwill gesture
8713	700	85565	22-250 REM	3-Feb-12	N	S	18-Mar-13	18-Mar-13	Fired on Safe Release	Could Not Duplicate Concern	304866	F	Per Ilion - Replace TA, check over & test at n/c
8714	710	27410	3006 SPRG	22-May-03	Y	S	18-Mar-13	20-Mar-13	Fired With Safe ON	Broken or Missing Parts	304831	F	Replace w/85633 in exchange @ n/c
8717	600	n/a	6MM REM	19-Oct-77	Y	S	19-Mar-13	19-Mar-13	Fired on Safe Release	Could Not Duplicate Concern	305039	F	Replace TPA, clean and test at BLSM program price
8720	597	26550	22 LR	28-Jul-08	N	S	20-Mar-13	20-Mar-13	Fired Out of Battery	Other - Unspecified or Undetermined - Firearms	305282	F	Per Ilion, check over completely, repair as needed
8721	700	n/a	6MM REM	1-Aug-69	N	S	20-Mar-13	22-Mar-13	Fired on Safe Release	Could Not Duplicate Concern	305249	F	Per Ilion - Quote to repair under BLM
8726	1911	96343	45 AUTO	18-May-12	N	S	21-Mar-13	21-Mar-13	Firing Pin Follows Down	Sent in for Evaluation	305447	F	Per Ilion - Repair @ n/c - warranty
8732	660	n/a	222 REM	1-Jan-68	Y	S	25-Mar-13	25-Mar-13	Fired on Safe Release	Improper Maintenance	305766	F	Per Ilion, replace TPA, clean and test under recall at no charge
8736	600	n/a	243 WIN	1-Feb-77	Y	S	25-Mar-13	25-Mar-13	Delayed Firing - Firearms	Improper Maintenance	305726	F	Per Ilion - Quote to repair under BLM
8742	870	26927	12 GA	29-Mar-07	N	S	26-Mar-13	26-Mar-13	Defective Parts	Defective Trigger Assembly	305982	F	Per Ilion - Repair @ n/c
8740	700	n/a	7MM MAG	21-Mar-79	N	PD/S	26-Mar-13	14-Feb-14	Fired on Bolt Closing	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
8744	XM15-E2S	n/a	223/5.56	26-Nov-08	N	S	27-Mar-13	27-Mar-13	Went Automatic	Could Not Duplicate Concern	306033	F	Check over completely, repair as needed and test fire at no charge
8745	40X	27225	308 WIN	30-Nov-11	N	S	27-Mar-13	27-Mar-13	Fired on Safe Release	Could Not Duplicate Concern	306070	F	Per Ilion - Replace TA & test fire @ n/c
8747	700	n/a	264 WIN MA	1-Apr-63	N	S	28-Mar-13	28-Mar-13	Fired on Bolt Closing	Could Not Duplicate Concern	306184	F	Per Ilion - Quote to repair under BLM
8749	700	27480	7MM MAG	3-May-00	N	S	28-Mar-13	14-Feb-14	Fired on Safe Release	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam

RAC001156

## Confidential

8752	Carbon 15 Pistol	n/a	223/5.56		Y	PI/S	1-Apr-13	4-Jun-13	Defective Parts	Broken or Missing Parts	304640	F	Per Release - 90289 is replacement in exchange @ n/c
8753	700	27580	50 CAL	8-Aug-97	Y	S	1-Apr-13	16-Apr-13	Fired on Bolt Closing	Broken or Missing Parts	306299	F	Ordering #84275 as replacement
8754	700	25630	270 WIN	26-Jul-87	N	S	1-Apr-13	1-Apr-13	Safety not working properly	Altered Adjustments or Components	306306	F	Per Ilion, can offer to replace TPA, clean and test at 1/2 normal cost
8755	700	n/a	7MM REM MA	1-Sep-72	N	S	1-Apr-13	1-Apr-13	Fired on Safe Release	Altered Adjustments or Components	306303	F	Per Ilion, replace TPA, clean and test at BLSM program price
8759	700	n/a	3006 SPRG	9-Jul-76	N	S	2-Apr-13	2-Apr-13	Delayed Firing - Firearms	Improper Maintenance	306443	F	Per Ilion, replace TPA, clean and test at BLSM program price
8760	660	n/a	308 WIN	1-Feb-69	Y	S	2-Apr-13	2-Apr-13	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	306490	F	Per Ilion, check over completely, replace TPA, clean, test at no charge
8761	700	25614	243 WIN	10-Apr-89	N	S	2-Apr-13	2-Apr-13	Fired on Bolt Closing	Improper Maintenance	306504	F	Replace TPA, clean and test at 1/2 normal cost
8765	700	85479	308 WIN	16-Dec-11	N	S	3-Apr-13	3-Apr-13	Fired on Bolt Closing	Could Not Duplicate Concern	306089	F	Per Ilion: Replace TA @ n/c - goodwill gesture
8768	600	n/a	308 WIN	1-Feb-66	Y	S	4-Apr-13	4-Apr-13	Fired on Safe Release	Improper Maintenance	306770	F	Per Ilion: Replace TA, clean & test under recall @ n/c
8770	700	29675	2506 REM	11-Sep-00	N	S	4-Apr-13	4-Apr-13	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	306895	F	Per Ilion, offer to replace TPA, clean, test at 1/2 normal cost
8771	660	n/a	243 WIN	1-Jan-68	Y	S	4-Apr-13	4-Apr-13	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	306812	F	Per Ilion, replace TPA, clean and test under recall at no charge
8772	887	82500	12 GA	14-Dec-11	N	PD/S	4-Apr-13	4-Apr-13	Fired Out of Battery	Broken or Missing Parts	306723	F	Per Ilion, check over completely, repair, update, test at no charge
8773	700	n/a	22-250 REM	1-Dec-77	N	S	4-Apr-13	4-Apr-13	Fired on Bolt Closing	Could Not Duplicate Concern	306776	F	Per Ilion - Quote to repair under BLM
8775	700	27363	3006 SPRG	6-Dec-04	N	PI/S	4-Apr-13	17-Jun-13	Fired on Safe Release	Improper Maintenance	311757	F	Replace TA, clean, test @ n/c goodwill gesture
8779	700	n/a	270 WIN	1-Jan-65	N	S	5-Apr-13	5-Apr-13	Fired on Bolt Closing	Could Not Duplicate Concern	306971	F	Per Ilion, replace TPA, clean, test at BLSM program price
8780	700	26404	243 WIN	24-May-00	N	S	8-Apr-13	8-Apr-13	Fired on Bolt Closing	Could Not Duplicate Concern	307197	F	Per Ilion - Quote to repair @ 1/2 normal cost
8781	700	n/a	2506 REM	31-Mar-78	N	S	8-Apr-13	8-Apr-13	Fired on Safe Release	Could Not Duplicate Concern	307165	F	Per Ilion - Quote to repair under BLM
8782	870	25077	12 GA	24-Sep-09	N	S	8-Apr-13	8-Apr-13	Action Opened on Firing	Could Not Duplicate Concern	307184	F	Per Ilion - Check over completely, test fire @ n/c - goodwill
8785	700	25739	308 WIN	4-Aug-10	N	S	8-Apr-13	1-May-13	Fired on Safe Release	Could Not Duplicate Concern	309552	F	Per Ilion - Replace TA, clean & test - goodwill gesture
8786	700	n/a	22-250 REM	1-Jun-77	N	PD/S	8-Apr-13	24-Apr-13	Fired on Bolt Closing	Altered Adjustments or Components	308903	F	Per Ilion, replace TPA, clean and test under BLSM program price
8787	700	n/a	243 WIN	1-Sep-81	N	S	9-Apr-13	9-Apr-13	Fired on Bolt Closing	Could Not Duplicate Concern	306521	F	Per Ilion, replace TPA, clean and test fire at BLSM program price

RAC001157

Confidential

8789	700	27111	300 RUM	3-Sep-05	N	S	9-Apr-13	9-Apr-13	Fired on Bolt Closing	Altered Adjustments or Components	307298	F	Offer to replace TPA, clean and test at 1/2 normal cost	
8790	700	27387	300 WIN	MA	8-Apr-13	N	S	9-Apr-13	9-Apr-13	Fired on Safe Release	Could Not Duplicate Concern	307417	F	Per Ilion, replace in exchange ramach 27387
8791	700	26096	300 RUM	24-Feb-00	N	S	10-Apr-13	10-Apr-13	Fired on Safe Release	Improper Maintenance	307385	F	Per Ilion, can offer to replace TPA, clean and test at 1/2 normal cost	
8795	7	24741	7MM/08 REM	16-Oct-95	N	S	11-Apr-13	11-Apr-13	Fired on Safe Release	Could Not Duplicate Concern	306878	F	Per Ilion - Replace TA, clean & test @ n/c	
8796	700	27527	204 RUG	15-Sep-04	N	S	11-Apr-13	11-Apr-13	Safety not working properly	Altered Adjustments or Components	306656	F	Offer to replace TPA, check over and test fire at 1/2 normal cost	
8799	700	84218	308 WIN	27-Jun-08	N	S	12-Apr-13	15-Apr-13	Fired on Safe Release	As received Follows Down	307049	F	Replace with a new rifle of same model/caliber	
8801	870	25561	20 GA	14-Aug-12	N	S	15-Apr-13	15-Apr-13	Other - Firearms	Could Not Duplicate Concern	307778	F	Replace with new 85561 to restore confidence	
8802	700	25813	3006 SPRG	23-Jan-01	N	S	15-Apr-13	15-Apr-13	Fired on Safe Release	Improper Maintenance	307837	F	Quote to repair at 50% discount	
8805	CARBON 15	90689	223/5.56	30-Dec-10	N	S	16-Apr-13	16-Apr-13	Went Automatic	Broken or Missing Parts	307881	F	Per Ilion - Repair @ n/c	
8807	700	n/a	6MM REM	1-May-74	N	S	17-Apr-13	17-Apr-13	Fired on Safe Release	Altered Adjustments or Components	307957	F	Per Ilion - Quote to repair under BLM	
8808	XP100	25387	260 REM	18-Nov-97	Y	S	17-Apr-13	17-Apr-13	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	308113	F	Per Ilion - Quote to repair @ 1/2 normal cost	
8809	788	n/a	22-250 REM	10-Mar-65	Y	S	17-Apr-13	17-Apr-13	Fired on Bolt Closing	Improper Assembly by Customer	308101	F	Per Ilion, quote to repair, adjust and clean as needed, test fire	
8810	770	85651	243 WIN	30-Oct-12	N	S	17-Apr-13	18-Apr-13	Fired on Bolt Opening	Fired on Bolt Opening	308112	F	Replacing with new 85651 on SNC order	
8811	700	n/a	6MM REM	17-Sep-78	N	S	17-Apr-13	23-Apr-13	Fired on Safe Release	Could Not Duplicate Concern	308687	F	Per Ilion, replace TPA, clean and test at BLSM program price	
8814	700	n/a	22-250 REM	1-Jan-72	N	PD/S	17-Apr-13	2-May-13	Fired on Bolt Closing	Improper Maintenance	309376	F	Repair @ n/c - goodwill gesture	
8816	770	85633	3006 SPRG	15-Apr-11	N	S/C	18-Apr-13	18-Apr-13	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	308283	F	Per Ilion, replace TPA and bolt assm, test fire at no charge as goodwill	
8820	700	25793	3006 SPRG	1-Oct-85	N	S	18-Apr-13	18-Apr-13	Delayed Firing - Firearms	Improper Maintenance	308217	F	Quote to repair @ 1/2 normal cost	
8825	40X	87920	308 WIN	14-Apr-10	N	S	22-Apr-13	22-Apr-13	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	308507	F	Per Ilion - Repair as needed at n/c	
8827	700	n/a	22-250 REM	1-Feb-75	N	S	22-Apr-13	22-Apr-13	Fired on Safe Release	Altered Adjustments or Components	308665	F	Per Ilion - Quote to repair under BLM	
8829	710	27412	7MM REM	10-Jun-05	Y	S	22-Apr-13	25-Oct-13	Fired on Safe Release	Broken or Missing Parts	324000	F	Per Release: Replace gun w/Item# 85635	
8833	721	n/a	3006 SPRG	1-Aug-49	Y	S	23-Apr-13	23-Apr-13	Fired on Bolt Closing	Could Not Duplicate Concern	308739	F	Replace TPA, clean and test at BLSM program price	
8834	700	n/a	270 WIN	1-May-62	N	S	23-Apr-13	23-Apr-13	Fired on Safe Release	Could Not Duplicate Concern	308740	F	Replace TPA, clean and test at BLSM program price	
8836	721	n/a	3006 SPRG	1-May-56	Y	S	23-Apr-13	23-Apr-13	Fired on Safe Release	Altered Adjustments or Components	308770	F	Per Ilion - Quote to repair under BLM	

RAC001158

## Confidential

8838	700	n/a	223 REM	1-Jan-98	N	S	23-Apr-13	10-May-13	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	310406	F	Per Ilion, can offer to replace TPA, clean, test at 1/2 normal cost
8840	870	24952	12 GA	26-Oct-00	N	S	24-Apr-13	24-Apr-13	Fired With Safe ON	Aft Mkt Safety	308771	F	Per Ilion, offer to replace TPA at 1/2 normal cost
8841	597	26513	22 LR	9-Feb-13	N	S	24-Apr-13	24-Apr-13	Went Automatic	Could Not Duplicate Concern	308830	F	Per Ilion - Repair as needed - warranty
8842	700	n/a	3006 SPR	26-Feb-80	N	S	24-Apr-13	24-Apr-13	Fired on Bolt Closing	Improper Maintenance	308788	F	Per Ilion, replace trigger assembly, clean and test fire at BLSM price
8845	700	n/a	243 WIN	1-Sep-68	N	S	24-Apr-13	24-Apr-13	Fired on Safe Release	Improper Maintenance	308789	F	Replace TPA, clean and test at BLSM program price
8846	700	n/a	7MM REM MA	1-Jun-75	N	S	24-Apr-13	24-Apr-13	Fired on Safe Release	Could Not Duplicate Concern	308787	F	Per Ilion, replace TPA, clean, test at BLSM program price
8851	700	n/a	7MM REM MA	4-Jun-75	N	S	26-Apr-13	26-Apr-13	Fired on Safe Release	Could Not Duplicate Concern	309019	F	Per Ilion, replace TPA, clean and test at BLSM program price
8855	XM15E25	n/a	223/5.56	21-Jul-06	N	S	26-Apr-13	26-Apr-13	Other - Firearms	Could Not Duplicate Concern	309014	F	Per Ilion, check over completely, repair as needed at no charge
8857	770	n/a	243 WIN		N	PI/S	26-Apr-13	9-May-13	Unexplained Discharge - No Mention of Safety Position	No Fault Found	n/a	F	Per Derek Watkins - No Fault Found
8861	700	85541	300 WIN MA	6-Feb-13	N	S	29-Apr-13	29-Apr-13	Fired on Bolt Closing	Could Not Duplicate Concern	309191	F	Gun forwarded to Derek Watkins in E-town for exam
8864	700	26133	7MM REM MA	24-Jun-00	N	S	30-Apr-13	30-Apr-13	Fired on Bolt Closing	Could Not Duplicate Concern	309377	F	Per Ilion, can offer to replace TPA, clean and test at 1/2 normal cost
8866	CARBON 15	90689	223/5.56	5-Mar-13	N	S	30-Apr-13	30-Apr-13	Fired With Safe ON	Fired on safe	309271	F	Per Ilion, repair/adjust as needed, test fire at no charge under warranty
8868	700	27518	243 WIN	9-Jun-00	N	S	30-Apr-13	30-Apr-13	Fired on Bolt Closing	Improper Maintenance	309324	F	Per Ilion, offer to replace TPA, clean and test at 1/2 normal cost
8869	700	n/a	3006 SPRG		N	PD/S	30-Apr-13	18-Feb-14	Fired on Safe Release	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
8875	700	n/a	270 WIN	2-Jun-81	N	S	2-May-13	2-May-13	Fired on Safe Release	Could Not Duplicate Concern	309422	F	Replace TPA, clean, test at BLSM program price
8876	700	n/a	3006 SPRG	1-Jun-83	N	S	2-May-13	2-May-13	Fired on Safe Release	Altered Adjustments or Components	309155	F	Replace TPA, clean and test at 1/2 normal cost
8881	700	27477	308 WIN	22-Feb-06	N	S	6-May-13	6-May-13	Fired on Safe Release	Could Not Duplicate Concern	309919	F	Can offer to replace TPA, clean and test at 1/2 normal cost
8882	700	n/a	3006 SPRG	1-Jul-63	N	S	6-May-13	6-May-13	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	309962	F	Per Ilion, replace TPA, clean and test at BLSM program price
8884	597	26562	22 LR	12-May-05	N	S	7-May-13	7-May-13	Fired Out of Battery	Other - Unspecified or Undetermined - Firearms	310020	F	Per Ilion, check over completely, repair as needed at no charge
8885	CARBON 15	90689	223/5.56	10-Nov-12	N	S	7-May-13	7-May-13	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	310061	F	Check over completely, repair as needed at no charge under warranty
8887	700	n/a	3006 SPRG	1-Jun-69	N	PD/S	7-May-13	4-Jun-13	Fired on Safe Release	Could Not Duplicate Concern	311839	F	BLM @ n/c - goodwill gesture

RAC001159

## Confidential

8890	770	85657	7MM REM MA		27-Jun-11	N	S	8-May-13	8-May-13	Fired With Safe ON	Could Not Duplicate Concern	310186	F	Per Ilion, will replace TPA, check over and test fire at no charge
8892	710	27410	3006 SPRG	15-Sep-05	N	S	8-May-13	8-May-13	Fired on Safe Release	Altered Adjustments or Components	310218	F	Per Ilion, offer to replace TPA, clean and test at 1/2 normal cost	
8895	600	n/a	308 WIN	1-Jan-66	Y	S	9-May-13	9-May-13	Fired on Bolt Closing	Improper Maintenance	310260	F	Per Ilion, replace TPA, clean and test under recall at no charge	
8896	700	n/a	308 WIN	1-Sep-71	N	S	9-May-13	9-May-13	Fired on Bolt Opening	Altered Adjustments or Components	310358	F	Per Ilion, replace TPA, clean and test at BLSM program price	
8900	597	26516	17 HMR	11-Nov-04	N	S	10-May-13	15-May-13	Fired Out of Battery	Other - Unspecified or Undetermined - Firearms	310440	F	Convert to .22 WMR	
8902	710	27418	243 WIN	18-Jul-06	N	S	10-May-13	10-May-13	Fired on Bolt Closing	Could Not Duplicate Concern	309547	F	Per Ilion, offer to repair/adjust/clean as needed and test fire at 1/2 normal cost	
8905	700	25709	308 WIN	25-Feb-02	N	S	10-May-13	10-May-13	Fired on Safe Release	Improper Maintenance	310378	F	Per Ilion, offer to replace TPA, clean and test at 1/2 cost	
8909	700	25793	3006 SPRG	4-Jan-90	N	S	13-May-13	13-May-13	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	310609	F	Per Ilion, offer to replace TPA, clean and test at 1/2 normal cost	
8913	700	n/a	300 WIN MA	1-Dec-69	N	S	14-May-13	14-May-13	Fired on Bolt Opening	Improper Maintenance	310632	F	Replace TPA, clean and test under BLSM program	
8914	700	n/a	270 WIN	17-Jun-81	N	S	15-May-13	15-May-13	Fired on Safe Release	Could Not Duplicate Concern	310762	F	Per Ilion, replace TPA, clean and test at BLSM program price	
8915	600	n/a	308 WIN	1-Sep-66	Y	S	15-May-13	15-May-13	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	310865	F	Replace TPA, clean and test under recall at no charge	
8916	742	n/a	3006 SPRG	27-Apr-79	Y	S	15-May-13	15-May-13	Fired With Safe ON	Improper Maintenance	310872	F	Per Ilion - Clean & Adjust at n/c	
8922	700	n/a	308 WIN	1-Aug-66	N	S	17-May-13	17-May-13	Fired on Bolt Closing	Improper Maintenance	310996	F	Per Ilion - Quote to repair under BLM	
8925	1100	n/a	12 GA	1-Nov-94	N	S	17-May-13	17-May-13	Fired on Bolt Closing	Could Not Duplicate Concern	311099	F	Per Ilion, repair as needed at 1/2 normal cost as goodwill gesture	
8928	700	n/a	3006 SPR	1-Apr-67	N	S	17-May-13	15-Jul-13	Fired on Safe Release	Sent in for Evaluation	314735	F	Per Ilion - Quote to repair under BLM	
8929	H&R Handi-Rifle SB2	72582	45/70 GOV	4-Mar-11	N	S	21-May-13	21-May-13	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	311248	F	Per Ilion, check over completely, repair as needed at 1/2 normal cost	
8933	870	26960	12 GA		N	PI/S	21-May-13	28-Jan-14	Fired With Safe ON	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam	
8934	700ML	27572	50 CAL	30-Jan-98	Y	S	22-May-13	12-Jun-13	Fired on Safe Release	Broken or Missing Parts	313119	F	Per Ilion - Repair & clean @ n/c	
8938	700	n/a	243 WIN	1-May-69	N	S	29-May-13	29-May-13	Fired on Bolt Closing	Altered Adjustments or Components	311860	F	Per Ilion - Quote to repair under BLM	
8939	1911 R1	96323	45 ACP	27-Mar-12	N	S	29-May-13	29-May-13	Defective Parts	Sent in for Evaluation	311742	F	Per Ilion, repair/adjust as needed at no charge	
8942	700	n/a	7MM REM MA	1-May-67	N	S	29-May-13	29-May-13	Fired on Safe Release	Improper Maintenance	311662	F	Per Ilion - Quote to repair under BLM	
8943	700	n/a	3006 SPRG	1-May-69	N	S	29-May-13	29-May-13	Fired With Safe ON	Improper Maintenance	311976	F	Per Ilion - Quote to repair under BLM	

RAC001160

## Confidential

8947	M 24	25705	7.62	20-Jan-06	N	S	30-May-13	30-May-13	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	312023	F	Per Ilion, to restore confidence, replace trigger assembly, check over and test fire
8953	H&R Handi-Rifle	72790	17 HMR	3-Mar-10	N	Pl/S	3-Jun-13	24-Jun-13	Action Opened on Firing	Sent in for Evaluation	311787	F	Repair as needed @ n/c
8954	721	n/a	3006 SPRG	1-Jun-51	Y	S	3-Jun-13	3-Jun-13	Fired on Bolt Closing	Altered Adjustments or Components	312249	F	Replace TPA, clean and test at BLSM program price
8958	700	84205	300 BLACKO	29-Nov-12	N	S	4-Jun-13	4-Jun-13	Bullet Lodged in Barrel	Inadequate or Lack of Powder	312298	F	Per Ilion, replace barrel, receiver assm and test at no charge
8963	700	n/a	6MM REM	1-Nov-67	N	S	5-Jun-13	5-Jun-13	Fired on Bolt Closing	Improper Maintenance	312514	F	Per Ilion, replace TPA, clean and test at BLSM program price
8967	700	n/a	3006 SPRG	24-Oct-88	N	S	6-Jun-13	6-Jun-13	Fired on Bolt Closing	Improper Maintenance	312560	F	Per Ilion, offer to replace TPA, clean and test at 1/2 normal cost
8969	721	n/a	3006 SPRG	1-May-52	Y	S	6-Jun-13	6-Jun-13	Fired on Safe Release	Altered Adjustments or Components	312527	F	Per Ilion, replace TPA, clean and test at BLSM program price
8970	722	n/a	222 REM	1-Mar-51	Y	S	7-Jun-13	7-Jun-13	Fired on Bolt Closing	Altered Adjustments or Components	312814	F	Per Ilion, replace TPA, clean, test at BLSM program price.
8973	700	27518	243 WIN	10-Dec-98	N	S	10-Jun-13	10-Jun-13	Fired on Safe Release	Altered Adjustments or Components	312965	F	Per Ilion, offer to replace TPA, clean and test at 1/2 normal cost
8981	700	25791	270 WIN	1-Mar-84	N	S	11-Jun-13	11-Jun-13	Fired on Safe Release	Could Not Duplicate Concern	313109	F	Per Ilion, offer to replace TPA, clean and test at 1/2 normal cost
8982	597	80877	22 LR	28-Jun-12	N	S	11-Jun-13	13-Jun-13	Jamming/Feeding issues	Other - Unspecified or Undetermined - Firearms	313019	F	Replacing with new 597
8983	700	25793	3006 SPR	6-Jun-96	N	S	11-Jun-13	14-Apr-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
8985	700	25801	17 REM	6-Dec-02	N	S	11-Jun-13	14-Apr-15	Fired on Bolt Closing	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
8987	700	n/a	243 WIN	1-Apr-64	N	S	13-Jun-13	13-Jun-13	Fired on Bolt Closing	Could Not Duplicate Concern	313301	F	Per Ilion, replace TPA, clean and test at BLSM program price
8991	660	n/a	350 REM MA	1-Mar-69	Y	S	18-Jun-13	18-Jun-13	Fired on Bolt Closing	Altered Adjustments or Components	313573	F	Per Ilion - Replace TA, clean & test at n/c
8992	597	26560	22 WMR	6-Sep-07	N	Pl/S	18-Jun-13	20-Aug-13	Fired Out of Battery	Other - Unspecified or Undetermined - Firearms	313622	F	Per Release: Replace gun w/Item# 84370
8994	722	n/a	222 REM	1-Feb-53	Y	S	19-Jun-13	19-Jun-13	Fired on Safe Release	Improper Maintenance	313688	F	Per Ilion - Quote to repair under BLM
8995	700	25795	308 WIN	1-Nov-85	N	S	19-Jun-13	21-Jun-13	Fired on Bolt Closing	Improper Maintenance	313717	F	Per Ilion - Quote to repair @ 1/2 normal cost
8996	700	86447	7.62 NATO	14-Feb-13	N	S	19-Jun-13	21-Jun-13	Fired on Safe Release	Could Not Duplicate Concern	313739	F	Replace TA, clean & test to restore confidence in rifle at no charge - goodwill gesture
8999	700	86447	7.62 NATO	14-Feb-13	N	S	19-Jun-13	21-Jun-13	Fired on Safe Release	Could Not Duplicate Concern	313751	F	Replace TA, clean & test to restore confidence in rifle at no charge - goodwill gesture
9004	700	84203	308 WIN	29-Jan-13	N	S	24-Jun-13	23-Jul-13	Fired on Bolt Closing	No Fault Found	n/a	F	Per Derek Watkins - Rifle is not malfunctioning
9006	710	27410	3006 SPRG	29-Sep-05	Y	S	25-Jun-13	25-Jun-13	Fired on Safe Release	Could Not Duplicate Concern	314131	F	Per Ilion - Replace TA @ n/c - goodwill gesture

RAC001161

## Confidential

9009	700	25807	300 WIN MA	12-Apr-95	N	S	26-Jun-13	26-Jun-13	Fired With Safe ON	Could Not Duplicate Concern	314172	F	Per lliion - Quote to repair @ 1/2 normal cost
9010	700	n/a	270 WIN	1-Nov-71	N	S	26-Jun-13	26-Jun-13	Fired on Safe Release	Could Not Duplicate Concern	314224	F	Per lliion - Quote to repair under BLM
9016	700	n/a	270 WIN	1-Jun-78	N	S	28-Jun-13	28-Jun-13	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	314410	F	Per lliion, quote to repair BLM
9017	700	84017	300 WSM	5-Feb-10	N	S	28-Jun-13	28-Jun-13	Fired on Bolt Closing	Could Not Duplicate Concern	314308	F	Replace TPA, check over and test at no charge
9028	XM15-E25	N/A	223/5.56	26-Nov-08	N	S	12-Jul-13	25-Jul-13	Went Automatic	Could Not Duplicate Concern	316150	F	Replacing trigger at no charge
9030	700	25793	3006 SPRG	1-Apr-84	N	S	15-Jul-13	15-Jul-13	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	314864	F	Offer to replace trigger assembly, clean, and test at 50% discount
9032	770	85630	243 WIN	14-Mar-07	N	S	15-Jul-13	15-Jul-13	Fired on Safe Release	Sent in for Evaluation	315163	F	Per lliion, repair at no charge
9033	700	n/a	7MM REM MA	20-Oct-76	N	S	15-Jul-13	15-Jul-13	Fired on Safe Release	Altered Adjustments or Components	315099	F	Per lliion, quote to repair BLM
9035	700	n/a	6MM REM	1-Sep-78	N	S	15-Jul-13	15-Jul-13	Fired on Safe Release	Could Not Duplicate Concern	314607	F	Per lliion, quote to repair BLM
9036	XM15-E25	90391	223/5.56	25-Mar-13	N	S	15-Jul-13	15-Jul-13	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	314816	F	Per lliion - Quote to repair @ 50% discount
9039	600	n/a	243 WIN		Y	S	16-Jul-13	16-Jul-13	Fired on Safe Release	Altered Adjustments or Components	315470	F	Per lliion, repair at no charge
9044	700	n/a	3006 SPRG	1-Oct-72	N	S	17-Jul-13	17-Jul-13	Fired on Safe Release	Could Not Duplicate Concern	315522	F	Per lliion, quote to repair BLM
9045	700	n/a	270 WIN	1-Jan-67	N	S	18-Jul-13	18-Jul-13	Fired on Safe Release	Altered Adjustments or Components	314861	F	Per lliion, quote to repair BLM
9046	7	29539	223 REM	26-Apr-04	N	S	18-Jul-13	18-Jul-13	Fired on Bolt Closing	Altered Adjustments or Components	315248	F	Offer to replace trigger assembly, clean, and test at 50% discount
9047	700	n/a	375 H&H MA	1-Jun-77	N	S	18-Jul-13	18-Jul-13	Fired on Bolt Opening	Could Not Duplicate Concern	315257	F	Per lliion, quote to repair BLM
9049	597	26550	22 LR	10-Aug-10	N	S	18-Jul-13	18-Jul-13	Fired Out of Battery	Other - Unspecified or Undetermined - Firearms	315601	F	Repair as needed at no charge
9050	514	80808	22 RF	21-Sep-11	N	S	18-Jul-13	18-Jul-13	Unexplained Discharge - No Mention of Safety Position	Sent in for Evaluation	315151	F	Check over completely and repair as needed at no charge
9053	700	n/a	3006 SPRG	1-Sep-73	N	S	19-Jul-13	19-Jul-13	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	314364	F	Replace TPA, clean, and test fire under BLP for \$20 plus S&H.
9054	700	n/a	3006 SPRG	1-Nov-83	N	S	19-Jul-13	19-Jul-13	Safety not working properly	Improper Maintenance	315709	F	Replace trigger assembly, clean, and test fire at 1/2 normal cost
9055	700	n/a	3006 SPRG	1-Feb-79	N	S	22-Jul-13	22-Jul-13	Fired on Safe Release	Could Not Duplicate Concern	315566	F	Replace trigger assembly, clean and test fire under bolt lock program
9057	700	25803	7MM REM MA	14-Oct-86	N	S	23-Jul-13	23-Jul-13	Fired Out of Battery	Improper Maintenance	315924	F	Per lliion - Quote to repair @ 1/2 normal cost for trigger, clean & test
9058	700	27476	270 WIN	4-Apr-03	N	PD/S	23-Jul-13	25-Sep-13	Fired on Bolt Closing	Altered Adjustments or Components	321344	F	Offer to replace trigger assembly and check over at 50% discount

RAC001162

## Confidential

9060	700	29663	308 WIN	13-Dec-07	N	S	23-Jul-13	15-Apr-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
									Unexplained Discharge - No Mention of Safety Position				Replace trigger assembly, clean, and test fire under bolt lock program for \$20.00 + shipping.
9062	700	n/a	308 WIN	16-Mar-78	N	S	24-Jul-13	24-Jul-13		Improper Maintenance	316104	F	Replace TPA, check over and test at no charge
9063	7	24741	7MM08 REM	14-Mar-01	N	S	25-Jul-13	25-Jul-13	Fired on Safe Release	Could Not Duplicate Concern	316153	F	Replace trigger assembly, clean, and test fire under bolt lock program for \$20.00 + shipping.
9068	600	n/a	308 WIN	10-Oct-75	N	S	26-Jul-13	26-Jul-13	Fired on Safe Release	Improper Maintenance	316313	F	Per Ilion - Quote to repair
9074	700	25771	270 WIN	1-Aug-85	N	S	29-Jul-13	29-Jul-13	Fired on Safe Release	Improper Maintenance	316457	F	Per Ilion - Quote to repair
9078	700	n/a	3006 SPRG	1-Jul-74	N	S	31-Jul-13	31-Jul-13	Fired on Bolt Closing	Could Not Duplicate Concern	316637/316638	F	Per Ilion, quote to repair BLM
9079	710	27408	270 WIN	5-Mar-03	N	S	31-Jul-13	31-Jul-13	Fired on Bolt Closing	Improper Maintenance	316658	F	Offer to remove trigger assembly, clean, and test at 50% discount
9081	XIM15-E25	90289	223/5.56	28-Jun-13	N	S	1-Aug-13	1-Aug-13	Went Automatic	Could Not Duplicate Concern	316760	F	Per Ilion, repair at no charge
9085	700	25829	243 WIN	16-Mar-89	N	S	5-Aug-13	5-Aug-13	Fired on Safe Release	Altered Adjustments or Components	316908	F	Offer to replace trigger assembly, clean, and test at 50% discount
9086	700	N/A	7MM REM MA	1-Nov-62	N	S	5-Aug-13	5-Aug-13	Fired on Bolt Opening	Improper Maintenance	316832	F	Per Ilion, quote to repair BLM
9087	700	27582	54 CAL	31-Jul-97	N	S	5-Aug-13	5-Aug-13	Safety not working properly	Broken or Missing Parts	316907	F	Per Ilion, repair at no charge
9093	700	25771	270 WIN	8-Nov-90	N	S	6-Aug-13	6-Aug-13	Delayed Firing - Firearms	Improper Maintenance	316964	F	Replace trigger assembly, clean, and test at 50% discount
9094	700	27491	223 REM	5-Feb-03	N	S	6-Aug-13	6-Aug-13	Fired on Bolt Opening	Other - Unspecified or Undetermined - Firearms	316966	F	Per Ilion - Repair @ n/c
9095	CARBON 15	90689	223/5.56	9-Dec-10	N	S	6-Aug-13	6-Aug-13	Went Automatic	Broken or Missing Parts	317006	F	Repair as needed at no charge
9098	CARBON 15	90689	223/5.56	19-Jul-12	N	S	7-Aug-13	7-Aug-13	Went Automatic	Sent in for Evaluation	317051	F	Repair as needed at no charge
9099	1911 R1	96324	45 ACP	11-Feb-13	N	S	7-Aug-13	7-Aug-13	Fired With Safe ON	Broken or Missing Parts	317105	F	Repair as needed at no charge
9102	700	84019	257 WBY MA	8-Jun-10	N	S	8-Aug-13	16-Apr-15	Fired on Safe Release	Not Examined by Product Service		F	Gun not returned to Ilion for exam
9104	VERSA-MAX	81048	12 GA	5-May-11	N	S	9-Aug-13	9-Aug-13	Fired on Bolt Closing	Broken or Missing Parts	317273	F	Repair as needed at no charge
9105	660	N/A	243 WIN	1-May-68	Y	S	9-Aug-13	9-Aug-13	Fired on Bolt Closing	Improper Maintenance	317317	F	Replace TPA, check over and test at no charge
9106	700	84370	223 REM	21-Jan-08	N	S	9-Aug-13	22-Aug-13	Fired on Safe Release	Could Not Duplicate Concern	318743	F	Replace TPA, check over and test at no charge
9109	700	N/A	7MM REM MA	20-Sep-76	N	S	13-Aug-13	13-Aug-13	Fired on Safe Release	Altered Adjustments or Components	317958	F	Replace trigger assembly, clean, and test fire under bolt lock program for \$20.00 + shipping.
9114	700	27518	243 WIN	30-May-03	N	S	15-Aug-13	15-Aug-13	Fired on Bolt Closing	Improper Maintenance	318086	F	Offer to replace trigger assembly, clean, and test at 50% discount
9117	600	n/a	243 WIN	1-Jun-77	Y	S	19-Aug-13	19-Aug-13	Fired on Safe Release	Altered Adjustments or Components	318354	F	Replace TPA, clean, and test under recall at no charge
9123	700	84203	308 WIN	19-Jul-13	N	S	19-Aug-13	6-Sep-13	Fired on Safe Release	Other - Unspecified or Undetermined - Firearms	320305	F	Per Ilion - Replace in exchange, ramac 84203

RAC001163

## Confidential

9121	770	85633	3006 SPRG	8-Feb-13	N	PD/S	19-Aug-13	15-Apr-15	Fired on Bolt Closing	No Fault Found	n/a	F	Gun not returned to Ilion
9124	887	82502	12 GA	3-Jun-10	N	S	20-Aug-13	20-Aug-13	Fail to Fire	Could Not Duplicate Concern	318571	F	Replace TPA, check over and test at no charge
9125	700	27363	3006 SPRG	8-Aug-11	N	S	20-Aug-13	20-Aug-13	Fired on Bolt Closing	Could Not Duplicate Concern	318559	F	Replace TPA, check over and test at no charge
9126	700	n/a	3006 SPRG	7-Feb-79	N	S	20-Aug-13	20-Aug-13	Fired on Safe Release	Altered Adjustments or Components	318542	F	Replace trigger assembly, clean, and test fire under bolt lock program for \$20.00 + shipping.
9127	700	n/a	2506 REM	1-Nov-70	N	S	20-Aug-13	20-Aug-13	Fired on Safe Release	Improper Maintenance	318503	F	Replace trigger assembly under BLP for \$20.00 + shipping and replace bolt at 25% discount
9129	700	n/a	7MM REM MA	1-Oct-71	N	S	20-Aug-13	20-Aug-13	Fired on Safe Release	Improper Maintenance	318410	F	Replace trigger assembly, clean, and test fire under bolt lock program for \$20.00 + shipping.
9135	742	n/a	3006 SPRG	1-Apr-74	Y	S	23-Aug-13	23-Aug-13	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	318925	F	Quote to clean TA & ck function only, Customer said Return as Received
9136	700	n/a	243 WIN	3-Jun-76	N	S	26-Aug-13	26-Aug-13	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	318973	F	Quote to repair under BLM
9139	600	n/a	6MM REM	1-Jul-73	Y	S	27-Aug-13	27-Aug-13	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	319127	F	Replace TPA, check over and test at no charge
9140	700	27094	270 WIN	18-Jul-12	N	S	27-Aug-13	27-Aug-13	Fired on Safe Release	Could Not Duplicate Concern	319065	F	Per Ilion - Replace TA @ n/c to restore confidence
9142	722	N/A	300 SAV	1-Nov-48	Y	S	28-Aug-13	28-Aug-13	Fired With Safe ON	Improper Maintenance	319199	F	Offer to replace trigger assembly, clean, and test at 50% discount
9162	700	20000	223 REM		N	S	28-Aug-13	14-Apr-15	Fired on Bolt Closing	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
9059	710	27410	3006 SPRG	17-Jan-03	Y	PD/S	29-Aug-13	10-Sep-13	Unexplained Discharge Safe ON	Could Not Duplicate Concern	319385	F	Replace rifle w/85633 in exchange
9145	700	27333	300 WSM	28-Aug-10	N	S	29-Aug-13	29-Aug-13	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	319028	F	Repair as needed at no charge and test fire
9149	700	N/A	270 WIN	10-Sep-79	N	S	29-Aug-13	29-Aug-13	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	319399	F	Replace trigger assembly, clean, and test fire under bolt lock program for \$20.00 + shipping.
9152	700	N/A	7MM REM MA	1-Apr-71	N	S	30-Aug-13	30-Aug-13	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	319507	F	Replace trigger assembly, clean, and test fire under bolt lock program for \$20.00 + shipping.
9154	700	85335	270 WIN	26-Jun-12	N	S	30-Aug-13	17-Sep-13	Ammunition Exploded	Sent in for Evaluation	319491	A	Repair as needed at no charge and test fire
9158	700	N/A	222 REM	1-Jan-75	N	S	4-Sep-13	4-Sep-13	Fired on Bolt Closing	Altered Adjustments or Components	319582	F	Replace trigger assembly under BLP for \$20.00 + shipping and repair magazine at 50% discount
9159	700	25773	3006 SPRG	9-Oct-97	N	S	4-Sep-13	4-Sep-13	Fired on Safe Release	Could Not Duplicate Concern	319617	F	Offer to replace trigger assembly, clean, and test at 50% discount

RAC001164

## Confidential

9160	700	N/A	270 WIN	13-Jan-81	N	S	4-Sep-13	4-Sep-13	Fired on Safe Release	Could Not Duplicate Concern	319629	F	Replace trigger assembly, clean, and test fire under bolt lock program for \$20.00 + shipping.
9161	700	N/A	3006 SPRG	11-Jun-80	N	S	4-Sep-13	4-Sep-13	Fail to Fire	Could Not Duplicate Concern	319647	F	Replace trigger assembly, clean, and test fire under bolt lock program for \$20.00 + shipping.
9166	7	N/A	7MM-08 REM	28-Oct-02	N	S	5-Sep-13	5-Sep-13	Fired on Safe Release	Altered Adjustments or Components	319768	F	Offer to replace trigger assembly, check over, and test at 50% discount
9169	750	27057	308 WIN	6-Mar-09	N	S	6-Sep-13	6-Sep-13	Went Automatic	Could Not Duplicate Concern	320086	F	Replace TPA, check over and test at no charge
9170	721	N/A	3006 SPRG	1-Feb-53	Y	S	6-Sep-13	6-Sep-13	Fired With Safe ON	Altered Adjustments or Components	320303	F	Replace trigger assembly, check over, and test fire under bolt lock program for \$20.00 + shipping.
9176	700	29663	308 WIN	6-Mar-13	N	S	9-Sep-13	23-Sep-13	Fired on Bolt Closing	Could Not Duplicate Concern	321706	F	Replace TPA, check over and test at no charge
9183	700	27580	50 CAL	6-Aug-96	N	S	11-Sep-13	11-Sep-13	Fired on Safe Release	Sent in for Evaluation	320590/320575	F	Replace trigger and check over at no charge
9185	700	N/A	338 WIN MA	1-Jul-62	N	S	11-Sep-13	11-Sep-13	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	320685	F	Replace trigger assembly under BLP for \$20.00 + shipping and replace bolt at 50% discount
9187	597	26536	17 HMR	3-Jun-03	N	S	13-Sep-13	17-Sep-13	Fired With Safe ON	Other - Unspecified or Undetermined - Firearms	320921	F	Converting to 22 WMR as requested by customer, repair and check over completely at no charge.
9192	597	26513	22 LR	1-Jul-13	N	S	16-Sep-13	16-Sep-13	Went Automatic	Other - Unspecified or Undetermined - Firearms	321037/325496	F	Replace TPA, check over and test at no charge / Replace with Ramac 26513 in exchange
9193	700	N/A	308 WIN	14-Mar-77	N	S	16-Sep-13	16-Sep-13	Fired on Safe Release	Improper Maintenance	321052	F	Replace trigger assembly, check over, and test fire under bolt lock program for \$20.00 + shipping.
9156	700	n/a	3006 SPRG	1-Sep-76	N	S	17-Sep-13	17-Sep-13	Fired on Safe Release	Altered Adjustments or Components	321167	F	Per Ilion - Quote to repair under BLM
9195	7	24782	243 WIN	25-May-90	N	S	17-Sep-13	17-Sep-13	Fired on Bolt Closing	Could Not Duplicate Concern	321159	F	Offer to replace trigger assembly, check over, and test at 50% discount
9200	700	not avail.	243 WIN	16-Oct-08	N	S	18-Sep-13	18-Sep-13	Fired on Safe Release	Altered Adjustments or Components	321356	F	Offer to replace trigger assembly, check over, and test at 50% discount
9201	700	84173	3006 SPRG	29-Apr-09	N	S	18-Sep-13	18-Sep-13	Fired on Safe Release	Could Not Duplicate Concern	321319	F	Replace TPA, check over and test at no charge
9205	CARBON 15	90863	223/5.56	19-Dec-12	N	S	20-Sep-13	20-Sep-13	Went Automatic	Sent in for Evaluation	321662	F	Check over completely, and repair as needed at no charge
9206	700	N/A	3006 SPRG	12-Oct-78	N	PI/S	20-Sep-13	20-Sep-13	Fired on Bolt Closing	Improper Maintenance	321608	F	Replace trigger assembly, clean, and test fire under bolt lock program for \$20.00 + shipping.
9214	597M	26536	17 HMR	27-Jun-03	N	S	23-Sep-13	4-Oct-13	Other - Firearms	Other - Unspecified or Undetermined - Firearms	323075	F	Replacing with Ramac 70723 in exchange
9215	700	n/a	243 WIN	11-Nov-80	N	S	24-Sep-13	24-Sep-13	Fired on Safe Release	Altered Adjustments or Components	321905	F	Replace trigger assembly, clean, and test fire under bolt lock program for \$20.00 + shipping.

RAC001165

## Confidential

9217	700	N/A	7MM REM MA							Altered Adjustments or Components	321933	F	Replace trigger assembly, clean, and test fire under bolt lock program for \$20.00 + shipping.
9221	700	n/a	3006 SPRG	27-Sep-79	N	S	24-Sep-13	24-Sep-13	Fired on Bolt Closing	Altered Adjustments or Components	323224	F	Per Ilion - Quote to repair under BLM
9235	7	24781	260 REM	7-Mar-03	N	S	27-Sep-13	27-Sep-13	Fired on Safe Release	Altered Adjustments or Components	322326	F	Offer to replace trigger assembly, check over, and test at 50% discount
9237	700	25793	3006 SPRG	1-Oct-84	N	S	27-Sep-13	27-Sep-13	Fired on Bolt Closing	Improper Maintenance	322345	F	Offer to replace trigger assembly, check over, and test at 50% discount
9243	597M	26514	17 HMR	29-Jan-04	N	S	30-Sep-13	11-Oct-13	Other - Firearms	Other - Unspecified or Undetermined - Firearms	323630	F	Converting to 22 WMR as requested by customer, repair and check over completely at no charge.
9245	887	82500	12 GA	11-Jun-13	N	S	30-Sep-13	22-Oct-13	Delayed Firing - Firearms	Could Not Duplicate Concern	324796	F	Replace TPA, check over and test at no charge
9207	700ML	27580	50 CAL	11-Sep-96	Y	S	1-Oct-13	1-Oct-13	Fired on Safe Release	Other - Unspecified or Undetermined - Firearms	322598	F	Replace trigger and check over at no charge
9247	700	N/A	7MM REM MA	1-May-74	N	S	1-Oct-13	1-Oct-13	Fired on Safe Release	Altered Adjustments or Components	322572	F	Replace trigger assembly under BLP for \$20.00 + shipping and replace trigger guard at 50% discount
9249	700	27037	300 WIN MA	6-Nov-06	N	S	1-Oct-13	1-Oct-13	Fired on Safe Release	Altered Adjustments or Components	322575	F	Per Ilion - Quote to repair
9251	700	27339	300 WIN MA	22-Jul-05	N	S	1-Oct-13	21-Oct-13	Fired on Bolt Closing	Altered Adjustments or Components	324650	F	Per Ilion - Quote to repair @ a discount
9254	597M	26536	17 HMR	30-Jun-05	N	S	1-Oct-13	16-Oct-13	Other - Firearms	Other - Unspecified or Undetermined - Firearms	324090	F	Converting to 22 WMR as requested by customer
9255	700	n/a	243 WIN	1-Jun-70	N	S	1-Oct-13	15-Oct-13	Delayed Firing - Firearms	Improper Maintenance	323840	F	Per Ilion - Quote to repair under BLM
9259	887	82500	12 GA	7-Mar-13	N	S	3-Oct-13	3-Oct-13	Fired on Bolt Closing	Could Not Duplicate Concern	322897	F	Check over completely, and repair as needed at no charge
9262	700	25803	7MM REM MA	20-Apr-91	N	S	4-Oct-13	4-Oct-13	Delayed Firing - Firearms	Improper Maintenance	322987	F	Offer to replace trigger assembly, check over, and test at 50% discount
9263	700	27452	25-06 REM	23-Jun-00	N	S	4-Oct-13	14-Oct-13	Fired on Bolt Closing	Improper Maintenance	323730	F	Replace trigger, check over and test fire at 50% discount
9264	700	N/A	243 WIN	12-Sep-72	N	PI/S	4-Oct-13	22-Oct-13	Fired on Safe Release	Improper Maintenance	324296	F	Replace TPA, check over and test at no charge
9280	700	25803	7MM REM MA	2-Nov-89	N	S	4-Oct-13	21-Oct-13	Fired on Safe Release	Improper Maintenance	324587	F	Per Ilion - Quote to repair @ a discount
9270	700	27165	270 WIN	18-Nov-05	N	S	7-Oct-13	7-Oct-13	Fired on Safe Release	Could Not Duplicate Concern	323178	F	Replace TPA, check over and test at no charge
9271	710	27408	270 WIN	28-Apr-05	Y	S	7-Oct-13	11-Oct-13	Action Opened on Firing	Could Not Duplicate Concern	323183	F	Replacing with Ramac 85632 in exchange
9273	710	27408	270 WIN	11-Mar-03	Y	S	8-Oct-13	8-Oct-13	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	323345	F	Remove and clean trigger assembly, function check and test fire at 50% discount.
9274	700	N/A	270 WIN	1-Aug-68	N	S	8-Oct-13	8-Oct-13	Fired on Safe Release	Altered Adjustments or Components	323213	F	Replace trigger assembly, check over, and test fire under bolt lock program for \$20.00 + shipping.

RAC001166

## Confidential

9275	700	25815	7MM REM MA	6-Dec-89	N	S	8-Oct-13	8-Oct-13	Fired With Safe ON	Could Not Duplicate Concern	323243	F	Offer to replace trigger assembly, check over, and test at 50% discount	
9293	700	27476	270 WIN	26-Sep-97	N	S	8-Oct-13	1-Nov-13	Fired on Bolt Closing	Improper Maintenance	326021	F	Per llion - Quote to repair @ a discount	
9285	700	27480	300 WIN MA	4-Nov-96	N	S	10-Oct-13	10-Oct-13	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	323518	F	Replace trigger, check over and test fire at 50% discount	
9287	700	29694	300 WIN MA	28-Jul-93	N	S	10-Oct-13	10-Oct-13	Fired on Safe Release	Altered Adjustments or Components	323442	F	Replace trigger, check over and test fire at 50% discount	
9288	870	81112	12 GA	1-May-13	N	PI/S	10-Oct-13	17-Oct-13	Action Opened on Firing	Sent in for Evaluation	323527	O	No fault found, returning gun to dealer	
9292	700	25799	7mm-08 REM	15-Aug-02	N	S	10-Oct-13	31-Oct-13	Fired on Bolt Closing	Improper Maintenance	325961	F	Per llion - Quote to repair @ a discount	
9296	582	n/a	22 RF	1-Apr-69	Y	S	14-Oct-13	14-Oct-13	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	323747	F	Per llion - Quote to repair	
9297	78	SPORTSMAN	N/A	3006 SPRG	18-Dec-87	Y	S	14-Oct-13	14-Oct-13	Fired on Safe Release	Could Not Duplicate Concern	323732	F	Offer to replace trigger assembly, check over, and test at 50% discount
9301	700	26905	243 WIN	11-Jun-96	N	S	15-Oct-13	15-Oct-13	Fired on Safe Release	Could Not Duplicate Concern	323925	F	Offer to replace trigger assembly and check over at 50% discount	
9302	700	26123	270 WIN	8-Jun-04	N	S	15-Oct-13	15-Oct-13	Fired on Bolt Closing	Altered Adjustments or Components	323841	F	Offer to replace trigger assembly, check over, and test at 50% discount	
9303	CARBON 15	90689	223 REM/5.	31-Aug-13	N	S	15-Oct-13	15-Oct-13	Fired With Safe ON	Sent in for Evaluation	323919	F	Check over completely, repair as needed, and test fire at no charge	
9304	700	29698	220 SWIFT	15-Mar-93	N	S	15-Oct-13	15-Oct-13	Fired on Bolt Closing	Altered Adjustments or Components	323955	F	Per llion - Quote to repair @ 1/2 normal cost for trigger, clean & test	
9310	597M	26514	17 HMR	9-Nov-04	N	S	16-Oct-13	31-Oct-13	Other - Firearms	Other - Unspecified or Undetermined - Firearms	325959	F	Replacing with Ramac 70723 in exchange	
9311	700	n/a	308 WIN	1-Jun-11	N	S	17-Oct-13	17-Oct-13	Fired on Safe Release	Could Not Duplicate Concern	324125	F	Replace TPA, check over and test at no charge	
9312	597	26536	17 HMR	20-May-03	N	PD/S	17-Oct-13	17-Oct-13	Other - Firearms	Other - Unspecified or Undetermined - Firearms	324153	F	Converting to 22 WMR as requested by customer, repair and check over completely at no charge.	
9314	597	26536	17 HMR	21-May-03	N	PD/S	17-Oct-13	17-Oct-13	Other - Firearms	Other - Unspecified or Undetermined - Firearms	324263	F	Converting to 22 WMR as requested by customer, repair and check over completely at no charge.	
9317	770	85637	243 WIN	29-Nov-07	N	PD/S	21-Oct-13	21-Oct-13	Fired on Bolt Closing	Broken or Missing Parts	324642	F	Replace TPA, bolt, check over, and test at no charge	
9324	700	n/a	300 WBY MA	16-Dec-99	N	S	22-Oct-13	22-Oct-13	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	324731	F	Replace trigger, check over and test fire at 50% discount	
9326	700	N/A	270 WIN	1-Sep-69	N	S	22-Oct-13	6-Nov-13	Fired on Bolt Closing	Improper Maintenance	326510	F	Replace trigger assembly, check over, and test fire under bolt lock program for \$20.00 + shipping.	
9327	700	N/A	3006 SPR	1-Oct-72	N	S	22-Oct-13	13-Nov-13	Delayed Firing - Firearms	Improper Maintenance	327419	F	Per llion, quote to repair BLM	

RAC001167

## Confidential

9322	597	26516	17 HMR	11-Nov-04	N	S	22-Oct-13	3-Mar-14	Fired Out of Battery	Other - Unspecified or Undetermined - Firearms	324787	F	Converting to 22 WMR as requested by customer, repair and check over completely at no charge.
9325	700	N/A	243 WIN		N	S	22-Oct-13	16-Apr-15	Fired on Bolt Closing	Not Examined by Product Service		F	Gun not returned to Ilion for exam
9330	700	27494	243 WIN	20-Mar-95	N	S	23-Oct-13	23-Oct-13	Fired on Safe Release	Altered Adjustments or Components	324841	F	Replace trigger, check over, and test at no charge
9331	700	25971	300 RUM	19-Jul-01	N	S	23-Oct-13	23-Oct-13	Fired on Bolt Closing	Improper Maintenance	324898	F	replace trigger, check over, and test fire at 50% discount
9335	700	n/a	243 WIN		N	S	23-Oct-13	15-Apr-15	Delayed Firing - Firearms	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
9336	700	N/A	243 WIN		N	PD/S	23-Oct-13	16-Apr-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
9345	700	N/A	3006 SPR	12-Jun-78	N	S	23-Oct-13	13-Apr-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
9339	700	N/A	270 WIN	26-Jul-78	N	S	24-Oct-13	24-Oct-13	Fired on Bolt Opening	Could Not Duplicate Concern	325070	F	Replace trigger assembly, check over, and test fire under bolt lock program for \$20.00 + shipping.
9340	700	84216	22-250 REM	11-Dec-06	N	S	24-Oct-13	24-Oct-13	Fired on Safe Release	Altered Adjustments or Components	324990	F	Replace trigger, check over and test fire at 50% discount
9346	870	81112	12 GA	1-May-13	N	S	24-Oct-13	13-Apr-15	Action Opened on Firing	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
9354	700	25771	270 WIN	29-Apr-94	N	S	24-Oct-13	15-Apr-15	Fired on Bolt Closing	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
9347	700	84022	6MM REM	9-Dec-11	N	S	25-Oct-13	25-Oct-13	Fail to Fire	Could Not Duplicate Concern	325130	F	Replace TPA, bolt, check over, and test at no charge
9355	700	n/a	270 WIN	1-May-75	N	S	25-Oct-13	20-Nov-13	Fired on Safe Release	Could Not Duplicate Concern	328044	F	Per Ilion - Quote to repair under BLM
9351	700	N/A	243 WIN	1-May-78	N	S	28-Oct-13	28-Oct-13	Fired on Bolt Closing	Improper Maintenance	325210	F	Replace trigger assembly, check over, and test fire under bolt lock program for \$20.00 + shipping.
9352	750	27059	270 WIN	21-Apr-10	N	S	28-Oct-13	28-Oct-13	Case Separation	Other - Unspecified or Undetermined - Firearms	325390	F	Check over completely, repair as needed, and test fire at no charge
9353	788	n/a	243 WIN	26-Aug-81	Y	S	28-Oct-13	28-Oct-13	Fired on Safe Release	Improper Maintenance	325333	F	Per Ilion - Quote to repair @ a discount
9359	700	N/A	7MM REM MA	1-Nov-73	N	S	28-Oct-13	6-Dec-13	Unexplained Discharge Safe OFF	Could Not Duplicate Concern	329684	F	Replace trigger assembly, check over, and test fire under bolt lock program for \$20.00 + shipping.
9362	770	85633	3006 SPRG	19-Jun-07	N	PI/S	29-Oct-13	29-Oct-13	Fired on Safe Release	Altered Adjustments or Components	325595	F	Replacing with Ramac 84371 in exchange at a 50% discount
9365	710	27408	270 WIN	25-Oct-05	Y	S	29-Oct-13	13-Nov-13	Fired on Safe Release	Could Not Duplicate Concern	327156	F	Per Ilion, replace trigger assembly and repair as needed at 50% discount
9368	710	27410	3006 SPR	30-Apr-01	Y	PD/S	30-Oct-13	18-Nov-13	Fired on Bolt Closing	Could Not Duplicate Concern	325693	F	Replacing with Ramac 85633 in exchange
9369	700	25971	300 RUM	8-Nov-01	N	S	30-Oct-13	30-Oct-13	Fired on Safe Release	Improper Maintenance	325685	F	Replace trigger, check over and test fire at 50% discount
9372	700	27361	270 WIN	16-Jan-06	N	S	30-Oct-13	9-Dec-13	Fired on Safe Release	Altered Adjustments or Components	329862	F	Per Ilion - Quote to repair @ a discount

RAC001168

## Confidential

9374	722	N/A	257 ROBTS	1-Feb-50	Y	S	30-Oct-13	7-Nov-13	Fired With Safe ON	AFT MKT TRIGGER ASSM	326769	F	Offer to replace bolt assembly, trigger assembly, check over, and test at 50% discount
9371	700	N/A	243 WIN	28-Aug-01	N	S	30-Oct-13	3-Jan-14	Fired on Bolt Closing	Could Not Duplicate Concern	332493	F	Per Ilion, replace trigger, check over, and test at 50% discount
9375	H&R	N/A	45-70 GOV	28-Sep-11	N	PI/S	30-Oct-13	2-Jan-14	Action Opened on Firing	Could Not Duplicate Concern	328173	F	Replacing with Ramac 72582 in exchange
9376	770	85634	308 WIN	19-Jul-12	N	S	31-Oct-13	31-Oct-13	Fired on Bolt Closing	Could Not Duplicate Concern	325820	F	Replace TPA, check over and test at no charge
9377	700	26308	7MM RUM	3-Apr-03	N	S	31-Oct-13	31-Oct-13	Fired on Safe Release	Could Not Duplicate Concern	325831	F	Replace trigger, check over, and test at no charge
9378	700	29705	308 WIN	2-Mar-01	N	S	31-Oct-13	31-Oct-13	Fired on Bolt Closing	Altered Adjustments or Components	325853	F	Replace trigger, check over and test fire at 50% discount
9379	58	N/A	12 GA	1-Apr-56	Y	S	31-Oct-13	31-Oct-13	Fired on Bolt Closing	Broken or Missing Parts	325838	F	Offer to check over completely and repair at 50% discount
9381	770	85633	3006 SPR	10-Jun-13	N	S	31-Oct-13	31-Oct-13	Fired on Bolt Closing	Could Not Duplicate Concern	325901	F	Replace TPA, check over and test at no charge
9382	700	N/A	270 WIN	24-Jan-05	N	S	31-Oct-13	20-Nov-13	Fired on Bolt Closing	Could Not Duplicate Concern	327952	F	Per Ilion, offer to replace trigger assembly, check over, and test at 50% discount
9385	700ML	27572	50 CAL	22-Jul-97	Y	S	31-Oct-13	2-Dec-13	Fired on Safe Release	Broken or Missing Parts	328551	F	Per Ilion, replace trigger, check over at no charge
9400	700	25971	300 RUM	27-Oct-00	N	S	31-Oct-13	20-Nov-13	Fired on Bolt Closing	Altered Adjustments or Components	327936	F	Not Examined by Product Service
9383	n/a	45 ACP			N	PI/S	31-Oct-13	17-Apr-14	Other - Ammunition	Not Examined by Product Service	n/a	A	Per Ilion - Quote to repair Ammo not returned to Lonoke for exam
9384	700	N/A	25-06 REM		N	S	31-Oct-13	16-Apr-15	Fired on Bolt Closing	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
9386	700	n/a	243 WIN	29-Sep-81	N	PD/S	31-Oct-13	14-Apr-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
9282	770	85636	300 WIN	16-Nov-07	N	PD/S	1-Nov-13	6-Nov-13	Fired on Bolt Opening	Broken or Missing Parts	326008	F	Repair @ n/c - goodwill gesture
9390	7	24786	7MM 08 REM	14-Sep-93	N	S	1-Nov-13	1-Nov-13	Fired on Safe Release	Altered Adjustments or Components	326064	F	Replace trigger, check over and test fire at 50% discount
9391	700	N/A	270 WIN	1-Oct-70	N	S	1-Nov-13	1-Nov-13	Fired on Safe Release	Altered Adjustments or Components	326068	F	Replace trigger assembly, check over, and test fire under bolt lock program for \$20.00 + shipping.
9392	700	27490	223 REM	1-Feb-96	N	S	1-Nov-13	1-Nov-13	Fired on Safe Release	Altered Adjustments or Components	326011	F	Offer to replace trigger assembly, check over, and test at 50% discount
9394	700	N/A	22-250 REM	18-Dec-76	N	S	1-Nov-13	14-Nov-13	Fired on Safe Release	Altered Adjustments or Components	327471	F	Per Ilion, quote to repair BLM
9396	597M	26514	17 HMR	9-Dec-03	N	S	1-Nov-13	3-Dec-13	Other - Firearms	Other - Unspecified or Undetermined - Firearms	327656	F	Replacing with Ramac 70743 in exchange
9398	700	N/A	7MM REM MA	1-Dec-72	N	S	1-Nov-13	4-Dec-13	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	329415	F	Per Ilion, quote to repair BLM
9406	700	84174	7MM REM MA	27-Oct-06	N	S	4-Nov-13	20-Nov-13	Fired on Safe Release	Altered Adjustments or Components	327800	F	Replace trigger, check over and test fire at 50% discount

RAC001169

## Confidential

9410	700	N/A	7MM REM MA	1-Apr-80	N	S	5-Nov-13	5-Nov-13	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	326244	F	Replace trigger assembly, check over, and test fire under bolt lock program for \$20.00 + shipping.
9412	710	27408	270 WIN	6-Feb-06	Y	S	5-Nov-13	5-Nov-13	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	326324	F	Replace trigger, check over and test fire at 50% discount
9414	700	25636	7MM STW	31-Oct-86	N	S	5-Nov-13	20-Nov-13	Fired on Safe Release	Altered Adjustments or Components	328096	F	Offer to replace trigger assembly, check over, and test at 50% discount
9424	700	n/a	3006 SPRG	2-Feb-81	N	S	5-Nov-13	20-Nov-13	Fired on Bolt Opening	Improper Maintenance	328069	F	Per Ilion - Quote to repair under BLM
9418	700	N/A	270 WIN	1-Sep-84	N	S	6-Nov-13	6-Nov-13	Fired on Bolt Closing	Altered Adjustments or Components	326391	F	Per Ilion, replace trigger assembly and repair as needed at 50% discount
9419	CARBON 15	90689	223/5.56	10-Nov-12	N	S	6-Nov-13	6-Nov-13	Went Automatic	Sent in for Evaluation	326454	F	Check over completely, and repair as needed at no charge
9422	722	N/A	222 REM	1-Jan-59	Y	S	6-Nov-13	6-Nov-13	Fired With Safe ON	Altered Adjustments or Components	325900	F	Per Ilion, quote to repair BLM
9434	Mohawk 600	n/a	243 WIN	1-May-74	Y	PD/S	6-Nov-13	2-Dec-13	Fired on Safe Release	Altered Adjustments or Components	328960	F	Per Ilion - Repair @ n/c - goodwill
9435	700	n/a	3006 SPRG	5-May-88	N	S	6-Nov-13	21-Nov-13	Fired on Safe Release	HARD OFF SAFE	328371	F	Per Ilion - Repair @ n/c
9425	700	N/A	25-06 REM	19-Oct-77	N	S	6-Nov-13	31-Jan-14	Fired on Bolt Closing	Altered Adjustments or Components	336054	F	Per Ilion, quote to repair BLM
9432	700	27265	7mm-08	3-Mar-06	N	S	6-Nov-13	16-Apr-15	Delayed Firing - Firearms	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
9427	700	n/a	243 WIN	1-Jan-68	N	S	7-Nov-13	7-Nov-13	Fired on Safe Release	Altered Adjustments or Components	326599	F	Per Ilion - Quote to repair @ a discount
9430	700	25803	7MM REM MA	11-Jun-91	N	S	7-Nov-13	3-Dec-13	Unexplained Discharge Safe OFF	Improper Maintenance	328851	F	Per Ilion, replace trigger assembly and repair as needed at 50% discount
9431	700ML	27572	50 CAL	30-Apr-97	Y	S	7-Nov-13	2-Dec-13	Unexplained Discharge Safe OFF	Could Not Duplicate Concern	328920	F	Per Ilion, replace trigger assembly and repair as needed at 50% discount
9440	700	26033	270 WIN	6-Sep-00	N	S	8-Nov-13	15-Nov-13	Unexplained Discharge Safe OFF	Improper Maintenance	327756	F	Per Ilion, replace trigger assembly and repair as needed at 50% discount
9441	700	25791	270 WIN	14-Feb-90	N	S	8-Nov-13	3-Dec-13	Fired on Safe Release	Altered Adjustments or Components	328975	F	Replace trigger, check over and test fire at 50% discount
9442	700	n/a			N	S	8-Nov-13	8-Nov-13	Fired on Safe Release	Not Examined by Product Service	n/a	F	Paralegal from Canada. Referred them to Gravel Agency
9443	700	25803	7MM REM MA	8-Nov-91	N	S	8-Nov-13	2-Dec-13	Fired on Safe Release	Could Not Duplicate Concern	328841	F	Per Ilion, replace trigger assembly and repair as needed at 50% discount
9449	700	25909	7MM WBY MA	10-May-91	N	S	11-Nov-13	10-Dec-13	Fired on Bolt Closing	Could Not Duplicate Concern	330172	F	Per Ilion, replace trigger, check over, and test at 50% discount
9451	700	27121	270 WIN	18-Sep-06	N	S	11-Nov-13	2-Dec-13	Fired on Safe Release	Sent in for Evaluation	328579	F	Per Ilion, replace trigger, check over and test fire at no charge
9456	700	25771	270 WIN	1-May-85	N	S	11-Nov-13	17-Dec-13	Fired on Safe Release	Could Not Duplicate Concern	331119	F	Per Ilion - Quote to repair
9457	700	85435	308 WIN	9-May-12	N	S	11-Nov-13	5-Dec-13	Fired on Safe Release	Could Not Duplicate Concern	329532	F	Per Ilion - Repair @ n/c - warranty

RAC001170

## Confidential

9463	700ML	27572	50 CAL	21-Oct-97	Y	S	11-Nov-13	6-Dec-13	Fired on Safe Release	Other - Unspecified or Undetermined - Firearms	329683	F	Per Ilion - Repair @ n/c
9450	742	N/A	308 WIN	1-Jul-78	N	S	11-Nov-13	8-Jan-14	Fired on Bolt Closing	Sent in for Evaluation	332891	F	Per Ilion, repair at no charge
9460	700	85591	7mm-08 REM	24-Jun-11	N	S	11-Nov-13	28-Jan-14	Fired on Safe Release	Could Not Duplicate Concern	335507	F	Per Ilion - Repair at n/c Per Ilion, replace trigger, check over and test fire at no charge
9452	700	25739	308 WIN	5-Mar-13	N	S	12-Nov-13	12-Nov-13	Fired on Safe Release	Other - Unspecified or Undetermined - Firearms	327039	F	Per Ilion - Repair at n/c Per Ilion, replace trigger, check over and test fire at no charge
9453	700	N/A	300 WIN MA	1-Sep-73	N	S	12-Nov-13	12-Nov-13	Fired on Bolt Closing	Altered Adjustments or Components	327006	F	Per Ilion, quote to repair BLM
9469	Mohawk 600	n/a	308 WIN	1-Jul-71	Y	S	12-Nov-13	2-Dec-13	Fired on Bolt Closing	Altered Adjustments or Components	328954	F	Per Ilion - Repair @ n/c Per Ilion - Quote to repair @ discount
9454	742	n/a	308 WIN	1-Feb-74	Y	S	12-Nov-13	31-Jan-14	Fired With Safe ON	Could Not Duplicate Concern	336104	F	Per Ilion - Repair at n/c Per Ilion - Repair @ n/c - goodwill
9480	700	27337	3006 SPRG	2-Sep-09	N	S	12-Nov-13	14-Mar-14	Fired on Safe Release	Could Not Duplicate Concern	340523	F	Per Ilion - Repair at n/c - goodwill
9464	597	N/A	17 HMR	10-Dec-03	N	S	13-Nov-13	23-Dec-13	Other - Firearms	Other - Unspecified or Undetermined - Firearms	331782	F	Converting to 22 WMR as requested by customer, repair and check over completely at no charge.
9483	700	25805	338 WIN MA	1-Dec-89	N	S	13-Nov-13	2-Dec-13	Delayed Firing - Firearms	Improper Maintenance	328723	F	Per Ilion - Quote to repair @ a discount
9473	700	25793	3006 SPR	30-May-96	N	S	13-Nov-13	16-Apr-15	Unexplained Discharge Safe OFF	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
9475	597	26536	17 HMR	20-Jun-03	N	S	13-Nov-13	15-Apr-15	Other - Firearms	Not Examined by Product Service	328633	F	Gun not examined by Product Service in Ilion
9467	597	26516	17 HMR	5-May-04	N	S	13-Nov-13	26-Dec-13	Other - Firearms	Other - Unspecified or Undetermined - Firearms	330312	F	Replacing with Ramac 85836 in exchange
9474	7005	85422	7MM REM MA	16-Sep-09	N	S	14-Nov-13	3-Dec-13	Fired on Safe Release	Could Not Duplicate Concern	329185	F	Per Ilion, replace trigger, check over and test fire at no charge
9477	700	27474	243 WIN	1-Aug-96	N	PI/S	14-Nov-13	4-Dec-13	Fired on Bolt Closing	Altered Adjustments or Components	329417	F	Repair @ n/c - goodwill gesture
9478	700	n/a	7MM REM MA	17-Sep-76	N	S	15-Nov-13	15-Nov-13	Fired on Safe Release	Improper Maintenance	327745	O	Per Ilion - Quote to repair under BLM
9484	700	N/A	3006 SPR	4-Jun-80	N	PD/S	15-Nov-13	14-Apr-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
9489	597M	26516	17 HMR	25-Mar-04	N	S	18-Nov-13	11-Dec-13	Other - Firearms	Other - Unspecified or Undetermined - Firearms	330282	F	Replacing with Ramac 70733 in exchange
9491	700	n/a	3006 SPRG	1-May-74	N	S	18-Nov-13	4-Dec-13	Fired on Bolt Opening	Improper Maintenance	329387	F	Quote to repair under BLM
9503	700	27359	308 WIN	28-Jan-12	N	S	18-Nov-13	12-Dec-13	Fired on Safe Release	Could Not Duplicate Concern	330554	F	Replace TPA, check over and test at no charge
9517	770	85634	308 WIN	8-Mar-13	N	S	18-Nov-13	11-Dec-13	Fired on Bolt Closing	Could Not Duplicate Concern	330361	F	Per Ilion, replace TPA, check over and test at no charge
9490	700	25773	3006 SPRG	15-Oct-87	N	S	18-Nov-13	26-Mar-14	Fired on Safe Release	Altered Adjustments or Components	341502	F	Repair @ n/c - goodwill gesture
9492	700	n/a	270 WIN	19-Jan-79	N	PI/S	18-Nov-13	2-Jan-14	Fired on Safe Release	Could Not Duplicate Concern	330314	F	Repair @ n/c - goodwill gesture
9509	597	N/A	17 HMR	25-Jun-03	N	S	18-Nov-13	12-Feb-14	Other - Firearms	Other - Unspecified or Undetermined - Firearms	335856	F	Converting to 22 WMR as requested by customer, repair and check over completely at no charge.
9525	700	n/a	270 WIN	28-Apr-76	N	PD/S	18-Nov-13	8-Jan-14	Fired on Bolt Closing	Improper Maintenance	331122	F	Quote to repair under BLM

RAC001171

## Confidential

9493	710	27404	270 WIN	27-Nov-01	Y	PD/S	18-Nov-13	14-Apr-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam	
9506	700	N/A	300 RUM		N	S	18-Nov-13	15-Apr-15	Fired on Bolt Closing	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam	
9524	700	n/a	n/a		N	S	18-Nov-13	15-Apr-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam	
9518	597M	26514	17 HMR	29-Jan-04	N	S	19-Nov-13	6-Dec-13	Other - Firearms	Other - Unspecified or Undetermined - Firearms	329754	F	Converting to 22 WMR as requested by customer	
9527	597M	26516	17 HMR	14-Oct-03	N	S	19-Nov-13	13-Dec-13	Other - Firearms	Other - Unspecified or Undetermined - Firearms	330587	F	Converting to 22 WMR as requested by customer	
9533	700	N/A	243 WIN	1-Mar-72	N	S	19-Nov-13	18-Dec-13	Fired on Safe Release	Altered Adjustments or Components	331227	F	Per Ilion, quote to repair BLM	
9529	700	N/A	3006 SPR	1-Sep-71	N	S	19-Nov-13	13-Jan-14	Fired on Bolt Opening	Could Not Duplicate Concern	333271	F	Per customer request Returning as Received.	
9526	700	20000	3006 SPRG		N	S	19-Nov-13	13-Apr-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam	
9528	700	not avail.	223 REM		N	S	19-Nov-13	16-Apr-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam	
									Unexplained Discharge - No Mention of Safety Position					
9494	700	27586	50 CAL	28-Jan-97	N	S	20-Nov-13	20-Nov-13	Broken or Missing Parts	Broken or Missing Parts	327796	F	Per Ilion, replace trigger, check over at no charge	
9495	700	27452	2506 REM	22-Sep-04	N	S	20-Nov-13	20-Nov-13	Fired on Safe Release	Could Not Duplicate Concern	327956	F	Per Ilion - Repair @ n/c - goodwill	
9496	700	25767	243 WIN	10-Jun-93	N	S	20-Nov-13	20-Nov-13	Fired on Bolt Closing	Improper Maintenance	327879	F	Offer to replace trigger assembly, check over, and test at 50% discount	
9498	700	n/a	7MM REM	MA	2-Apr-80	N	S	20-Nov-13	20-Nov-13	Fired on Safe Release	Altered Adjustments or Components	327997	F	Per Ilion - Quote to repair under BLM
9499	700	25773	3006 SPRG	7-May-03	N	S	20-Nov-13	20-Nov-13	Fired on Safe Release	Improper Maintenance	327790	F	Per Ilion, replace trigger assembly and repair as needed at 50% discount	
9500	700	25793	3006 SPRG	1-Jun-84	N	S	20-Nov-13	20-Nov-13	Fired on Safe Release	Altered Adjustments or Components	327996	F	Per Ilion, replace trigger, check over and test fire at no charge	
9505	600	n/a	243 WIN	1-Sep-66	Y	S	20-Nov-13	20-Nov-13	Delayed Firing - Firearms	Improper Maintenance	327963	F	Per Ilion - Repair @ n/c	
9507	700	n/a	7MM REM	MA	25-Mar-79	N	S	20-Nov-13	20-Nov-13	Fired on Bolt Closing	Could Not Duplicate Concern	327964	F	Per Ilion - Quote to repair under BLM
9508	700	25771	270 WIN	22-Oct-99	N	S	20-Nov-13	20-Nov-13	Delayed Firing - Firearms	Could Not Duplicate Concern	328072	F	Per Ilion - Quote to repair @ a discount	
9534	597M	26514	17 HMR	9-Nov-04	N	S	20-Nov-13	12-Dec-13	Other - Firearms	Other - Unspecified or Undetermined - Firearms	330514	F	Replacing with Ramac 70723 in exchange	
9513	600	N/A	6MM REM	1-May-64	Y	S	21-Nov-13	21-Nov-13	Fired on Bolt Closing	Improper Maintenance	328293	F	Per Ilion, replace trigger, check over and test fire at no charge	
9514	700	n/a	270 WIN	24-Sep-82	N	S	21-Nov-13	21-Nov-13	Fired on Safe Release	Improper Maintenance	328256	F	Per Ilion - Quote to repair @ a discount	
9515	700	25855	7MM08 REM	7-Mar-03	N	S	21-Nov-13	21-Nov-13	Fired on Safe Release	Improper Maintenance	328294	F	Per Ilion, replace trigger assembly and repair as needed at 50% discount	
9516	700	85339	243 WIN	16-Aug-11	N	S	21-Nov-13	21-Nov-13	Fired on Bolt Closing	Could Not Duplicate Concern	328292	F	Per Ilion, replace trigger, check over and test fire at no charge	
9531	700	n/a	270 WIN	1-Jul-73	N	S	21-Nov-13	11-Dec-13	Fired on Safe Release	Altered Adjustments or Components	330352	F	Per Ilion - Quote to repair under BLM	

RAC001172

## Confidential

9532	H&R Slug Hunter	72200	12 GA	24-Apr-13	N	S	21-Nov-13	9-Dec-13	Unexplained Discharge Safe OFF	Broken or Missing Parts	329433	F	Refund - \$250.04 - customer request
9530	770	85633	3006 SPRG	4-Feb-13	N	S	21-Nov-13	14-Apr-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
9521	700	27580	50 CAL	11-Apr-97	N	S	22-Nov-13	22-Nov-13	Fired on Safe Release	Broken or Missing Parts	328419	F	Per Ilion, replace trigger, check over at no charge
9545	700	N/A	300 SAUM	25-Sep-02	N	S	22-Nov-13	11-Aug-14	Fired on Safe Release	Could Not Duplicate Concern	453864	F	Per Ilion, replace trigger, check over and test fire at no charge
9553	700	25773	3006 SPR	21-May-86	N	PI/S	22-Nov-13	16-Jul-14	Fired on Safe Release	Could Not Duplicate Concern	446647	F	Replace trigger, check over, and test at no charge
9542	700	85478	270 WIN	18-May-10	N	S	25-Nov-13	18-Dec-13	Fired on Safe Release	Altered Adjustments or Components	331256	F	Per Ilion - Repair @ n/c - goodwill
9560	700	26129	3006 SPR	24-Feb-00	N	S	25-Nov-13	27-Dec-13	Fired on Safe Release	Improper Maintenance	332066	F	Per Ilion, replace trigger, check over, and test at 50% discount
9543	700	27476	270 WIN	5-Feb-04	N	S	25-Nov-13	27-Feb-14	Fired on Safe Release	Could Not Duplicate Concern	338920	F	Per Ilion - Quote to repair @ discount
9556	597M	26516	17 HMR	10-Jul-05	N	S	25-Nov-13	3-Jan-14	Other - Firearms	Other - Unspecified or Undetermined - Firearms	332497	F	Converting to 22 WMR as requested by customer
9544	700	25803	7MM MAG	16-Apr-91	N	S	25-Nov-13	16-Apr-15	Fired With Safe ON	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
9548	700	25793	3006 SPRG	23-Oct-02	N	S	25-Nov-13	16-Apr-15	Fired With Safe ON	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
9564	710	27410	3006 SPR	15-Jul-02	Y	S	26-Nov-13	15-Apr-15	Fired on Bolt Closing	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
9565	700	N/A	3006 SPR	1-Feb-70	N	S	27-Nov-13	18-Dec-13	Fired on Bolt Closing	Improper Maintenance	331235	F	Per Ilion, quote to repair BLM
9552	710	27416	243 WIN	20-Mar-06	N	S	27-Nov-13	14-Apr-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
9568	788	n/a	308 WIN	25-Sep-75	Y	S	2-Dec-13	2-Dec-13	Fired With Safe ON	Improper Maintenance	328695	F	Per Ilion - Quote to repair @ a discount
9569	700	n/a	3006 SPRG	17-Mar-82	N	S	2-Dec-13	2-Dec-13	Fired on Bolt Closing	Improper Maintenance	328850	F	Per Ilion - Quote to repair @ a discount
9570	700	n/a	243 WIN	1-Mar-67	N	S	2-Dec-13	2-Dec-13	Fired With Safe ON	Altered Adjustments or Components	328687	F	Per Ilion - Quote to repair under BLM
9574	700	n/a	270 WIN	17-Aug-79	N	S	2-Dec-13	2-Dec-13	Fail to Fire	Improper Maintenance	329100	F	Per Ilion - Quote to repair under BLM
9582	700	N/A	3006 SPR	1-Apr-67	N	S	2-Dec-13	27-Dec-13	Fired on Safe Release	Altered Adjustments or Components	332065	F	Per Ilion, quote to repair BLM
9603	700	27385	MA	10-Aug-09	N	S	2-Dec-13	17-Dec-13	Fired on Safe Release	Could Not Duplicate Concern	331121	F	Per Ilion - Repair @ n/c
9606	700	29705	308 WIN	1-Jan-96	N	PI/S	2-Dec-13	20-Jan-14	Fired on Safe Release	Altered Adjustments or Components	332195	F	Quote to repair at a discount goodwill gesture
9607	700	27453	7mm-08 REM	28-Mar-02	N	PD/S	2-Dec-13	14-Apr-14	Fired on Safe Release	Could Not Duplicate Concern	339870	F	Repair @ n/c - goodwill gesture
9608	700	n/a	3006 SPRG	24-Feb-77	N	PD/S	2-Dec-13	22-Jan-14	Fired on Safe Release	Improper Maintenance	333110	F	Repair @ n/c - goodwill gesture
9576	700	N/A		17-Aug-77	N	S	2-Dec-13	14-Apr-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
9579	700	27253	270 WIN	12-Jul-07	N	S	2-Dec-13	14-Apr-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Gun not examined by Product Service in Ilion
9581	700	n/a	7MM REM	1-May-73	N	S	3-Dec-13	3-Dec-13	Fired on Bolt Closing	Could Not Duplicate Concern	329039	F	Per Ilion - Quote to repair under BLM
9584	870	24407	12 GA	9-Jan-12	N	S	3-Dec-13	3-Dec-13	Unexplained Discharge - No Mention of Safety Position	Sent in for Evaluation	329283	F	Per Ilion - Repair @ n/c - warranty

RAC001173

## Confidential

9586	700	N/A	7MM REM MA	1-Oct-83	N	PI/PD/S	3-Dec-13	17-Dec-13	Fired on Safe Release	Could Not Duplicate Concern	330339	F	Replace trigger, check over, and test at no charge
9623	700	84207	308 WIN	13-Feb-12	N	S	3-Dec-13	20-Dec-13	Fired on Safe Release	Could Not Duplicate Concern	331598	F	Per Ilion - Repair @ n/c - warranty
9599	700	85569	308 WIN	12-Jun-09	N	PD/S	3-Dec-13	7-Feb-14	Fired on Safe Release	Could Not Duplicate Concern	332864	F	Repair @ n/c - goodwill gesture
9609	700	n/a	3006 SPRG	1-Sep-68	N	PD/S	3-Dec-13	14-Jan-14	Fired on Bolt Closing	Improper Maintenance	333717	F	Replace TA, clean & test fire @ n/c - goodwill gesture
9593	700ML	N/A	50 CAL		Y	S	3-Dec-13	15-Apr-15	Fired on Bolt Opening	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
9624	700	n/a	3006 SPRG	20-Aug-75	N	S	4-Dec-13	19-Dec-13	Fired on Bolt Closing	Altered Adjustments or Components	331479	F	Per Ilion - Quote to repair under BLM
9626	700	84600	223 REM	13-Jul-11	N	S	4-Dec-13	12-Feb-14	Fired on Safe Release	Could Not Duplicate Concern	337484	F	Per Ilion - Repair at n/c - goodwill
9625	700	27476	270 WIN	22-Jan-99	N	S	4-Dec-13	14-Apr-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
9598	770	85633	3006 SPRG	25-Jan-08	N	S	5-Dec-13	5-Dec-13	Fired on Bolt Closing	Altered Adjustments or Components	329543	F	Quote to repair at a discount
9604	700	25709	308 WIN	26-Dec-12	N	S	5-Dec-13	29-Jan-14	Fired on Safe Release	Could Not Duplicate Concern	335752	F	Per Ilion, replace TPA, check over and test at no charge
9619	700	N/A	270 WIN	1-Sep-83	N	S	5-Dec-13	3-Jan-14	Fired on Bolt Closing	Altered Adjustments or Components	332498	F	Per Ilion, replace trigger, check over, and test at 50% discount
9643	700	29708	270 WIN	16-Jul-92	N	S	5-Dec-13	3-Jan-14	Fired on Safe Release	Could Not Duplicate Concern	332499	F	Per Ilion - Quote to repair @ a discount
9630	700	N/A	3006 SPR		N	S	5-Dec-13	14-Apr-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
9612	700	n/a	243 WIN	1-Dec-70	N	PD/S	6-Dec-13	6-Dec-13	Fired on Safe Release	Broken or Missing Parts	329125	F	Per Ilion - Repair @ n/c
9614	660	n/a	308 WIN	1-Aug-68	Y	S	6-Dec-13	6-Dec-13	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	329692	F	Per Ilion - Repair @ n/c
9616	700	N/A	243 WIN	1-Dec-73	N	PD/S	6-Dec-13	30-Dec-13	Fired on Safe Release	Could Not Duplicate Concern	329295	F	quote to repair BLM
9617	700	26035	3006 SPRG	23-Mar-98	N	S	6-Dec-13	6-Dec-13	Fired on Safe Release	Improper Maintenance	329703	F	Per Ilion - Quote to repair @ a discount
9644	597	26560	22 WMR	22-Oct-12	N	S	6-Dec-13	16-Jan-14	Blowback in Face	Other - Unspecified or Undetermined - Firearms	332264	F	Replace w/26560 in exchange
9634	700	26909	270 WIN	12-May-03	N	S	9-Dec-13	9-Dec-13	Fired on Safe Release	Altered Adjustments or Components	330046	F	Per Ilion - Quote to repair @ a discount
9635	Versa Max	81059	12 GA	14-Aug-13	N	S	9-Dec-13	9-Dec-13	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	329888	F	Per Ilion - Repair @ n/c
9636	721	n/a	3006 SPRG	1-Feb-56	Y	PD/S	9-Dec-13	9-Dec-13	Fired on Safe Release	Could Not Duplicate Concern	330026	F	Per Ilion - Quote to repair under BLM
9637	700	27093	243 WIN	16-Aug-06	N	PD/S	9-Dec-13	9-Dec-13	Fired on Bolt Closing	Could Not Duplicate Concern	330006	F	Per Ilion - Quoted to repair, consumer refused, rifle returned to dealer
9642	700	25793	3006 SPRG	10-May-12	N	PD/S	9-Dec-13	2-Jan-14	Fired on Safe Release	Could Not Duplicate Concern	331923/364482	F	Repair @ n/c - warranty
9674	700	n/a	3006 SPRG	29-Oct-81	N	PD/S	9-Dec-13	13-Jan-14	Fired on Safe Release	Altered Adjustments or Components	332868	F	Repair @ n/c - goodwill gesture
9647	700	84456	308 WIN	28-May-09	N	PI/S	10-Dec-13	30-Dec-13	Blowback in Face	Sent in for Evaluation	330173	F	Quote to repair at a discount
9649	700ML	27580	50 CAL	29-Oct-96	Y	S	10-Dec-13	10-Dec-13	Fired on Bolt Closing	Broken or Missing Parts	330058	F	Per Ilion - Repair @ n/c

RAC001174

## Confidential

9650	700	84406	300 WIN MA	23-Sep-09	N	S	10-Dec-13	10-Dec-13	Fired on Safe Release	Could Not Duplicate Concern	330139	F	Per Ilion - Quote to repair @ a discount
9654	700	N/A	7MM REM MA	1-Oct-70	N	S	10-Dec-13	19-Dec-13	Delayed Firing - Firearms	Improper Maintenance	331374	F	Replace trigger assembly under BLP for \$20.00 + shipping and replace bolt at 50% discount
9668	700	n/a	270 WIN	16-Nov-78	N	S	10-Dec-13	8-Jan-14	Fired on Bolt Closing	Could Not Duplicate Concern	332852	F	Per Ilion - Quote to repair under BLM
9653	700	n/a	270 WIN	11-Jun-92	N	S	10-Dec-13	15-Apr-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
9656	1187	25277	12 GA	29-Aug-92	N	S	11-Dec-13	11-Dec-13	Fired on Bolt Closing	Could Not Duplicate Concern	330341	F	Per Ilion, check over, repair as needed, and test at 50% discount
9657	700	N/A	7MM REM MA	1-Feb-70	N	S	11-Dec-13	11-Dec-13	Fired on Bolt Opening	Could Not Duplicate Concern	330402	F	Per Ilion, quote to repair BLM
9659	700	27255	300 WSM 22-250 REM	20-Aug-09	N	S	11-Dec-13	11-Dec-13	Fired on Safe Release	Could Not Duplicate Concern	330323	F	Per Ilion, replace trigger, check over and test fire at no charge
9663	700	N/A		1-Jan-73	N	S	11-Dec-13	27-Dec-13	Fired on Safe Release	Improper Maintenance	332064	F	Per Ilion, quote to repair BLM
9666	700	84178	3006 SPRG	25-Mar-09	N	S	12-Dec-13	12-Dec-13	Fired on Bolt Closing	Improper Maintenance	330531	F	Returning as received
9669	SPT-78	26164	3006 SPRG	6-Jan-89	N	PI/S	12-Dec-13	14-Jan-14	Fired on Safe Release	Could Not Duplicate Concern	332496	F	Replace TPA, check over and test at no charge
9672	700	84642	243 WIN	7-Aug-12	N	S	12-Dec-13	2-Jan-14	Fired on Safe Release	Could Not Duplicate Concern	332222	F	Per Ilion, replace TPA, check over and test at no charge
9681	700	n/a	300 WIN MA	13-Apr-81	N	S	12-Dec-13	17-Jan-14	Fired on Safe Release	Altered Adjustments or Components	334245	F	Per Ilion - Quote to repair under BLM
9671	700	n/a	7MM MAG		N	PD/S	12-Dec-13	15-Apr-15	Fired on Bolt Closing	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
9676	700	N/A	270 WIN	10-Sep-82	N	S	13-Dec-13	13-Dec-13	Fired on Bolt Opening	Improper Maintenance	330532	F	Per Ilion, replace trigger, check over, and test at 50% discount
9677	700	27514	223 REM	21-Jul-99	N	S	13-Dec-13	13-Dec-13	Fired on Safe Release	Broken or Missing Parts	330694	F	Per Ilion, replace TPA, check over and test at no charge
9678	700	n/a	7MM REM MA	27-May-80	N	S	13-Dec-13	13-Dec-13	Fired on Safe Release	Improper Maintenance	330594	F	Per Ilion - Quote to repair under BLM
9679	700	n/a	243 WIN	27-Nov-79	N	S	13-Dec-13	13-Dec-13	Fired on Bolt Closing	Altered Adjustments or Components	330563	F	Per Ilion - Quote to repair under BLM
9684	700	25793	3006 SPRG	21-May-12	N	S	13-Dec-13	13-Dec-13	Fired on Safe Release	Not Examined by Product Service	n/a	F	Customer refused to send gun in for exam
9682	770	85634	308 WIN	30-Mar-11	N	PD/S	13-Dec-13	20-Jan-14	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	332334	F	Replace TA & test fire @ n/c - goodwill gesture
9695	700	n/a	308 WIN		N	S	16-Dec-13	8-Jan-14	Fired on Bolt Closing	Could Not Duplicate Concern	332874	F	Per Ilion - Repair at n/c
9696	700	25771	270 WIN	1-Mar-90	N	S	16-Dec-13	9-Jan-14	Fired on Bolt Closing	Could Not Duplicate Concern	333104	F	Per Ilion - Quote to repair @ a discount
9697	700	N/A	270 WIN	31-Mar-80	N	S	16-Dec-13	20-Jan-14	Fired on Safe Release	Could Not Duplicate Concern	334543	F	Per Ilion, quote to repair BLM
9698	700	n/a	308 WIN	1-May-78	N	S	16-Dec-13	9-Jan-14	Fired on Bolt Closing	Improper Maintenance	333009	F	Per Ilion - Quote to repair under BLM
9702	760	n/a	308 WIN	26-Apr-73	Y	S	16-Dec-13	27-Feb-14	Delayed Firing - Firearms	Could Not Duplicate Concern	339039	F	Per Ilion - Quote to repair @ discount
9689	700	n/a	3006 SPRG	1-Jun-71	N	S	17-Dec-13	17-Dec-13	Fired on Safe Release	Altered Adjustments or Components	331034	F	Per Ilion - Quote to repair under BLM
9690	700	N/A	3006 SPRG	16-Jul-75	N	S	17-Dec-13	17-Dec-13	Fired on Bolt Closing	Could Not Duplicate Concern	331046	F	Per Ilion, quote to repair BLM

RAC001175

## Confidential

9692	700	25775	308 WIN	1-Jun-85	N	S	17-Dec-13	17-Dec-13	Fired on Safe Release	Could Not Duplicate Concern	331116	F	Per Ilion, offer to replace trigger assembly, check over, and test at 50% discount
9693	700	84515	3006 SPRG	21-Apr-10	N	S	17-Dec-13	17-Dec-13	Fired on Bolt Closing	Could Not Duplicate Concern	331044	F	Per Ilion, replace trigger, check over and test fire at no charge
9713	700	27361	270 WIN	2-Jan-07	N	S	17-Dec-13	14-Apr-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
9707	CARBON 15	90689	223/5.56	11-Mar-13	N	S	18-Dec-13	18-Dec-13	Went Automatic	Sent in for Evaluation	331180	F	Per Ilion, check over completely and repair at no charge
9708	700	26309	270 WSM	23-Sep-05	N	S	18-Dec-13	18-Dec-13	Fired on Safe Release	Altered Adjustments or Components	331233	F	Per Ilion, replace trigger, check over, and test at 50% discount
9710	700	n/a	2506 REM	31-Mar-82	N	S	18-Dec-13	18-Dec-13	Fired on Safe Release	Altered Adjustments or Components	331237	F	Per Ilion - Quote to repair Gun not returned to Ilion for exam
9724	700	N/A	270 WIN	15-Sep-77	N	S	18-Dec-13	16-Apr-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Per Ilion - Repair @ n/c - goodwill
9717	770	85632	270 WIN	2-Apr-09	N	S	19-Dec-13	19-Dec-13	Fired With Safe ON	Could Not Duplicate Concern	331390	O	Per Ilion, replace trigger, check over, and test at 50% discount
9719	700	84218	308 WIN	28-May-13	N	S	19-Dec-13	19-Dec-13	Fired on Bolt Closing	Altered Adjustments or Components	331345	F	Per Ilion, replace trigger, check over, and test at 50% discount
9720	770	85632	270 WIN	4-Oct-11	N	S	19-Dec-13	19-Dec-13	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	331361	F	Per Ilion, replace TPA, check over and test at no charge
9721	Seven	29551	7MM SAUM	31-Jan-03	N	S	19-Dec-13	19-Dec-13	Unexplained Discharge Safe OFF	Could Not Duplicate Concern	331377	O	Per Ilion - Quote to repair
9722	700	N/A	270 WIN	22-Apr-80	N	S	19-Dec-13	19-Dec-13	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	331414	F	Per Ilion, quote to repair BLM
9726	SEVEN	24784	6MM REM	1-Jul-83	N	PD/S	19-Dec-13	3-Feb-14	Delayed Firing - Firearms	Altered Adjustments or Components	334254	F	Check over completely, repair as needed, and test fire at a 50% discount
9727	700	N/A	3006 SPR	11-Nov-76	N	S	19-Dec-13	16-Jan-14	Fired on Safe Release	Improper Maintenance	334111	O	Per Ilion, quote to repair BLM
9729	700	N/A	270 WIN	29-Aug-77	N	S	20-Dec-13	20-Dec-13	Fired on Bolt Closing	Improper Maintenance	331539	F	Per Ilion, quote to repair BLM
9730	700	84515	3006 SPRG	15-Feb-10	N	S	20-Dec-13	20-Dec-13	Fired on Safe Release	Could Not Duplicate Concern	331586	F	Per Ilion, replace TPA, check over and test at no charge
9732	700	N/A	3006 SPRG	1-Oct-69	N	S	23-Dec-13	23-Dec-13	Fired on Safe Release	Improper Maintenance	331732	F	Per Ilion, quote to repair BLM
9733	597	26516	17 HMR	24-Nov-04	N	PD/S	23-Dec-13	23-Dec-13	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	331717	F	Converting to 22 WMR as requested by customer, repair and check over completely at no charge.
9737	700	27095	3006 SPRG	7-Dec-11	N	S	26-Dec-13	6-Feb-14	Fired on Safe Release	Could Not Duplicate Concern	335058	F	Repair @ n/c - to restore confidence in rifle
9738	700	n/a	3006 SPRG	1-Sep-76	N	S	26-Dec-13	17-Jan-14	Fired on Safe Release	Could Not Duplicate Concern	334252	F	Per Ilion - Quote to repair under BLM
9739	700	85430	25-06 REM	17-Aug-11	N	PD/S	26-Dec-13	24-Jan-14	Fired on Bolt Closing	Altered Adjustments or Components	333194	F	Repair @ n/c - goodwill gesture
9742	700	n/a	25-06 REM	1-Feb-73	N	S	26-Dec-13	9-Jan-14	Fired on Bolt Closing	Altered Adjustments or Components	333107	F	Per Ilion - Quote to repair under BLM
9743	7	24739	243 WIN	29-Apr-02	N	S	27-Dec-13	20-Jan-14	Fired on Bolt Closing	Could Not Duplicate Concern	334542	F	Per Ilion - Quote to repair @ a discount

RAC001176

## Confidential

9744	700	n/a	243 WIN	20-Feb-80	N	S	30-Dec-13	30-Dec-13	Fired With Safe ON	Could Not Duplicate Concern	332053	F	Repaired @ n/c - Consumer Serv. supervisor
9745	700	N/A	3006 SPRG	14-Feb-79	N	S	30-Dec-13	30-Dec-13	Fired on Safe Release	Could Not Duplicate Concern	332153	F	Per Ilion, quote to repair BLM
9746	700	27099	300 WIN MA	17-Feb-06	N	S	30-Dec-13	30-Dec-13	Fired on Bolt Closing	Altered Adjustments or Components	332169	F	Per Ilion, replace trigger, check over, and test at 50% discount
9748	597	80875	22 LR	20-Sep-13	N	PI/S	30-Dec-13	16-Jan-14	Broken Part	Sent in for Evaluation	332990	F	Repair @ n/c - warranty
9749	700	N/A	270 WIN	1-Nov-72	N	S	30-Dec-13	17-Jan-14	Fired on Safe Release	Could Not Duplicate Concern	334250	F	Per Ilion, quote to repair BLM
9752	700	26933	7MM REM MA	6-Nov-95	N	S	30-Dec-13	27-Jan-14	Fired on Safe Release	Altered Adjustments or Components	335391	F	Per Ilion, replace trigger assembly and repair as needed at 50% discount
9753	770	85633	3006 SPR	6-Jun-13	N	PI/S	30-Dec-13	15-Apr-15	Delayed Firing - Firearms	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
9757	700	27478	3006 SPRG	4-Jan-02	N	S	31-Dec-13	7-Feb-14	Fired on Safe Release	Could Not Duplicate Concern	336874	F	Per Ilion - Quote to repair
9758	700	N/A	3006 SPR	24-Jul-75	N	S	31-Dec-13	14-Feb-14	Fired on Safe Release	Improper Maintenance	337823	F	Per Ilion, quote to repair BLM
9759	700	N/A	3006 SPR	18-Feb-77	N	S	31-Dec-13	19-Mar-14	Fired on Bolt Closing	Could Not Duplicate Concern	340874	F	Per Ilion, quote to repair BLM
9761	700	N/A	222 REM	1-Jan-73	N	S	2-Jan-14	24-Jan-14	Fired on Safe Release	Altered Adjustments or Components	335203	F	Per Ilion, quote to repair BLM
9652	700	N/A	308 WIN	20-Jul-06	N	S	3-Jan-14	3-Jan-14	Fired on Safe Release	Could Not Duplicate Concern	332426	F	Per Ilion, replace trigger, check over, and test at 50% discount
9765	660	N/A	222 REM	1-Sep-68	Y	S	3-Jan-14	3-Jan-14	Fired on Safe Release	Could Not Duplicate Concern	332388	F	Per Ilion, replace TPA, check over and test at no charge
9766	700	25773	3006 SPRG	12-Jan-94	N	S	3-Jan-14	3-Jan-14	Fired on Safe Release	Improper Maintenance	332428	F	Per Ilion, replace trigger assembly and repair as needed at 50% discount
9768	700	N/A	280 REM		N	S	3-Jan-14	3-Jan-14	Fired on Bolt Closing	Altered Adjustments or Components	332489	F	Per Ilion, offer to replace trigger assembly, check over, and test at 50% discount
9771	597	26516	17 HMR	21-Jun-04	N	PD/S	3-Jan-14	23-Jan-14	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	334981	F	Converting to 22 WMR as requested by customer, repair and check over completely at no charge.
9772	597	N/A	17 HMR	12-Feb-03	N	PI/PI/S	3-Jan-14	23-Jan-14	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	334122	O	Replacing with Ramac 70743 in exchange
9774	Seven	not avail.	308 WIN		N	S	3-Jan-14	6-Feb-14	Fired on Safe Release	Sent in for Evaluation	336719	F	Per Ilion - Quote to repair @ discount
9775	700	n/a	3006 SPRG	12-Jul-75	N	S	3-Jan-14	6-Feb-14	Fired on Safe Release	Altered Adjustments or Components	336716	F	Per Ilion - Quote to repair under BLM
9776	721	n/a	270 WIN		Y	PD/S	3-Jan-14	15-May-14	Fired on Bolt Closing	Could Not Duplicate Concern	342133	F	Repair @ n/c - goodwill gesture
9777	597	26516	17 HMR	23-Sep-03	N	PD/S	3-Jan-14	28-Jan-14	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	335536	F	Converting to 22 WMR as requested by customer, repair and check over completely at no charge.
9782	600	n/a	243 WIN	1-Mar-66	Y	S	3-Jan-14	30-Jan-14	Fired on Bolt Closing	Altered Adjustments or Components	335992	F	Per Ilion - Repair at n/c
9510	700	25771	270 WIN	21-Oct-96	N	S	6-Jan-14	6-Jan-14	Unexplained Discharge Safe OFF	Improper Maintenance	332598	F	Per Ilion, replace trigger, check over, and test at 50% discount
9783	700	N/A	7MM REM MA	5-Jan-96	N	PI/S	6-Jan-14	13-Feb-14	Fired on Safe Release	Altered Adjustments or Components	335416	F	Returned as Received - customer request

RAC001177

## Confidential

9786	870	81282	12 GA	10-Jun-09	N	S	6-Jan-14	30-Jan-14	Unexplained Discharge Safe OFF	Could Not Duplicate Concern	335854	F	Per llion - Quote to repair @ discount - goodwill
9789	700	n/a	223 REM	26-Mar-69	N	S	6-Jan-14	28-Oct-14	Fired on Safe Release	Altered Adjustments or Components	472983	F	llion repaired at n/c under BLP
9793	700	84643	270 WIN	6-Aug-12	N	S	6-Jan-14	27-Jan-14	Fired on Safe Release	Could Not Duplicate Concern	335334	F	Per llion, replace trigger, check over and test fire at no charge
9795	597	26516	17 HMR	2-Sep-05	N	PD/S	7-Jan-14	19-Feb-14	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	335603	F	Replacing with Ramac 70743 in exchange
9797	700	25858	6MM REM	1-Nov-83	N	S	7-Jan-14	20-Jan-14	Delayed Firing - Firearms	Could Not Duplicate Concern	334534	F	Per llion, replace trigger, check over, and test at 50% discount
9798	700	N/A	7MM REM MA	1-May-72	N	S	7-Jan-14	24-Jan-14	Fired on Safe Release	Altered Adjustments or Components	335161	F	Per llion, quote to repair BLM
9800	700	25771	270 WIN	1-Oct-84	N	PD/S	9-Jan-14	9-Jan-14	Fired on Safe Release	Improper Maintenance	333001	F	Check over completely, repair as needed, and test fire at a 50% discount
9801	700	84545	257 WBY MA	8-Aug-13	N	S	9-Jan-14	9-Jan-14	Fired on Bolt Closing	Could Not Duplicate Concern	332977	F	Per llion, replace trigger, check over and test fire at no charge
9802	770	85660	243 WIN	19-May-10	N	S	9-Jan-14	9-Jan-14	Delayed Firing - Firearms	Could Not Duplicate Concern	333135	F	Per llion, replace TPA, check over and test at no charge
9803	700	25898	264 WIN MA	13-May-86	N	S	9-Jan-14	24-Jan-14	Delayed Firing - Firearms	Could Not Duplicate Concern	335162	F	Per llion, replace trigger, check over and test fire at no charge
9805	700	29743	22-250 REM	3-Jan-03	N	S	10-Jan-14	6-Feb-14	Fired on Safe Release	Altered Adjustments or Components	336678	F	Per llion - Quote to repair @ discount
9806	722	N/A			Y	S	10-Jan-14	1-Apr-15	Fired on Bolt Closing	Not Examined by Product Service	n/a	F	Gun not returned to llion for exam
9808	887	82500	12 GA	26-Mar-10	N	S	13-Jan-14	13-Jan-14	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	333272	F	Check over completely, repair as needed, and test fire at no charge
9811	700	84200	17 FB	20-Sep-07	N	S	13-Jan-14	13-Jan-14	Fired on Safe Release	Altered Adjustments or Components	333418	F	Per llion, check over, repair as needed, and test at 50% discount
9817	700	n/a	3006 SPRG	25-Mar-69	N	PD/S	13-Jan-14	17-Mar-14	Fired on Bolt Closing	Improper Maintenance	338472	F	Repair @ n/c - goodwill gesture
9832	700	84273	270 WIN	21-Jun-13	N	S	13-Jan-14	22-Jan-14	Other - Firearms	Not Examined by Product Service	n/a	F	Customer does not want to send rifle in for exam
9826	700	n/a	270 WIN	4-Dec-78	N	S	14-Jan-14	6-Feb-14	Fired on Safe Release	Altered Adjustments or Components	336756	F	Per llion - Quote to repair under BLM
9823	700	not avail.	7MM REM MA		N	S	14-Jan-14	1-Apr-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Gun not returned to llion for exam
9822	XM15E25	90391	223/5.56	22-Feb-13	N	S	15-Jan-14	15-Jan-14	Went Automatic	Could Not Duplicate Concern	333917	F	Per llion, check over, repair as needed, and test at no charge
9843	700	25773	3006 SPRG	1-May-84	N	S	15-Jan-14	31-Jan-14	Fired on Safe Release	Improper Maintenance	336157	F	Per llion - Quote to repair
9829	BACR	90838	223/5.56	27-Sep-13	N	S	16-Jan-14	16-Jan-14	Went Automatic	Could Not Duplicate Concern	334105	F	Per llion, check over, repair as needed, and test at no charge
9833	600	N/A	6MM REM	1-Jun-66	Y	S	16-Jan-14	30-Jan-14	Fired on Bolt Closing	Could Not Duplicate Concern	335940	F	Per llion, replace trigger, check over and test fire at no charge
9840	700	N/A	270 WIN	30-Jun-10	N	S	17-Jan-14	25-Feb-14	Fired on Safe Release	Altered Adjustments or Components	338722	F	Per llion, replace trigger, check over, and test at 50% discount

RAC001178

## Confidential

9841	700	N/A	300 WIN MA	1-Aug-74	N	PD/S	17-Jan-14	11-Mar-14	Fired on Safe Release	Improper Maintenance	337209	F	Per release, replace trigger at no charge and \$2027.78 comp for truck damage.
9848	700	25791	270 WIN	27-Nov-90	N	S	20-Jan-14	20-Jan-14	Fired on Safe Release	Improper Maintenance	334454	F	Per llion, offer to replace trigger assembly, check over, and test at 50% discount
9849	Handi-Rifle	HSCY425	44 REM MAG	17-Jul-06	N	S	20-Jan-14	20-Jan-14	Delayed Firing - Firearms	MIN LOCK UP ON BBL CATCH	334449	F	Check over completely, repair as needed, and test fire Per llion, replace trigger, check over and test fire at no charge
9851	710	27410	3006 SPRG	27-Sep-05	Y	S	20-Jan-14	6-Feb-14	Fired on Bolt Closing	Broken or Missing Parts	336700	F	Converting to 22 WMR as requested by customer, repair and check over completely at no charge.
9853	597	26536	17 HMR	29-May-03	N	PI/PD/S	20-Jan-14	4-Mar-14	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	339455	F	Per llion, replace trigger, check over, and test at 50% discount
9854	700	25791	270 WIN	1-Dec-84	N	S	21-Jan-14	21-Jan-14	Fired on Bolt Closing	Altered Adjustments or Components	334694	F	Per llion, replace trigger, check over and test fire at no charge
9858	700	85446	243 WIN	28-Sep-12	N	S	22-Jan-14	22-Jan-14	Fired on Safe Release	Could Not Duplicate Concern	334912	F	Per llion, replace trigger, check over and test fire at no charge
9862	700	84203	308 WIN	23-Apr-12	N	S	23-Jan-14	23-Jan-14	Fired on Safe Release	Could Not Duplicate Concern	334960	F	Per llion, replace trigger, check over and test fire at no charge
9863	700	25803	7MM REM MA	1-Mar-04	N	S	23-Jan-14	23-Jan-14	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	334045	F	Per llion, replace trigger, check over, and test at 50% discount
9864	700	N/A	3006 SPRG	3-Feb-81	N	S	23-Jan-14	23-Jan-14	Fired on Bolt Closing	Could Not Duplicate Concern	334996	F	Per llion, quote to repair BLM
9870	710	27416	243 WIN	19-Mar-06	Y	S	23-Jan-14	11-Mar-14	Fired on Safe Release	Other - Unspecified or Undetermined - Firearms	340072	F	Per llion, replace trigger, check over and test fire at no charge
9871	700	27095	3006 SPRG	16-Jul-12	N	PI/S	23-Jan-14	17-Feb-14	Fired on Safe Release	Could Not Duplicate Concern	337551	F	Repair @ n/c
9866	600	N/A	243 WIN	26-Feb-77	N	S	24-Jan-14	24-Jan-14	Fired on Bolt Closing	Altered Adjustments or Components	335188	F	Per llion, quote to repair BLM
9867	700	N/A	270 WIN	26-Nov-78	N	S	24-Jan-14	24-Jan-14	Fired With Safe ON	Improper Maintenance	335197	F	Per llion, quote to repair BLM
9872	700ML	27572	50 CAL	20-Jan-97	Y	S	24-Jan-14	6-Feb-14	Fired on Safe Release	Sent in for Evaluation	336763	F	Per llion - Repair at n/c
9875	700	27267	270 WIN	22-Sep-09	N	S	27-Jan-14	27-Jan-14	Fired on Safe Release	Could Not Duplicate Concern	335398	F	Per llion, replace trigger, check over and test fire at no charge
9879	700	27478	3006 SPRG	25-Mar-02	N	S	27-Jan-14	13-Feb-14	Fired on Safe Release	Altered Adjustments or Components	337565	F	Per llion, replace trigger, check over, and test at 50% discount
9877	700	27011	270 WIN	24-Mar-04	N	S	27-Jan-14	6-Apr-15	Unexplained Discharge - No Mention of Safety Position	Not Examined by Product Service	n/a	F	Gun not returned to llion for exam
9880	700	N/A	22 250 REM	20-Feb-70	N	S	28-Jan-14	28-Jan-14	Fired With Safe ON	Altered Adjustments or Components	335508	F	Per llion, quote to repair BLM
9886	700	n/a	7MM REM MA	1-Jun-68	N	S	29-Jan-14	29-Jan-14	Fired With Safe ON	Improper Maintenance	335681	F	Per CSR - Cust. refused quote R as R
9889	700	27478	3006 SPRG	15-Oct-96	N	S	30-Jan-14	30-Jan-14	Fired on Bolt Closing	Improper Maintenance	335831	F	Per llion, replace trigger, check over, and test at 50% discount

RAC001179

## Confidential

9893	700	27502	7MM STW	10-Feb-98	N	S	30-Jan-14	17-Feb-14	Fired With Safe ON	Altered Adjustments or Components	337866	F	Per Ilion, replace trigger, check over, and test at 50% discount	
9894	700	n/a	270 WIN		N	S	30-Jan-14	6-Apr-15	Fired on Bolt Closing	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam	
9897	710	27410	3006 SPRG	26-Oct-01	Y	PD/S	31-Jan-14	27-Mar-14	Fired on Bolt Closing	Could Not Duplicate Concern	339779	F	Check over & test @ n/c	
9899	700	not avail.	MA	300 WIN			N	S	31-Jan-14	6-Apr-15	Fired With Safe ON	Not Examined by Product Service	n/a	Gun not returned to Ilion for exam
9903	700	N/A	3006 SPRG	24-Aug-76	N	S	3-Feb-14	3-Feb-14	Fired on Safe Release	Could Not Duplicate Concern	336205	F	Per Ilion, quote to repair BLM	
9904	700	84207	308 WIN	8-Aug-13	N	S	3-Feb-14	3-Feb-14	Fired on Bolt Closing	Could Not Duplicate Concern			Per Ilion, replace trigger, check over and test fire at no charge	
9905	700	N/A	3006 SPRG	19-Oct-81	N	S	3-Feb-14	3-Feb-14		Unexplained Discharge - No Mention of Safety Position				
9906	1187	25343	12 GA	11-Feb-05	N	S	3-Feb-14	3-Feb-14	Fired on Bolt Closing	Improper Maintenance	336288	F	Per Ilion, quote to repair BLM	
9907	700	n/a	270 WIN	4-May-82	N	S	3-Feb-14	17-Apr-14	Fired on Safe Release	Could Not Duplicate Concern	336057	F	Per Ilion - Repair at n/c-goodwill	
9909	700	not avail.	3006 SPRG	17-Jun-74	N	S	3-Feb-14	17-Feb-14	Fired on Bolt Closing	Altered Adjustments or Components	341255	F	Per Ilion - Repair at n/c	
9913	770	85656	30-06	22-Aug-08	N	S	4-Feb-14	4-Feb-14	Fired on Bolt Closing	Could Not Duplicate Concern	336476	F	Per Ilion - Quote to repair under BLM	
9919	700	not avail.	280 REM	11-Jan-88	N	S	4-Feb-14	20-Feb-14	Fired on Safe Release	Could Not Duplicate Concern	338340	F	Per Ilion - Quote to repair @ discount	
9921	597	26514	17 HMR	17-May-07	N	PD/S	4-Feb-14	3-Mar-14	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	339366	F	Converting to 22 WMR as requested by customer, repair and check over completely at no charge.	
9915	1911	96329	45 ACP	3-Dec-12	N	S	5-Feb-14	5-Feb-14	Light Trigger Pull	Could Not Duplicate Concern	336377	F	Check over completely, repair as needed, and test fire at no charge	
9916	1911	96324	45 ACP	30-Jul-13	N	S	5-Feb-14	5-Feb-14	Fired With Safe ON	Sent in for Evaluation	336390	F	Per Ilion, check over, repair as needed, and test at no charge	
9926	7	29551	7MM SAUM	11-Sep-02	N	S	6-Feb-14	6-Feb-14	Fired on Safe Release	Could Not Duplicate Concern	336674	F	Per Ilion, replace trigger, check over, and test at 50% discount	
9927	700	84545	257 WBY MA	8-Aug-13	N	S	6-Feb-14	12-Feb-14	Fired on Bolt Closing	Could Not Duplicate Concern	337361	F	Per Ilion - Repair at n/c-warranty	
9928	597	26536	17 HMR	5-Nov-02	N	S	6-Feb-14	14-Mar-14	Fired Out of Battery	Other - Unspecified or Undetermined - Firearms	336773	F	Replacing with Ramac 70741 in exchange	
9932	597	26516	17 HMR	31-Jan-05	N	PD/S	6-Feb-14	28-Feb-14	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	339125	F	Converting to 22 WMR as requested by customer, repair and check over completely at no charge.	
9934	887	82502	12 GA	20-May-10	N	S	7-Feb-14	7-Feb-14	Fired Out of Battery	Could Not Duplicate Concern	336823	F	Per Ilion, check over, repair as needed, and test at no charge	
9935	700	N/A	3006 SPRG	1-Sep-66	N	S	7-Feb-14	7-Feb-14	Light Trigger Pull	Altered Adjustments or Components	336819	F	Per Ilion, quote to repair BLM	
9937	700	not avail.	3006 SPRG	6-Jul-79	N	S	7-Feb-14	7-Feb-14	Fired on Safe Release	Could Not Duplicate Concern	336922	F	Per Ilion - Quote to repair under BLM	
9940	700	27107	3006 SPRG	29-Aug-06	N	S	10-Feb-14	10-Feb-14	Fired on Safe Release	Altered Adjustments or Components	337129	F	Per Ilion, replace trigger, check over, and test at 50% discount	

RAC001180

## Confidential

9941	Handi Rifle	HSB206L	308 WIN	19-Mar-01	N	PI/S	10-Feb-14	15-Apr-15	Personal Injury while using firearm	Not Examined by Product Service	339199	F	Gun not examined by Product Service in Ilion
9947	700	26909	270 WIN	16-Oct-03	N	S	10-Feb-14	6-Apr-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
9948	700	N/A	3006 SPR		N	S	10-Feb-14	6-Apr-15	Fired With Safe ON	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
9944	1187	29891	20 GA	4-Feb-05	N	S	11-Feb-14	11-Feb-14	Unexplained Discharge - No Mention of Safety Position	Sent in for Evaluation	337231	F	Per Ilion - Repair at n/c
9945	710	27418	243 WIN	21-Jun-06	N	S	11-Feb-14	11-Feb-14	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	337286	F	Per Ilion, replace trigger, check over, and test at 50% discount
9953	600	n/a	6MM REM	1-Mar-67	Y	S	11-Feb-14	25-Feb-14	Fired on Safe Release	Altered Adjustments or Components	338746	F	Per Ilion - Quote to repair under BLM
9952	700	84600	223 REM	23-Jul-11	N	PD/S	11-Feb-14	13-Apr-15	Fired on Bolt Closing	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
9955	700	N/A	3006 SPRG	1-Oct-72	N	S	13-Feb-14	13-Feb-14	Fired on Safe Release	Altered Adjustments or Components	337587	F	Per Ilion, replace trigger, check over, and test at 50% discount
9956	7	27253	7MM/08 REM	4-Jan-11	N	S	13-Feb-14	13-Feb-14	Fired With Safe ON	Could Not Duplicate Concern	337699	F	Replace trigger, check over, and test at no charge
9957	700	25771	270 WIN	26-Feb-98	N	S	13-Feb-14	13-Feb-14	Fired on Bolt Closing	Could Not Duplicate Concern	337549	F	Replace trigger, check over, and test at no charge
9958	700	27194	243 WIN	8-Jun-11	N	S	13-Feb-14	13-Feb-14	Fired With Safe ON	Could Not Duplicate Concern	337582	F	Per Ilion, check over, repair as needed, and test at no charge
9961	600	N/A	308 WIN	30-Jan-76	N	S	14-Feb-14	14-Feb-14	Fired on Bolt Closing	Could Not Duplicate Concern	337801	F	Per Ilion, quote to repair BLM
9964	597	26516	17 HMR	15-Oct-03	N	PD/S	17-Feb-14	17-Feb-14	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	334338	F	Converting to 22 WMR as requested by customer, repair and check over completely at no charge.
9974	700	25793	3006 SPRG	31-May-96	N	PD/S	17-Feb-14	4-Jun-14	Fired on Bolt Opening	Altered Adjustments or Components	406892	F	Repair @ n/c - goodwill gesture
9966	1100	N/A	12 GA		N	S	17-Feb-14	13-Apr-15	Fired With Safe ON	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
9977	700	N/A	22-250 REM	30-Mar-84	N	PD/S	18-Feb-14	10-Apr-14	Fired on Bolt Closing	Altered Adjustments or Components	340286	F	Check over completely, repair as needed, and test fire at a 50% discount
9970	660	not avail.	308 WIN	14-Apr-70	Y	S	19-Feb-14	19-Feb-14	Fired on Safe Release	Altered Adjustments or Components	337922	F	Per Ilion - Repair at n/c
9972	700	25795	308 WIN	1-Mar-84	N	S	19-Feb-14	19-Feb-14	Delayed Firing - Firearms	Improper Maintenance	338178	F	Per Ilion - Quote to repair @ discount
9978	597	26536	17 HMR	23-Mar-03	N	PD/S	19-Feb-14	28-Jul-14	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	339928	F	Replacing with Ramac 70703 in exchange and 5 boxes of 17 HMR ammo
9979	700	N/A	308 WIN	1-Mar-68	N	S	20-Feb-14	20-Feb-14	Fired on Safe Release	Improper Maintenance	338234	F	Per Ilion, quote to repair BLM
9981	887	82500	12 GA	25-Jun-12	N	S	21-Feb-14	21-Feb-14	Dissatisfied with Service - Firearms	Could Not Duplicate Concern	338353	F	Per Ilion, check over, repair as needed, and test at no charge
9982	700	85536	3006 SPRG	7-Sep-10	N	S	21-Feb-14	21-Feb-14	Fired on Bolt Closing	Could Not Duplicate Concern	338362	F	Per Ilion, replace trigger, check over and test fire at no charge

RAC001181